


**Douglas County Surveyor's Record of
Government Corners Renewed**

25 T. S. 7 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97195

Section Corner to Sections 11, 12, 14, & 13. 51
Found - Cross chisled on Rock thus  Size of Rock 8'x 6'x 6' high.
Record size of this Cor. Rock is 2'x 2'x 4'.

Three Original Bearing Trees:

- 15", now 24" Laurel Snag, good scribing visible, record S.75°W. 52.8 ft., should be S.78°W. 54.5 ft.
- 20", now 30" Laurel, checks record dist. I find bearing to be S.25°E., face rotted.
- 12", now 24" Laurel, record dist., bearing should be N.32°W., face rotted.

- New BT's:
- 7" R.Fir bears N.42°W. 14.2 ft. scribed S11 T25S R7W CS BT.
 - 11" R.Fir bears S.16°E. 20.0 ft. scribed S13 T25S R7W CS BT.
 - 20" R.Fir bears S.88½°W. 52.8 ft. scribed S14 T25S R7W CS BT.
 - 5" W.Fir bears N.24°E. 14.0 ft. scribed S12 CS BT.

James W. Byron, Deputy
M. Godfrey
S. Blouw
Nov., 1957 & May, 1958
C. S. File No. 49/76

Section Cor. for Secs. 31-32 T25S R7W, & Secs. 5-6 T26S R7W. 52
Found - Stump Hole on edge of Small Bluff, Laurel roots, that bears S.35°E. 42 ft.

Uprooted Large Fir that bears N.78°E. 7 ft., burned roots still remain.

Laurel Clump that will fit for proper distance & bearing for other two trees. Did not find any blazes to the West, though a 50' Rock Bluff fit the called distance.

Top of ridge to the North fits called distance of 2 chains, also Creek at 12.00 chains.

New BT's: I set a 4"x 4"x 48" Cedar Post for the Corner & Scribed the following Trees;

- 24" Fir bears N.2½°E. 28.6 ft. S32 T25S R7W
- 6" Madrone " N.55½°W. 5.8 ft. S31 T25S R7W
- 6" Fir bears S.49°W. 16.6 ft. S 6 T26S
- 10" Fir bears S.30½°E. 11.2 ft. S 5 T26S R7W.

Richard C. Grant
D. Powell & W. Ollar
For Martin Bros. Box Co.
2/20/58
C.S. File No. 42/372

¼ Section Corner to Sec. 32 T25S R7W, & Sec. 5, T26S R7W. 53

Set a Fir Post from which:

- 30" Fir bears S.33°E. 8.0 ft. mkd: ¼ S5 BT.
- 16" Madrone bears N.18½°W. 12.9 ft. mkd. ¼ S32 T25S R7W 2807.

104

Renew Meander Corner North Line of D.L.C. #38 54

Found - B.B.I. 19" B.Oak, now 22", shows good scars. I do not open.

Note - Corner falls on steep bank slope. I do not find 1½" Pipe set by B.B.I.

I set Brass Cap in Fence Line & 44.0 ft. West of Corner, mark brass cap W. C.

S25 ↘
 |
 S30 ↙
 44' East to MC - DLC 38
 County Surveyor's Office, 1958

T25S R7W R6W

New BT's: Rescribe 22" B. Oak N.15°E. 13.0 ft. W. C. MC S30 S25 CS BT.

2-17-69 - RESET BRASS CAP - CORNER O.K. V.R.T. C.S. 54/10

James W. Byron
Milo Godfrey
S. A. Blouw
August 22, 1958
C.S. File No. 49/76

Renew Closing Corner to 17/16 55

Found - Both Orig. BT's: Orig. 12", now 16" Laurel S.79°E. 29.0 ft., I open & find good scribing "T R BT". Ren. # 30

Orig. 18", now 30" R. Fir S.46°W. 19.1 ft., shows good scar, I do not open.

Set Brass Cap at Corner Mkd: County Surveyor's Office, S8
1959 T25S R7W C C S17/S16 96

New BT: 56" R.Fir bears S.73°E. 46.6 ft. scribed CC S16 T25S R7W CS BT.

James W. Byron, Deputy
Milo Godfrey
S. A. Blouw
April 13, 1959
C. S. File No. 49/76

¼ Section Corner to Sections 9 & 16. 55-A

Found - Both Orig. BT's.:

Now 14" W. Fir, scribed by Kerr, 1953, N.20°E. 4.3 ft., I do not find his S.W. BT. nor Rod Set for Corner. Ren. #31

30" Stump scribed "BT", this is BT. used by Kerr to set corner.

Now 24" W. Fir Snag, previously opened, shows good scribing "BT",

This is also an Orig. BT. N.45°W. 26.4 ft. I use this BT. to set Corner which checks record dist. to Stump but I find bearing should be S.25½°W., record S.13°E. Also BT's. face

(continued next page)