

Douglas County Surveyor's Record of
Government Corners Renewed

T. 25 S. T. S. R. 7. W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Milo E. Godfrey, Deputy
Vernon Tracy & Clete Putnam
March 1962
C. S. File No. 49/76

65
 $\frac{1}{4}$ Corner to Sections 12 and 13.
 Found - Fir Tree, 39", S.27°E. (instead of S.37°E.) 52.8 ft. This tree has been opened previously & good scribing $\frac{1}{4}$ " visible on old face.
 31" Fir N. 9°E. 31.7 ft. shows very good scar, did not chop open.
 Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1962 T25S R7W $\frac{1}{4}$ S12/S13
 Rescribe - 31" D. Fir N. 9°E. 31.7 ft. Mkd: $\frac{1}{4}$ S12 CS BT, in wood.
 New BT's: 16" D. Fir S. 30°W. 19.3 ft. Mkd: $\frac{1}{4}$ S13 CS BT.
 Corner lies on W. Slope approx. 130 ft. W. of top of ridge.
 Also found 32" D. Fir N. 45°E. 48.4 ft. with scribing visible in opening previously chopped out. (unrecorded B.T.)

66
 $\frac{1}{4}$ Corner to Sections 13 and 14.
 Found - Badly rotted Fir Snag S. 80°E. 27.7 ft. Opened & found good scribing "BT" on old pitchy face.
 A faint depression in the ground bears N. 68°W. 11.9 ft. The Site of the other Orig. B.T.
 Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1962 T25S R7W $\frac{1}{4}$ S14/S13.
 New BT's: 10" D. Fir S. 60°E. 42.5 ft. Mkd: $\frac{1}{4}$ S13 CS BT.
 5" D. Fir S. 74°W. 9.0 ft. Mkd: $\frac{1}{4}$ S14 CS BT.

67
 Corner to Sections 5 and 4 only.
 This corner bears West of Closing Corner S32/S33 T24S R7W, a dist. of 52.1 feet, record distance.
 72" Fir Tree N. 37°E. 74.6 ft., shows very faint old scar. Did not open.
 56" Fir Stump S. 48°E. 89.1 ft. Cut off too low to find scars or scribing.
 Rotted Remains of Fir Stump, in place, S. 60°W. 19.1 ft.
 Rotted Remains of Laurel Stump, in place, N. 35°W. 41.6 ft.
 (These 2 stumps too far gone to find scars or scribing.)
 Set - Brass Cap at Corner Mkd: County Surveyor's Office, 1962 T25S R7W S5/S4
 New BT's: 40" W. Fir S. 12°E. 14.4 ft. Mkd: T25S R7W S4 CS BT.
 20" D. Fir S. 17°W. 14.4 ft. Mkd: T25S R7W S5 CS BT.

68
 Closing Corner for Sections 32 and 33, T24SR7W.
 Found - Double W. Fir, now 42" N. 35 $\frac{1}{2}$ °W. 16.5 ft. This tree has been previously chopped open, scribing visible on old face "24 SR CC".
 D. Fir, now 24", N. 86°E. 12.5 ft., shows good scar. Did not cut open.
 Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1962 T24S R7W S32/S33 C.C.
 Rescribe 24" D. Fir N. 86°E. 12.5 ft. Mkd: T24S R7W CC S33 CS BT.
 New BT: 7" W. Fir N. 64°W. 33.9 ft. Mkd: T24SR7W CC S32 CS BT.

Milo E. Godfrey, Deputy Co. Surveyor
Vernon Tracy
June 18, 1962
C. S. File No. 49/41

Milo E. Godfrey, Deputy
Vernon Tracy & Mike Stone
October 29, 1962
C. S. File No. 49/88

68-A
 West Line T25-7W. - East Corner to Sections 12 & 13 only, T25-8W.
 Found - 30" Fir S. 65°E. 17.8 ft., old bark scribing visible "T2 R W S18 BT".
 Scribing has characteristics of Flint's scribing. This scribing was suppose to have been destroyed by Heydon in 1896.
 53" Fir S. 85°W. 7.9 ft. No scribing found, but old axe faces on bark.
 14" W. Fir N. 5°W. 7.3 ft., shows 2 axe faces on bark & scribe Mrk. "*" No trace of Original N.E. BT.
 Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1962 T25S R8W S12/S13
 New BT's: 14" W. Fir S. 55°W. 23.2 ft. Mkd: T25S R8W S13 CS BT.
 18" W. Fir N. 17°W. 62.0 ft. Mkd: T25SR8W S12 CS BT.
 Corner lies on bench at foot of fairly steep West Slope. #134

RE-REMOVED, SEE CORNER NO. #134