

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 25 S. T. S. R. 7 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

(continued)

Blaze & Rescribe: 24" D. Fir N. 55° E. 4.2 ft. Mkd: T25S R6W S6 CS BT.  
36" D. Fir S. 5° E. 19.0 ft. Mkd: T25S R6W S7 CS BT.  
24" D. Fir N. 38° W. 4.5 ft. Mkd: T25S R7W S1 CS BT.

New BT: 16" D. Fir S. 22° W., 21.8 ft. Mkd: T25S R7W S12 CS BT.

Note - Corner lies on gentle west slope approx. 80 ft. W. of top of ridge.

75

Closing Corner to Sec. 1, T25-7W. & Sec. 36, T24-7W.

Found - 50" D. Fir S. 59½° W. 42.9 ft., old bark scribing vis., faces corner.  
60" D. Fir N. 49° W., 37.0 ft. Bark shows evidence of having been flattened off with axe. Bark badly burned & no scribe marks found. Did not find S.E. tree called for in notes.

Rotten Fir Snag S. 10° W. 14.3 ft. with portion of old face showing fragments of scribe marks. At time it was faced off, tree would have been 12" to 15" diam., face & scribing faces approximately N. 40° W., not toward corner as set from 2 BT's.

Set - Brass Cap at Cor. Mkd: County Surveyor's T24S R7W  $\frac{S36}{S1}$  R6W CC

New BT's: 13" D. Fir N. 30° W. 111.0 ft. Mkd: T24S R7W CC S36 CS BT.

28" I. Cedar N. 31° E. 99.2 ft. Mkd: CC T24S & 25S R7W CS BT.

No trees available to S.W. except old, overripe & half-dead D. Firs. Did not mark Southwest Tree.

Corner lies approximately 10 feet west of logging road, nearly at south end of road.

76

¼ Corner to Sec. 24, T25-7W. & Sec. 19, T25-6W.

Found - 18" White Oak N. 68° E. 27.1 ft. Opened upper scar & found good scribing "S". Lower scar previously opened, scribing visible "T". Stump Hole & Rotten Pieces of Oak Log S. 32° W. 58.1 ft. Too far gone to find any markings.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963  
T25S R7W ¼ S24/S19 R6W.

New BT's: 10" W. Oak (in fence line) N. 32° W. 12.5 ft. Mkd: ¼ S24 CS BT.

16" Bl. Oak N. 41° E. 28.0 ft. Mkd: ¼ S19 CS BT.

Note - Corner falls at base of 12" White Oak Tree in fence corner, fences approximately east, west and north from corner.

The new bridge crossing the Calapooya on the Garden Valley Road is visible from this corner and bears S. 14½° E. approximately 1 mile distant.

77

¼ Corner to Sec. 13, T25-7W. & Sec. 18, T25-6W.

Found - 37" Fir N. 2° W. 99.0 ft. Faint bark scribing visible "¼". Tree alive and standing, top partly dead.

36" Fir N. 82° E. 42.2 ft., tree recently uprooted & down, bark shows evidence of having been faced off with axe. No scribing.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963  
T25S R7W ¼ S13/S18 R6W

New BT's: 22" D. Fir N. 1° E. 8.2 ft. Mkd: ¼ S18 CS BT.

15" D. Fir S. 85° W. 20.4 ft. Mkd: ¼ S13 CS BT.

Note - Corner lies on steep, rocky, S.E. slope, approximately 100 ft. south of top of spur, and between two large outcrops of rock.

78

N. W. Corner D. L. C. No. 48.

Found - Orig. 18" Bl. Oak, down & rotted, tree opened & scribing visible. (Stump hole by Oak fits bearing & distance S. 50° E. 31.7 ft.)

Squared Stake at Corner, not original.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1965

N.W. Cor. DLC 48 T25S R7W

New BT's: 14" Cedar S. 7° W. 18.3 ft. Mkd: N.W. DLC 48 CS BT.

25" D. Fir N. 7° E. 8.8 ft. Mkd: N.W. DLC 48 CS BT.

May 21, 1965

Milo E. Godfrey, Deputy County Surveyor  
Vernon Tracy and Mike Stone  
July 1963  
C. S. File No. 49/123

Bruce R. Rogers,  
Deputy  
W.S. & M.S.  
May 1965  
C.S. File  
No. 54/10