

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 25 S. T. S. R. 7 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

79

1/4 Section Corner to Section 24 and 25.

Found - 1" Iron Rod (buried) set by Ben Irving in 1932. -Ren. #18  
40" Bl. Oak N. 82 1/2° W. 77.2 ft. Has been previously opened  
and face entirely rotted away.

18" W. Oak S. 3 3/4° W. 92.4 ft., shows faint scars. Did not open.

Set - Alongside I. Rod at Cor. Set Brass Cap Mkd: T25S R7W 1/4  
County Surveyor's Office, 1963

Blze & Rescribe: 18" W. Oak S. 3 3/4° W. 92.4 ft. Mkd: 1/4 S25 CS BT.

New BT: 13" W. Oak N. 18 1/2° W. 125.1 ft. Mkd: 1/4 S24 CS BT.

Note - Found Stump Hole & Young Black Oak at location of Orig. N.W.  
Bearing Tree, N. 51° W. 124 ft. Location for Orig. SW. BT. is  
now out in river.

RE-RENEWED, SEE CORNER NO. #142

S24  
S25  
12/83  
R. Doherty  
M. 95-70  
A. 80

Mike E. Godfrey, Deputy  
Mike Stone  
August 1963  
C. S. File No. 49/76

Aug. 5, 1963

80

N. E. Corner D. L. C. #47.

W. SW. Corner D. L. C. #44.

Found - Rock 6"x18"x30", 6" out of ground, as called for Boyer, 1913.

(See Ren. #20)

12" Bl. Oak, now rotted Log bears S. 84° W. 92.4 ft.

Set - Brass Cap alongside Rock Mkd: County Surveyor's

Office, 1966 T25S R7W NE Cor. DLC 47

DLC 48 N.F.

CS BT. W SW Cor. DLC 44

DLC 47 / DLC 44

Note - Rock which is mkd. R7W & other unreadable marks is 4 ft.  
East of a 3-way fence corner, S.-E-W.

New BT: 27" W. Oak S. 88° E. 41.6 ft. scribed W SW DLC 44 CS BT.

Michael S. Stone  
Jack Heritage  
April 13, 1966  
C.S. File No. 54/10  
Mike Stone  
Douglas County Surveyor

81

Sec. Cor. to Secs. 33 & 34, T25-7W. & Secs. 4 & 3, T26-7W.

Found - 1" x 30" Steel Shaft set by Woodford, see Ren. #45.

15", now 24" D. Fir S. 30 1/2° W. 7.7 ft. (not S. 30 1/2°)

24", now 38" Orig. B. Oak S. 75° E. 21.8 ft.

Set - Brass Cap alongside Shaft at Cor. Mkd: County Surveyor's Office, 1966

T25S	S 33	S 34
T26S R7W	S 4	S 3

New BT's: 16" D. Fir N. 56° E. 71.4 ft. scribed T25S R7W S34 CS BT.

5" B. Oak N. 18° W. 31.0 ft. scribed S 33 CS BT.

RE-RENEWED, SEE CORNER NO. #146

82

1/4 Corner to Sec. 4, T25-7W, only.

Found - 34" Fir N. 52° E. 30.5 ft., turned out, shows "CS BT"  
scribe on unhealed face. See Ren. #24.

Possible Orig. 12" Fir N. 37° E. 15.8 ft., shattered stump,  
no scribing found.

Orig. S. E. BT., now turned out stump, out of position.

Set - Brass Cap at 1/4 Cor. Mkd: County Surveyor's T24S R7W 1/4  
Office, 1966 T25S S 4

New BT's: 5" D. Fir S. 63° E. 92.2 ft. Mkd: 1/4 S 4 CS BT.

14" W. Fir N. 8° E. 64.8 ft. Mkd: 1/4 S 4 CS BT.

83

Sec. Cor. to Secs. 32-33, T25-7W. & Secs. 4-5, T26-7W.

Found - Orig. 30", now 50" Fir N. 80° E. 18.5 ft., shows old bark  
scribe "S R7W" & frag. scribe. Alive.

Orig. 30", now 43" Fir N. 50° W. 39.6 ft., shows "S",  
bark scribed & fragmentary letters. Alive.

Other BT's. down.

Set - Brass Cap at Cor. Mkd: County Surveyor's T25S R7W S 32 | S 33  
Office, 1966 T26S S 5 | S 4

New BT's: 10" Maple N. 50° W. 10.0 ft. Mkd: T25S R7W S32 CS BT.

8" D. Fir S. 63° W. 18.2 ft. Mkd: T26S R7W S5 CS BT.

19" D. Fir S. 22° E. 24.6 ft. Mkd: T26S R7W S 4 CS BT.

Note - Corner lies 4.0 ft. east of small, dry creek, course  
south curving to S. E.

June 15, 1966

Vernon "Ray"  
Tracy &  
Crew

June, 1966  
C.S. File  
No. 54/10