

Douglas County Surveyor's Record of
Government Corners Renewed

T. 25 S. T. S. R. 7 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

93

Witness Corner to Sec. Cor. Sections 5 & 6, T25-7W. and
Sections 31 & 32, T24-7W.

Set - Brass Cap mkd: T24S R7W
S 31 | S 32 896
S 6 | S 5 1970

Bearing Trees: 44" Cedar N. 47°W. 11.0 ft. scribed WC S32 T24S R7W BT.
12" Oak S. 60°W. 32.4 ft. scribed WC S 5 B.T.
12" Cedar N. 3°E. 5.3 ft. scribed W.C. X B.T.

RE-RENEWED, SEE CORNER NO. #128

94

1/4 Corner to Sec. 5, T25-7W. and Sec. 32, T24-7W.

Set Brass Cap Mkd: T24S R7W
1/4 S 32 896
S 5 1970
T25S R7W

Bearing Trees: 11" Hemlock S. 73°E. 14.3 ft. scribed 1/4 S 5 T25S R7W BT.
12" Cedar N. 31°E. 31.5 ft. scribed 1/4 S32 T24S R7W BT.

See letter concerning this corner in C.S. File No. 55/140

March 9, 1970

95

Section Corner to Sections 8 & 9 only.

Found - Sandstone 7"x10"x14" mkd: "+" on top, not recorded in field notes.

Orig. 36", now 48" Fir Snag, N. 49°E. 19.1 ft., bark scribe "T25SR7WS9".

No other Orig. BT's. found.

Set - Brass Cap at Cor. Mkd: County Surveyor's T 25 S R 7 W
Office S 8 | S 9
(Reset old stone alongside) 1970 S 16

New BT's: 8" W. Fir S. 25°W. 4.1 ft. mkd: "T25S R7W S16 CS BT".

9" Chinquapin N. 32°W. 25.9 ft. mkd: "T25S R7W S8 CS BT".

No suitable tree close in Section 9.

This corner lies on moderate easterly slope. C.C. Secs. 16 & 17 bears W. 147'

5/4/70

96

Closing Corner to Sections 17 and 16.

Found - 1959 C.S. Brass Cap, in place, See Ren. #55.

Orig. BT's. still in good condition.

C.S. BT. to S. E., now down.

New BT: 5" W. Fir S. 19° E. 5.2 ft. mkd: "CC S16 CS BT".

This corner lies on moderate northerly slope 20 ft. S. of ancient logging road, course E. & W. The Sec. Cor. of Secs. 8 & 9 bears East 147.0 ft.

5/4/70

97

1/4 Corner to Sections 16 and 17.

Found - Orig. 20", now 40" Fir Stump, S. 46°E. 42.2 ft., find probable
axe marks on bark.

Orig. 10", now 21" Fir, Alive, S. 38°W. 30.4 ft., prev. opened & shows "1/4".

Set - Brass Cap at Cor. Mkd: County Surveyor's T 25 S R 7 W
Office, 1970 1/4 S 17 | S 16

New BT's: 14" D. Fir N. 60 1/2°W. 13.0 ft. mkd: "1/4 S17 CS BT".

12" D. Fir N. 70°W. 10.6 ft. mkd: "1/4 S16 CS BT".

From corner as set by us, find small squared post with hub tack in top, bearing N. 38°E. 4.0 ft. This corner lies on steep N.E. slope approx.

75.0 ft. south of 5.0' creek, course easterly. See Ren. #33 & 39

FD OK PER LANG, 10/89, m 109-3

5/13/70

98

South 1/4 Corner to Section 8 only.

Found - Rock Bluff with faint mks: "CS B0", as called for in Ren. #15,
by J.W. Cole which bears S. 31°E. 64.6 ft, 4.0 ft. above ground.

Orig. BT. that was apparently used by Cole.:

Orig. 48" Fir S. 45°W. 33.0 ft. (face) Alive, shows "1/4 S BT", bark scribe.

We Rescribe "1/4 S CS BT", low & alongside old scribe. Rec. Bear. N. 59°W.

Orig. 48" Fir Snag bears N. 65°E. 19.4 ft. (Rec. N36E 33'), badly burned
& decayed on S.W. Side. (We believe this to be other Orig. BT.)

Set - Brass Cap at Cor. Mkd: County Surveyor's T 25 S R 7 W
Office 1/4 S 8
1970

New BT: 8" Chinquapin S. 74°E. 27.3 ft. mkd: "1/4 S8 CS BT".

This corner lies on very steep rocky, northerly slope.

Note - Brass Cap Reset 10.0 ft. N. 31°W. on this date to use Cole's record
distance of 64.6 ft. from bluff.

7/27/70

Larry D. Bishop
by B.N. Glanville
C.S. File 55/140 M 33 - 68

Vernon R. Tracy
V. Perron & Don Collins, HLM.
C. S. File No. 54/10