

Douglas County Surveyor's Record of
Government Corners Renewed

T 25

T. S. R 7

R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 91881

139

1/4 Corner for Sections 16 and 21
Found - A 1968 BLM 3 1/2" dia. brass cap on a 2 1/2" O.D. iron pipe, protruding 8" above ground.
12" now 24" dia. W. oak, illegible reverse scribe marks seen from a previously opened unhealed blaze, bears N.45°E., 12.5 ft. (agrees with record.) Orig. BT.
18" Oak now a root hole. An approx. 30" dia. rotted, uprooted and down oak, no blazes or scribing seen (did not open), found approx. 10 ft. down hill of root hole. Root hole bears S.48°E., 65.3 ft. (agrees with record) Orig. BT.
12" now 17" dia. 1 ft. high D. fir stump with an illegible scribe mark found bears N.75°W., 17.4 ft. (Rec. N.75°W., 18.2 ft.) From 1968 BLM resurvey.
12" now 12" dia. W. oak with a fully healed single blaze bears S.23 1/2°E., 27.3 ft. (Rec. S.24 3/4°E., 28.0 ft.) from 1968 BLM resurvey.
New BTs - 8" dia. pistol-butt D. fir double blazed and scribed "1/4 S21 CS BT" bears S.49 1/2°E., 12.3 ft.
12" dia. W. oak double blazed and scribed "1/4 S16 CS BT" bears N.32 1/2°W., 22.2 ft.
Corner lies on a steep south west slope. (See also Ren. #37-A)

11/17/89

Special Meander Corner in Section 9

Found - 1985 3 1/4" BLM brass cap on a 2 1/2" O.D. iron pipe protrudes 2" above ground. 140
11" now 11" dia. D. fir with a partially healed single blaze, scribing visible "S9 SMC BT" bears S.29 1/2°E., 17,8 ft. (agrees with record)
10" now 10" dia. cedar with a partially healed single blaze, scribing visible "S9 SMC BT" bears S.57°W., 9.3 ft. (Rec. S.57°W., 8.9 ft. dist. is a face measurement).
(Corner report only - no new accessories.)

12/1/89

1/4 Corner for Sections 9 and 16. 141

Found - 1959 County 2 1/2" dia. DCSO brass cap on an iron pipe, flush with ground. Ren. No. 55A
12" now 20" dia. 2 1/2 ft. high rotted D. fir stump, with scribing "BT" found on a previously opened blaze, bears S.25 1/2°W., 23.4 ft (Agrees with most recent renewals) Orig. BT.
13" now 10" dia. broken and rotted Chinquipin stump, no scribing or blazes visible, bears N.43 1/2°W., 55.8 ft. (agrees with record) Ren. No. 55A
12" now 31" dia. D. fir with a fully healed single blaze bears S.83°E., 45.5 ft. (agrees with record) Ren. No. 55A
13" now 29" dia. D. fir, previously opened on south side in Ren. #55A and scribing axed out, this BT went to an erroneous corner set by Kerr in Ren. #31. No blazes found facing 1959 DCSO corner. Tree bears N.64 1/2°W., 13.9 ft. which agrees with 1985 BLM survey record.
New BTs - 31" dia. D. fir (BT in Ren. #31) double blazed and scribed "1/4 S9 CS BT" bears N.64 1/2°W., 13.9 ft.
10" dia. d. fir double blazed and scribed "1/4 S16 CS BT" bears S.24 1/2°W., 14.5 ft.
7" dia. D. fir double blazed and scribed "1/4 S9 CS BT" bears N.74°E., 13.9 ft.

Corner lies at edge of old logging road, approx. 80 ft. south of a gravel road.

12/4/89

1/4 Corner for Sections 24 and 25 142

Found - 1963 DCSO 2 1/2" brass cap on a bent 1 1/4" O.D. iron pipe, protruding 17" above ground. BC/IP leans 0.4 ft. south of plumb. Ren. #79
1" dia. x 18" long Iron bar is found along south side of BC/IP. 5" below ground. Ren. #18
40" now 41" dia. 8 ft. high Oak snag with a previously opened rotted out blaze, an axe mark is visible, no scribing seen, bears N.82 1/2°W., 77.2 ft. (agrees w/record.) Ren. #3

C O N T. N E X T P A G E - - -

Douglas County
Surveyors Office
Randall Smith
Stephen Flause
Nov. 17, 1989
C. S. 64/3

Douglas County
Surveyors Office
Randall Smith
Stephen Flause
Dec. 1-4, 1989
C.S. 64/3

Douglas County
Surveyors Office
Larry E. Monrean
Randall Smith
April 6, 1990
C.S. 64/6