

Douglas County Surveyor's Record of
Government Corners Renewed

T. 25 S. T. S. R. 8 W. R.W.W.M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21881

V. "Ray"
Tracy &
Crew
C.S. File
No.
49/88

Vernon "Ray" Tracy
Jack Heritage
September, 1967
C. S. File No. 49/88

Witness Corner to $\frac{1}{4}$ Corner to Sections 4 and 9.

36

Found - Orig. 32", now 32" Fir Snag, S. $33\frac{1}{2}^\circ$ E. 52.8 ft., scribe visible on unhealed blaze.

Since the exact corner point falls on logs in creek, we move 3.0 ft. North & Set - Brass Cap at Cor. Mkd: County Surveyor's T 25 S R 8 W

Office, 1967 Wit Cor. $\frac{1}{4}$ $\frac{S}{S}$ $\frac{4}{9}$ 3' S. to Corner.

New BT's: 7" D. Fir S. 43° E. 9.3 ft. mkd. W. C. $\frac{1}{4}$ S 9 CS BT.
9" D. Fir N. 87° W. 36.4 ft. mkd. W. C. $\frac{1}{4}$ S 4 CS BT.

Note - This Wit. Corner lies in flat along creek bottom.
No trace other BT.

Sept. 15, 1967

$\frac{1}{4}$ Corner to Sections 10 and 11.

37

Found - Orig. 42" Burnt Fir Snag, badly decayed, S. 47° E. 101.0 ft. (slope) $\frac{1}{4}$ S11" scribe visible.

Orig. 40" burnt Fir, S. 26° W. 53.5 ft., turned out, downhill approx. 75 ft., scribe marks $\frac{1}{4}$ S10" visible on upside.

Note - We could not find any hole or roots to indicate exact spot where the Orig. S.W. BT. stood. From our present corner location, there is a small slide approx. 35' wide & 40' long. If we had set the corner another 20.2' level distance, making a total of 101.0 ft. level dist., we would be approx. 15' west of old blazed line. This would put SW. Orig. BT. above slide area, and we find no evidence of stump hole nor roots. The call on ridge top also would not fit the record distance.

Because we were unable to determine where S.W. BT. stood, we measure to top of spur to north 2 chs. or 132' on old blazed line. This fixed the corner locus as being slope distance from Orig. BT. to S.E.

Set - Brass Cap at Cor. Mkd: County Surveyor's T 25 S R 8 W
Office, 1967 $\frac{1}{4}$ S 10 | S 11

New BT's: 18" D. Fir S. 31° W. 4.6 ft. mkd. $\frac{1}{4}$ S10 CS BT.
12" D. Fir N. 44° E. 2.6 ft. mkd. $\frac{1}{4}$ S11 CS BT.

Note - This corner lies on steep, S.E. slope 132 ft. S. of spur, sloping E.

$\frac{1}{4}$ Corner to Sections 3 and 10.

38

Found - Orig. 20" burnt Fir Stub, very badly decayed. S. 71° E. 4.6 ft., blazed & very poor scribe $\frac{1}{4}$ U" visible.

Orig. burnt Fir Stub, badly decayed, N. 88° E. 101.0 ft. (Record 103.0')
No scribe found.

Set - Brass Cap at Cor. Mkd: County Surveyor's T 25 S R 8 W
Office 1967 $\frac{1}{4}$ $\frac{S}{S}$ $\frac{3}{10}$

New BT's: 16" D. Fir S. 27° E. 6.1 ft. mkd. $\frac{1}{4}$ S10 CS BT.
8" D. Fir N. 33° W. 6.7 ft. mkd. $\frac{1}{4}$ S 3 CS BT.

Note - This corner lies on very steep, north slopes, approx. 150 ft. south of Little Wolf Creek.

$\frac{1}{4}$ Corner to Sections 9 and 10.

39

Found - Orig. 36", now 45" Fir, alive, N. 45° E. 23.1 ft., shows good scar, We open & find "BT" and nothh.

Orig. 42", now 51" Fir, alive, N. 53° W. 24.4 ft., shows good scar, & "4" cut into bark above scar. Do not open.

Set - Brass Cap at Cor. Mkd: County Surveyor's T 25 S R 8 W
Office, 1967 $\frac{1}{4}$ S 9 | S 10

New BT's: 6" D. Fir S. 9° W. 7.7 ft. mkd. $\frac{1}{4}$ S 9 CS BT.
7" D. Fir N. 71° E. 23.5 ft. mkd. $\frac{1}{4}$ S10 CS BT.

Note - This corner lies on very steep, East slope, approx. 365 ft. north of creek, course N.E.

MICROFILM TO HERE - 10/67 -

40

SEE OVER