

Douglas County Surveyor's Record of
Government Corners Renewed

T. 25 S. T. S. R. 8 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Vernon "Ray" Tracy
Jack Heritage & V. Perron
July, 1968
C. S. File No. 54/72

Section Corner to Sections 9 and 16 only. 46
Found - Orig. 48" Fir, now snag, N.21°E. 50.8 ft., scribe visible on
unhealed blaze.

Orig. 48" Fir, now snag, S.89°E. 22.4 ft., scribe visible on
unhealed blaze.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office T 25 S R 8 W
1968

S 9
S 16

New BT's: 8" Cedar S.68°E. 21.7 ft. mkd. T25S R8W S16 CS BT.
9" D.Fir N.59°E. 18.2 ft. mkd. T25S R8W S9 CS BT.

This corner lies on extremely steep N.E. slope 132 ft. N. of top of ridge.
The Sec. Cor. to Secs. 8 & 17, See Ren. #45, bears S. about 208 ft.

Note - I feel these Orig. BT's. were snags when scribed.

$\frac{1}{4}$ Corner to Sections 34 and 35. 47

Found = Orig. 60", now 72" Fir, N.58°E. 66.0 ft., alive, " $\frac{1}{4}$ " bark scribe
in poor condition.

Probably N.W. BT., down & decayed, no scribe found & unable to
fix exact location where it stood,

Unrecorded BT: 24" Fir N.45°W. 35.4 ft, Snag, " $\frac{1}{4}$ " pocket knife
scribe under 32 rings overgrowth.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1968

$\frac{1}{4}$ S 34	S 35
--------------------	------

New BT's: 13" D.Fir S. 47° W. 20.3 ft. mkd. " $\frac{1}{4}$ S34 CS BT".
8" Cedar N.38°E. 35.2 ft. mkd. " $\frac{1}{4}$ S35 CS BT".

This corner lies on moderate N.W. slope.

$\frac{1}{4}$ Corner to Sections 27 and 34. 48

Found - Orig. 20", now 32" Hemlock, alive, N.70°E. 16.5 ft., previously
opened, shows scribe " $\frac{1}{4}$ ".

Orig. 10", now 13" Hemlock, badly decayed remains of stump,
S.30°E. 9.2 ft., Open & find reverse "BT".

Set - Brass Cap at Cor. Mkd: County Surveyor's Office T 25 S R 8 W
1968

$\frac{1}{4}$ S 27	S 34
--------------------	------

New BT's: 14" Hemlock, N. 10° W. 19.3 ft. mkd. " $\frac{1}{4}$ S27 CS BT".
8" Hemlock S. 34° W. 24.1 ft. mkd. " $\frac{1}{4}$ S34 CS BT".

This corner lies on moderate northerly slope, about 150 ft. E.
of small ravine, course N.

Section Corner to Sections 34 & 35, T25-8W. & Secs. 3 & 2, T26-8W. 49

Found - Orig. 15", now 36" Fir, alive, N.75°E. 8.6 ft., bark scribe in
poor condition.

Orig. 60", now 72" Fir, alive, S.20°W. 42.9 ft., no scribe or scar.

Orig. 18", now 24" Cedar, alive, N.45°W. 42.9 ft., shows good scar.

Orig. S.E. BT. gone.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office T 25 S

S 34	S 35	R 8 W
S 3	S 2	

New BT's: 10" D.Fir N. 42° W. 34.3 ft. mkd: T25S R8W S34 CS BT.

10" D.Fir N. 41° E. 6.7 ft. mkd: T25S R8W S35 CS BT.

5" D.Fir S. 25° E. 18.5 ft. mkd. S 2 CS BT.

11" Maple S. 6° W. 15.0 ft. mkd. T26S R8W S3 CS BT.

This corner lies on very steep S.W. slope about 165' E. of creek, course NW.

$\frac{1}{4}$ Corner to Sec. 35, T25-8W. & Sec. 2, T26-8W. 50

Found - Orig. 20", now 24" Fir, turned out, S.15°E. 19.1 ft., hole fits
bearing and distance.

Orig. 40", now 48" Fir, alive, N.35°W. 4.6 ft., shows old bark
scribe " $\frac{1}{4}$ S BT" in fair condition.

Set - Brass Cap at Cor. MKd: County Surveyor's Office, 1968 T25S R8W

$\frac{1}{4}$ S 35
S 2

New BT's: 6" D.Fir N. 82° E. 20.2 ft. mkd. " $\frac{1}{4}$ S35 CS BT".

7" D.Fir S. 64° E. 26.1 ft. mkd. " $\frac{1}{4}$ S 2 CS BT".

This corner lies on moderate changing to steep S.E. slope in old
growth fir timber & rhododendron brush.