

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 25 S. T. S. R. 8 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

51

1/4 Corner to Sections 29 and 20.  
Found - Orig. 24", now 28" Fir, alive, N. 75° E. 74.6 ft., shows good scar. Also "W" nail.  
Orig. 30", now 36" Fir, alive, S. 86 1/2° E. 52.1 ft., opened and scribe marks visible. Also "W" nail.  
Set - Brass Cap at Cor. Mkd: County Surveyor's Office 1968 T 25 S R 8 W S 20 S 29  
New BT's: 9" Hemlock N. 70° E. 25.0 ft. mkd. "1/4 S20 CS BT".  
9" Hemlock S. 55° E. 12.2 ft. mkd. "1/4 S29 CS BT".

52

1/4 Corner to Sections 19 and 30.  
Found - Orig. 30", now 48" Fir, alive, N. 87 1/2° E. 47.5 ft., shows good scar. Orig. 24", now 36" Fir Snag, S. 3 1/3° E. 47.5 ft., open & find scribe.  
Set - Brass Cap at Cor. Mkd: County Surveyor's Office 1968 T 25 S R 8 W S 19 S 30  
New BT's: 9" Hemlock S. 43 1/2° E. 21.3 ft. mkd. "1/4 S30 CS BT".  
11" D. Fir N. 1° W. 9.3 ft. mkd. "1/4 S19 CS BT".  
This corner lies on moderate southerly slope approx. 150 ft. North of canyon bottom, course NW.

53

Section Corner to Sections 19 - 20 - 29 - 30.  
Found - Orig. 55", now 60" Fir, alive, N. 15° E 58.7 ft. (Rec. 65.3' - 10 lks.) shows good scar, also "W" nail.  
Orig. 42", now 65" Fir, alive, S. 55° W. 62.0 ft., opened, scribe visible & "W" nail.  
Orig. 14", now 20" Yew, N. 6 1/2° W. 13.2 ft. (Rec. N16 1/2° W) "W" nail.  
Rescribe: "T25S R8W S19 CS BT".  
S. E. Bearing Tree gone.  
Set - Brass Cap at Cor. Mkd: County Surveyor's Office 1968 T 25 S R 8 W S 19 S 20 S 30 S 29  
New BT's: 14" Hemlock S. 67° W. 17.5 ft. mkd. "T25S R8W S30 CS BT".  
12" Hemlock N. 50° E. 38.3 ft. mkd: "T25S R8W S20 CS BT".  
15" Hemlock S. 85° E. 24.0 ft. mkd.: "T25S R8W S29 CSBT".  
This corner lies very steep westerly slope, approx. 100 ft. E. of dry ravine.

54

1/4 Corner to Sections 19 and 20.  
Found - Orig. 20", now 20" Fir Snag, N. 1° E. 29.0 ft., scribe visible.  
Orig. 24", now 24" Fir Snag, S. 39 1/2° W. 20.5 ft. scribe visible.  
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1968 T 25 S R 8 W S 19 S 20  
New BT's: 10" Hemlock N. 31° W. 12.4 ft. mkd: "1/4 S19 CS BT".  
8" D. Fir N. 61° E. 13.4 ft. mkd: "1/4 S20 CS BT".  
13" Hemlock S. 40° E. 18.2 ft. mkd: "1/4 S20 CS BT".  
This corner lies on very steep, south slope. 9/6/68

55

Section Corner to Secs. 32 & 33, T25-8W. and Secs. 5 & 4, T26-8W.  
Found - Orig. 8" Cedar, now 20" Snag, decayed center, S. 60° W. 15.2 ft., no scribing found.  
Orig. 8", now 24" Cedar, alive, N. 20° E. 25.1 ft., Open & find "S33" scribe & reverse.  
Only decayed remains of N. W. Orig. BT. - No trace S.E. BT.  
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1968 T25S R8W S 32 S 33 S 5 S 4  
New BT's: 20" Cedar N. 24° W. 26.6 ft. mkd: T25S R8W S32 CS BT.  
9" Hemlock N. 34° E. 12.2 ft. mkd: T25S R8W S33 CS BT.  
7" Hemlock S. 9° E. 21.8 ft. mkd: T26S R8W S 4 CS BT.  
9" Hemlock S. 40° W. 23.9 ft. mkd: T26S R8W S 5 CS BT.  
This corner lies on moderate easterly slope approx. 100 ft. west of bench, course N. & S. 8/22/68

Vernon "Ray" Tracy  
Jack Heritage & V. Perron  
August, 1968  
C. S. File No. 54/72

SEPT '68