

Douglas County Surveyor's Record of
Government Corners Renewed

T. 25 S. T. S. R. 8 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21681

65

Section Corner to Sections 31 & 32, T25-8W. and
Section 6 & 5, T26-8W.
Found - Orig. 42", now 60" Fir, alive, S.10"E. 21.8 ft., bark scribe
visible, poor condition.
Orig. 34", now 52" Fir, alive, S.10"W. 26.4 ft., bark scribe
visible, poor condition.
28", now 40" Fir, alive, N.70"E. 42.9 ft., no scribe nor scar
found, injured. (1896 BT)
72", now 82" Fir, alive, N. 8* W. 66.0 ft. bark scribe visible,
fair condition.

Set - Brass Cap at Cor. Mkd: County Surveyor's T25S R8W $\frac{S}{S} \frac{31}{6} \frac{S}{S} \frac{32}{5}$
Office, 1968 T26S

New BT's: 11" Hemlock N. 12* E. 23.8 ft. mkd: T25S R8W S32 CS BT.
10" Hemlock N.12* W. 18.8 ft. mkd: T25S R8W S31 CS BT.
7" Hemlock S. 65* W. 18.7 ft. mkd: S 6 CS BT.
13" Hemlock S. 72* E. 26.1 ft. mkd: T26S R8W S5 CS BT.

This corner lies on precipitous S.E. slope in large old fir & hemlock.

66

$\frac{1}{4}$ Corner to Sec. 33, T25-8W. and Sec. 4, T26-8W.
Found - Orig. 16", now 28" Hemlock S.15"E. 29.0 ft., Open & find "T" scribe.
No trace of other Orig. BT.

Set-Brass Cap at Cor. Mkd: County Surveyor's T25S R8W $\frac{1}{4}$ $\frac{S}{S} \frac{33}{4}$
Office, 1968 T26S

New BT's: 35" Hemlock S. 60* W. 33.1 ft. mkd: " $\frac{1}{4}$ S4 CS BT".
32" Hemlock N. 29 $\frac{1}{2}$ *E. 26.0 ft. mkd: " $\frac{1}{4}$ S33 CS BT".

9/23/68

67

East $\frac{1}{4}$ Corner Section 12, T25-9W.
Found - Orig. 48" Fir, now 51" sawed stump, S. 45* W. 6.6 ft., we chop
open & find " $\frac{1}{4}$ " scribe.

No trace of corner stone or other original B. T.

Set - Brass Cap at Cor. Mkd: County Surveyor's R T 25 S R
 $(\frac{1}{2}$ " Steel Pipe bears S.47*E.) Office 9 $\frac{1}{4}$ S 12 | 8
1968 W S 12 | W
(2.8 ft.)

New BT's: 51" Fir Stump S.45*W. 6.6 ft. mkd: " $\frac{1}{4}$ S12 CS BT.
42" Fir Stump N.57*W. 55.6 ft. mkd: " $\frac{1}{4}$ S12 CS BT.

Corner lies on steep southerly slope in large clear-cut area and 75 ft.
south of Weyerhaeuser Rd. #2000.

68

Section Corner to Sections 12 and 13 only, T25-9W.
Found - Sandstone called for with 4 notches on S. & 2 notches on N. sides.
Orig. 60", now 68" Fir, alive, N.70"E. 7.9 ft., shows good scar.
Orig. 64", now 70" Fir, alive, S.36 $\frac{1}{2}$ *E. 21.1 ft., shows good scar.
Note - The BT's above were marked before the Closing corner of Secs. 7 & 18.
Orig. 56", now 60" Fir, alive, S. 5 $\frac{1}{2}$ *W. 23.1 ft., shows good scar.
(Rescribed: "T25S R9W S13 CS BT".)
Orig. 40", now 48" Fir, alive, N.14*W. 30.4 ft., shows good scar.
(Rescribed: "T25S R9W S12 CS BT".) No smaller trees close.

Set - Brass Cap at Cor. Mkd: County Surveyor's R T 25 S R
Office 9 $\frac{S}{S} \frac{12}{13}$ | 8
1968 W S 13 | W

This corner lies on steep brushy south slope approx. 430 ft. south of
ridge, course N.E. and S.W.

69

Section Corner to Sections 21 and 28 only.
Found - Orig. 48", now 60" Fir, alive, N.85"E. 37.0 ft., shows good scar.
Orig. 15", now 30" Cedar, alive, S.0*30'E. 55.4 ft., alive, open
& find scribe "W".
Orig. 1881, 16", now 48" Cedar S.70*W. 18.5 ft. (Rec. 15.2) No scar fd.

Set - Brass Cap at Cor. Mkd: County Surveyor's T 25 S R 8 W
Office $\frac{S}{S} \frac{21}{28}$ # 118
1968

New BT's: 14" Hemlock S.61*E. 40.1 ft. mkd: T25S R8W S28 CS BT.
11" Hemlock N.14*E. 22.5 ft. mkd: "T25S R8W S21 CS BT.

This corner lies 8 ft. N. of small dry ravine, course S.W. & 100 ft.
East of Arrow Creek, course S.E. Best route to corner at this time is
hike 1 $\frac{3}{4}$ mi. up Arrow Creek from logging road 10/1/68
in Cedar Ck. Canyon. We put yellow line tag on log in
Arrow Ck. about 100' west of corner.

Vernon "Ray" Tracy
Jack Heritage & V. Perron
September & October 1968
C. S. File No. 54/72

Def. 72, 740 C.S. 22/111
for replacement Co.
Casey J. Smith