

Douglas County Surveyor's Record of  
Government Corners Renewed

T 25 S. T. S. R. 8 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

76

1/4 Corner common to Sections 21 and 28. 1/4 S  
Set - 1 1/2" x 3' Iron Pipe with Brass Cap Mkd: 21  
Referenced & Scribed: 28  
24" Hemlock N. 12° E. 31.1 ft. (Mkd: 1/4 S BT) 1970  
18" Fir S. 71° W. 20.3 ft. (Mkd: 1/4 S BT)

RE-RENEWED CORNER NO. #119

77

1/4 Corner common to Sections 27 and 28. 1/4 S  
Set - 1 1/2" x 3' Iron Pipe with Brass Cap Mkd: 28 - 27  
Referenced & Scribed: 1970  
36" Fir S. 20° E. 7.0 ft. (mkd 1/4 S BT)  
4" Fir S. 67° W. 3.8 ft. (mkd 1/4 S BT)

78

1/4 Corner common to Sections 22 and 27. 1/4 S  
Set - 1 1/2" x 3' Iron Pipe with Brass Cap mkd: 22  
Referenced & Scribed: 27  
6" Fir N. 36 1/2° E. 8.5 ft. (Mkd 1/4 S BT) FO. OK 6/94 BY QUMBY  
6" Fir S. 61° W. 6.7 ft. (Mkd 1/4 S BT) M125-17

79

Center 1/4 to Section 24  
Set - Brass Cap mkd. T25S, R8W, WM, C 1/4 S24 1973.  
New BT's - 30" D. Fir, scribed "C 1/4 S24 BT., bears N. 34° W., 11.3 ft.  
8" D. Fir, scribed "C 1/4 S24 BT. bears S. 36 1/2° E., 39.6 ft.

80

1/4 Corner, sections 23 and 24  
Found - 1965 Cadastral brass cap.  
28" White fir, bears S. 42 1/2° E., 15.2 ft.  
14" White fir, now blown down, bears N. 88 1/2° W., 16.5 ft.  
New BT.- 10" D. Fir, scribed "1/4 S23 BT", bears S. 40 1/2° W., 25.6 ft. 2/5/73

81

1/4 Corner btwn. Sections 26 and 27. (Single Prop. Meas.)  
After a thorough search of surrounding area, Set a Brass  
Cap on a two inch pipe, from which:  
18" Hemlock bears N. 70° E. 21.0 ft. (Weyco Tag, "W" nail, scribed)  
30" Cedar bears N. 85-1/2° W. 29.4 ft. (Weyco Tag, "W" nail, scbd.)  
Bearings were taken to the "W" nail and distances were  
measured to the center of the tree. Aug. 31, 1973

82

1/4 Corner for Secs. 32 and 33.  
Set - 1 1/2" x 3' Gal. I. Pipe, with brass cap marked  
" T. 25 S R 8 W., 1/4 Corn 32/33  
BT"s - A 28" Red cedar N. 77° 30' E. 29.0 ft. (H.D.) scribed 1/4  
S BT and further marked with Weyerhaeuser tag and  
gal. spike in root collar.  
An 18" Red cedar N. 76 1/2° W., 54.0 ft. (H.D.) scribed  
1/4 S BT and further marked with a Weyerhaeuser tag  
and gal. spike in the root collar.

83

Section Corner for Secs. 2, 3, 10 and 11.  
Note: This corner was referenced in 1972 at the request of the BLM  
to permit a road to be built across the corner location.  
Find - Twp BT's m kd. by the County Surveyor in 1966 remaining. Ren. #23  
There is no evidence remainig of the orig. BT's or of the monument  
and additional BT's mkd. in 1966.  
Set - A 5/8" x 30" I. Rod buried 8" below the surface of a gravelled road.  
From Which:  
A 9" D. Fir bears S. 45° W., 49.6 ft. scribed "T25S R8W S 10CS BT".  
A 9" D. Fir bears N. 52° W., 73.2 ft. scribed "T25S R8W S3 CS BT"  
This corner now lies buried in the center of a rock-surfaced logging road.  
10/1/74

Craig L. Templin  
For Weyerhaeuser Co.  
Oct. 15, 1970 C.S. File 55/177

MARCH 71

U.S. BLM  
by Bruce A. Shaner  
February 5, 1973  
M 49 - 13

Repetto, H.R.  
For: Weyer-  
haeuser Co.  
C. S. File  
No. 55/309

H. Repetto for  
Weyerhaeuser Co.  
C.S. 58/8  
Date ?

Gary L. Langlitz  
Surveyors Office  
Peter Earle  
C.S. 57/8  
10/1/74

FD ok  
B Shoner  
12-7-2000

JAN 75