

**Douglas County Surveyor's Record of
Government Corners Renewed**

T. 25 S. T. S. R. 9 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

(continued)

Found - Orig. 56", now 60" Fir, alive, S. 5 1/2° W. 23.1 ft., shows good scar. Rescribed: "T25S R9W S13 CS BT".

Orig. 40", now 48" Fir, alive, N. 14° W. 30.4 ft., shows good scar. Rescribed: "T25S R9W S12 CS BT" No smaller trees close.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office 1968

R	T 25 S	R
9	S 12	8
W	S 13	W

This corner lies on steep, brushy, south slope about 430 ft. south of ridge, course N.E. and S.W.

10/9/68

1/4 Corner Section to Section 24 Only

Found - O.B.T. as follows:

Orig. 40" now 58" Fir N. 10 3/4° W. 7.3 Ft. now stump shows BT scribe. No trace other O.B.T. or Cor. stone called for. 1/4 Cor. fall on sandstone out crop 8'x10'x6' high in area of many sandstone outcrops & Boulders. At Cor. point drill rock and

Set - Brass Cap in concrete 7"x7"x3" high. Brass cap Mkd:

County Surveyors	T25S
Office, 1969	R9W 1/4 S24/R8W

No trees available for BT's Set 5/8" I.R. S. 87° W. 16.4 ft.

& Set 5/8" I.R. N. 29° W. 7.8 ft. alongside Orig. BT. Stump.

Creek Bears East 25.0 Ft. also

Weyerhaeuser reference. 40" Hemlock S. 85° E. 44.2 Ft. "W" Nail & Tag.

This tree across creek on very steep slope. 5-21-69

N. W. Corner Section 6, T 25 - 8 W. Closing Corner.

Found - 1/2" Steel Pipe, See Ren. #4 and Weyerhaeuser BT's.

Orig. 60" Cedar, down, S. 86° W. 7.3 ft., scribe visible on decaying blaze.

Orig. 12", now 16" Cedar, Alive, S. 60° E. 51.5 ft., opened, scribe vis. Rescribed: "T25S R8W S 6 CC CS BT".

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1970

T 25 S	R9W	S 6	R8W
--------	-----	-----	-----

(Reset Steel Tube alongside) New BT: 13" Hemlock S. 15° W. 26.0 ft. mkd: "CC CS BT".

This corner lies on N.E. slope in old growth timber.

Also found 15x12x3" Sandstone mkd "CR 6", no record at this time.

8/26/70

N.E. corner Section 25

Found BLM monument with the following accessories:

55" D fir bears N64° E, 46 lks. Orig. BT (record 24 lks)

34" D fir bears S81 3/4° E, 11 lks Orig. BT

74" D fir bears S 4 1/2° W, 89 1/2 lks. Orig. BT (record 46 lks)

40" D fir bears N16 1/2° W, 14 lks

E 1/4 Corner Section 25 only

Found- BLM monument with the following accessories:

66" D Fir stump bears N54 3/4° E, 67 lks. Orig. BT

54" D fir stump bears S51 1/2° W, 66 lks. Orig. BT

6" stub bears S52° W, 50 lks.

SE Corner Section 25 only

Found- BLM monument with the following accessories:

54" D fir stump bears N35° E, 79 lks. Orig. BT

40" D fir stump bears S85° E, 25 lks. Orig. BT

54" D fir stump bears S37 1/4° W, 49 lks Orig. Bt

58" D. fir stump bears N32 3/4° W, 50 lks. Orig. BT'

72" D fir stump bears N87° E, 71 lks.

Section corner for Secs. 34 and 35; and 2 and 3 of T.26-9

Found - 1" iron pipe (See Ren. #17 of T.26-9)

36" Fir, OBT, bears N. 43° 00' W., 55.6 ft.

28" cedar, OBT, bears S. 23° 00' W., 24.2 ft.

Said corner falling on the centerline of a proposed logging spur, and with the possibility of existing accessories being obliterated by the road construction, new accessories were established as follows:

28" white fir scribed BT bears N. 19° 30' E., 68.2 ft.

20" fir scribed BT bears S. 42° 30' E., 87.3 ft.

18" cedar scribed BT bears S. 36° 00' W., 36.6 ft.

Vernon "Ray" Tracy
Jack Heritage & V. Perron
1968 & 1969
C.S. File No. 54/72

Vernon
R. Tracy
C.S. File
54/72

MARCH 71

Henry R Reppeto
For: Weyerhaeuser Co.
Feb. 6, 1976
C.S. 58/90 M 59-34

2-77

Michael S. McDowell
Weyerhaeuser Company
Sept. 25, 1981
C.S. 58/8

1-79