

Douglas County Surveyor's Record of
Government Corners Renewed

T 26 S. T. S. R 1 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21891

Arthur Boyer
Witnesses: Mr. Caldwell of the U.S. Forest Service
Joe Forrest, Pac. Plywood
For Pacific Plywood, Dillard, Ore.
Nov. 30, 1959
C. S. File No. 51/64

$\frac{1}{4}$ Section Corner between Secs. 28 and 33. 1

Found mkd. Stump of Orig. B.T. which is shown in orig. govt. notes as being 20" Fir, S.12°W. 22 lks. or 14.5 ft. from the $\frac{1}{4}$ corner. This stump is still in good shape and is now 38" in diam. Measured the corner from where the face of the blaze would be if the tree were a 20" tree and at N.12°E. 14.5 ft. from this stump, set a 1 $\frac{1}{2}$ " Iron Pipe, 40" long, leaving it about 12" out of the ground with rocks piled around it. This stump will be in good evidence for a long time for renewing the corner or finding this pipe.

Blazed and Scribed: 11" Yew Tree S.26°W. 23 ft. & marked it $\frac{1}{4}$ S33
T26S RLW. 1581 B.T.

Blazed, (on one long blaze) a 30" Fir and scribed it $\frac{1}{4}$ S28 T26S RLW 1581 B.T. It is measured on slope, N.40°E. 266.5 ft. from the corner or 255.3 ft. measured on a horiz. or level msmt. This tree is below a road & on a slope averaging abt. 23°, it is on the south edge of a cutting: close trees were not available.

The corner is hard to locate, although there is little brush there now. It is on a sidehill which faces N. and is about 40 ft. S. of a road and about 15 ft. above the road, vertically. The Yew Tree mentioned is easy to find, it is alone on the sidehill.

The corner Pipe and the Fir B.T. are not easy to find, nor the stump of the Orig. B.T.

Milo Godfrey
Clete Putnam
April 17, 1961
C.S. File
No. 52/77

West $\frac{1}{4}$ Corner Section 7. 2

Found - Mound of Rocks. No markings found on any rock, crumbly. Chinquapin, now 18", N.28°E. 48.2 ft. Tree has been chopped open., scribing "S7 BT" visible. Tree in good condtn. Madrone, down & badly rotted, S.69°E. 28.4 ft. No scribing.

Set - Iron Pipe with Brass Cap Mkd: County Surveyor's Office, 1961
T26 S. R 1 W. W $\frac{1}{4}$ S7

New BT: 6" I. Cedar S.87°E. 39.3 ft. Mkd: $\frac{1}{4}$ S7 CS BT.

Milo E. Godfrey
Vernon Tracy &
Clete Putnam
June 8, 1962
C.S. File No.
52/77

$\frac{1}{4}$ Corner to Sections 11 and 12. 3

Found - Rock set by Mensch, in place, Mkd: " $\frac{1}{4}$ " on W. face. Cedar S.84°E. 10.6 ft., down & dead, good scribing " $\frac{1}{4}$ S12 BT" visible on old face.

Fir, now 55", S.8°W. 38.9 ft., has been opened previously & good scribing "S" visible on portion of old face.

Alongside Rock at Cor. Set Brass Cap Mkd: County Surveyor's Office, 1962
T26S RLW $\frac{1}{4}$ S11/S12

New BT's: 5" D.Fir N.46°W. 17.6 ft. Mkd: $\frac{1}{4}$ S11 CS BT.

5" D.Fir N.64°E. 26.6 ft. Mkd: $\frac{1}{4}$ S12 CS BT.

Section Corner to Sections 8 - 9 - 16 - 17. 4

Found - Rock at Cor. with 4 notches on S. & E. edges as called for in Gov't. notes. - Wooden Stake in mound of rock about 1' W. of Cor.

Dead Chinq. Snag N.31°E. 21.8 ft., scribing vis. on old face.

14 $\frac{1}{2}$ " Chinq. S.85°E. 22.4 ft., shows good scars. Did not open.

A Stump Hole to N.W. & a rotten piece of Madrone Wood to S.W. approx. fit bearings & distances for N. W. & S.W. BT's.

Set - Brass Cap alongside Rock Mkd: County Surveyor's Office, 1963

Pile Rocks around corner. T 26 S. RLWS $\frac{8}{S 9}$
S17 | S16

New BT's: 14" D.Fir S.7°W. 17.1 ft. Mkd: T26S RLW S17 CS BT.

20" Sugar Pine N.62°W. 22.9 ft. Mkd: T26S RLW S8 CS BT.

18" D.Fir N.36°E. 63.7 ft. Mkd: T26S RLW S9 CS BT.

12" D.Fir S.28°E. 63.7 ft. Mkd: T26S RLW S16 CS BT.

Corner lies approx. 260 ft. North of N. Umpqua Highway and 130 ft. East of Fall Creek. *FOUND O.K. 3/3/70 VRT. C.S. 52/77*

Milo E. Godfrey, Deputy
V. Tracy and Mike Stone
March 29, 1963
C. S. File No. 52/77