

Douglas County Surveyor's Record of
Government Corners Renewed

T. 26 S. T. S. R. 1 W. R. W. W. M.

KOKE-CHARMAN CO., EUGENE, ORE. 21881

10

Vernon "Ray"
Tracy & Crew
C. E. File
No.
52/77

Closing Corner to Sections 19 and 30, T26-1W.
Found - Both Orig. BT's. in excellent condition, as follows:
Orig. 30", now 38" Fir N. 58° E. 9.2 ft., shows good scar. Do not open.
Orig. 18", now 22" Cedar S. 81° E. 15.2 ft., shows "T26S RLW S30
CC BT" on unhealed face.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1966
T26S R2W C C | S 19 RLW
S 30
Did not mark New BT's, as both Orig. in good condition.
Corner lies on very steep, N. E. slope.

June 22, 1966

11

Vernon "Ray"
Tracy & Crew
C.S. File
No.
52/30

T. 25 S. R 1 W
S 36
Closing Corner to T26-1W S 1/S 31 T25 1/2-RLW.
Found - 2" I.P. & 1928 GLO Brass Cap attached & properly marked. #100
18", now 26" Fir S. 38° E. 4.4 ft., shows very good scar.
Tree alive, we do not open.
Orig. 36", now 48" Fir, S. 31° W. 48.2 ft. Now badly rotted stump,
shows fragmentary scribe marks "T2" on shattered blaze.
New BT: 15" Pine S. 64° W. 23.6 ft. mkd. T26S RLW S1 CC CS BT.
Note - Corner lies on steep, south slope approx. 140 ft. E. of shallow
ravine, course S.E.

10/17/66

12

C.S.
File
No. 52/30

Closing Corner to Sec. 6, T26-1W. & Sec. 31, T25-1W.
Found - Orig. Corner Stone 17"x14"x7" set in Mound of Stone & Mkd: "CC"
and 6 notches on N. and S.
Orig. 24", now 33" Fir, N. 58° E. 41.6 ft., Alive, shows good
scar, do not open.
Orig. 6", now 21" Fir S. 71° E. 29.7 ft., Alive, shows good
(Rescribed: "CCT26S RLW S6 CS BT") scar, do not open.
Set - Brass Cap in Mound of Stone Mkd: County Surveyor's Office, 1967
R2W CC | S 31 T25S RLW
S 31 T26S
New BT's: 10" D. Fir N. 37° E. 17.2 ft. mkd.
Note - This corner lies approx. 100 ft. S. of creek, course SE.

May 31, 1967

13

Sec. Cor. to Sections 25 and 36 only, T26-2W.
Found - 1916 G.L.O. Brass Cap, firmly set, properly marked.
Orig. 30", now 32" Fir Stump, S. 40° W. 20.5 ft., shows scar.
Orig. 48", now 50" Cedar, down, N. 40° W. 11.9 ft., shows scribe marks
on rotted face.
New BT's: 50" Cedar S. 84° W. 23.4 ft. mkd. T26S R2W S36 CS BT. #123
36" D. Fir N. 76° W. 37.1 ft., mkd. T26S R2W S25 CS BT.
Note - This corner lies on top of spur, sloping SW. at old cutting
corner, cut off in sec. 36.

14

Vernon "Ray" Tracy
Jack Heritage & E. West
August, 1967
C. S. File No. 54/40

1/4 Corner to Section 31, T26-1W.
Found - Orig. Corner Stone, 12"x8"x6", in place, mkd. "1/4" on E. side.
Orig. 14", now 28" Fir, N. 12° E. 37.0 ft., alive, shows good scar.
Orig. 30", now 40" Fir, S. 27° E. 12.5 ft., alive, shows good scar.
Set - Brass Cap at Cor. Mkd: County Surveyors Office, 1967
T26S R2W 1/4 | S31 RLW
Reset Stone alongside in Mound of Stone.
Note - This corner lies on steep southerly slope 87.8 ft. S. of
1/4 corner of sec. 36, T26-2W. No new BT's. marked.

15

Closing Corner to Sections 30 & 31, T26-1W.
Found - No trace of corner stone or N.E. BT.
Orig. 8", now 16" Hemlock, S. 27° E. 15.2 ft., alive, open & find scribe.
Set - Brass Cap at Cor. mkd: County Surveyors Office, 1967
T26S R2W CC | S 30 RLW
S 31
New BT's: 44" D. Fir N. 40° E. 32.0 ft. mkd. T26S RLW S30 CC CS BT.
14" Hemlock S. 32° E. 34.7 ft. mkd. T26S RLW S31 CC CS BT. #124
Note - This corner lies on N. side of dry creek bottom, course W.

Township Corner - T26S & T27S., R's. 1 & 2 W.
Found