

Douglas County Surveyor's Record of
Government Corners Renewed

T. 26 S. T. S. R. 1 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

16

Township Corner - T26S & T27S, R's. 1 & 2 W.
Found - No trace Orig. Corner Stone nor other obliterated BT.
Orig. 40", now 48" Fir, down, S.74°W. 16.5 ft., open & shows scribe.
Orig. 24", now down & almost completely buried Fir, N. 3°W. 15.2 ft.
Orig. 6", now 16" Fir, down, S.60°E. 20.5 ft., open & find obliterated
blaze as called for.
Set - Brass Cap at Cor. Mkd: County Surveyors T26S R2W S 36 | RW
Office, 1967 T27S R2W S 1 | RW
New BT's: 10" Cedar N. 70° W. 36.5 ft. mkd. T26S R2W S36 CS BT.
18" D.Fir S. 88° W. 41.7 ft. mkd. T27S R2W S 1 CS BT.
Note - This corner lies on southerly slope.

Vernon "Ray" Tracy
Jack Heritage & E. West
August, 1967
C. S. File No. 54/40

17

Closing Corner of Townships. T26-2; T26-1; T27-2; T27-1
Found - Corner Stone mkd: "CC" & 6 notches on N. & S. edges.
Orig. 28", now 38" Cedar, S.62°E. 21.1 ft., alive, scribe vis. on
unhealed blaze. Rescribe: "T27S RLW S 6 CC CS BT".
Orig. 12", now 22" W.Fir, N.80°E. 25.7 ft. Alive, scribe vis. on
unhealed blaze. Rescribe: "T26S RLW S31 CC CS BT".
Set - Brass Cap at Cor. Mkd: County Surveyors T26S R2W CC S 31 | RW
Office, 1967 T27S R2W S 6 | RW
New BT: 14" W.Fir S. 35° E. 30.9 ft. mkd. T27S RLW S6 CC CS BT.
Note - This corner lies on steep north slope approx. 450' S. of E.Mile Ck.

Bruce A. Shaner
For. U.S. Forest
Service
Nov. 1967
C.S. File 55/66

18

1/4 Section Corner common to Sections 15 and 22.
Found - Conglomerate Stone, 12"x8"x6" mkd. "1/4" on the north face,
and from which stone a: Orig., 14" diam. Madrone BT.
bears N.42°W. 8.6 ft., now missing, but at which point
there is a hole in the ground with 6" diam. madrone trees
growing alongside.
Madrone BT., Orig., 14" diam., bears S.9°W. 14.5 ft., now missing.
Set - Hemlock, 4" diam., bears S.5°E. 3.4 ft., I scribed "1/4 S, S22 BT".
Hemlock, 8" diam., bears N.5°E. 77.0 ft., I scribed "1/4 S, S15 BT".
Nov. 1967

RE-RENEWED SEE CORNER NO. #70

9-68

Witness Corner to Sections 19 - 20 - 29 - 30.
Found - Orig. 30", now 36" Cedar, alive, S.11°E. 36.3 ft., scribe
visible on nearly healed blaze. (To be removed by road const.)
Corner Stone buried under clearing debris several feet.
Other bearing trees gone.
Because of road to be built over corner, we chain East 110 ft.
Set - Brass Cap at Wit. Cor. Mkd: County Surveyor's T 26 S R 1 W
Office 110 ft. S 19 | S 20
1968 W. to Cor. S 30 | S 29
New BT's: 5" Hemlock N. 63° W. 22.6 ft. mkd: " W.C. S19 CS BT.
16" Hemlock N. 72° E. 25.0 ft. mkd: " W.C. T26S RLW S20 CS BT.
20" Hemlock S. 63° E. 27.3 ft. mkd: " W.C. T26S RLW S29 CS BT.
20" Cedar S. 38° W. 21.5 ft. mkd. " W.C. T26S RLW S30 CS BT.
Witness Corner lies 20 ft. E. of R/W Line East of Roadway.
9/5/68

Vernon "Ray" Tracy
Jack Heritage & V. Perron
Sept. 5, 1968
C.S. File No. 52/77

19

1/4 Corner to Sections 18 and 19. (Witness Corner)
Found - 1927 GLO Brass Cap tied to tree. Corner now falls in logging road.
26" Hemlock, now stump, S.56°W. 32.3 ft., scribe visible.
No trace of N. E. Bearing Tree.
Reset - GLO 1927 Brass Cap, remarked W.C. 35' North to.
New BT's: 34" Hemlock S.21°E. 34.0 ft. mkd: W.C. 1/4 S19 CS BT.
39" D.Fir S.44°W. 13.8 ft. mkd: W.C. 1/4 S19 CS BT.
This corner lies on top of cut bank 40.0 ft. S. of centerline of logging road.
10/22/69

20