

Douglas County Surveyor's Record of
Government Corners Renewed

T. 26 S. T. S. R. 1 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

John M. Powell
Frank Jones & W. Penley
October, 1969 C.S. File No. 54/94

Section Corner to Sections 35 and 36 only, T26-1W. 21
Found - 16x10x5 Stone, firmly set, mkd. with 1 - 5 notches.
20" Fir, now down, N.76°E. 17.8 ft., broken face & scribe marks visible.
9" Fir, now down, N.87°W. 6.6 ft., tree opened, pitched over,
scribe visible.

Set - Brass Cap at Cor. Mkd: County Surveyor's T 26 S R 1 W
Office 1969 S 35 | S 36
T27S S 1

New BT's: 30" D.Fir N.74°E. 22.0 ft. mkd: T26S R1W S36 CS BT.
30" D.Fir N.11°E. 22.4 ft. mkd: T26S R1W S36 CS BT.

This corner lies in E. edge of clear cut unit, 49.5 ft. E. of Corner S 35
S 2 | S 1

Section Corner to Sections 1 and 2, only, T27-1W. 22

Found - Unrecorded Alum. Cap at Cor. Mkd: U.S.P.C. Prop. Cor. 35
RE4287 S 2/ S 1

Possible S.E. BT., down & out of place, laying on face.
20" Hemlock S.63°E. 52.6 ft. mkd: "S1 BT".

New BT: 18" Hemlock S.47°E. 62.0 ft. mkd: T27S R1W S1 CS BT.

This corner lies on E. side of cut unit, on top of ridge, running N.,
49.5 ft. west of Section Corner to Secs. 35 & 36 only, T26-1W. 10/27/69

1/4 Corner to Section 36 only, T26-1W. (Witness Corner) 23

Found - No trace of N.W. BT. or Stone, as they fall in the road. #66
10" W.Fir, now dead, N.6°E. 37.6 ft., scribe visible.

Set - Brass Cap for Wit. Cor. Mkd: County Surveyor's T 26 S R 1 W
W.C. 55' Eastto S 36
1969 T 27 S

New BT; 28" D.Fir N.74°W. 94.5 ft. mkd: W.C. 1/4 S36 CS BT.

Bearing Object: RR Spike in Rock cut bank N.36°E. 47.1, 4' above Road. 10/27/69

South 1/4 Corner of Section 35, T26-1W. 24

Found - No trace of Corner Tree, due to logging.
10" Hemlock, now burnt stump, N.46°E. 13.7 ft., scribe visible.
24" Fir, N.50°W. 12.3 ft., high stump, shows good scar.

Set - Brass Cap at Cor. Mkd: County Surveyor's T 26 S R1W S 35
Office, 1969 T 27 S

New BT; 55" D.Fir N.82 1/2°W. 189.3 ft. mkd: "1/4 S35 CS BT".

This corner lies 70 ft. east of 1/4 Corner Sec. 2, T27-1W, see below. 11/3/69

1/4 Corner to Section 2 only (North Bdry.) T27-1W. 25

Found - Corner Stone 20x18x15 mkd. "1/4" on west face. #99
Unrcd. Alum. Cap by Corner Stone mkd: U.S.P.C. Prop Cor. T 27 S R 1 W
RE 4287 1963
S 2 only

10" Hemlock S.56°E. 48.9 ft., remains of old stump.

New BT's: 22" Hemlock S.69°W. 72.0 ft. scribed "1/4 S 2 CSBT".

22" Hemlock S.26°W. 105.0 ft. scribed "1/4 S 2 CSBT".

This corner lies in west side of large cutting unit 125 ft. E. of timber.
1/4 corner Sec. 35 only, see above, lies east 70 ft. 11/3/69

Section Corner to Sections 33 & 34 only, T26-1W. 26

Found - Corner Stone, firmly in ground, mkd. with notches.
36", now 39" D.Fir, N.64°E. 23.1 ft., shows good scar.
16", now 22" Fir, N.51°W. 20.5 ft., shows good scar.

Set - Brass Cap at Cor. Mkd: County Surveyor's T 26 S R1W S 33 S 34
Office, 1969 T 27 S S 3

Bearing Trees O. K. & Tagged.

This corner lies 89.8 ft. East of Sec. Cor. 3 & 4, T27-1W. 11/13/69