

**Douglas County Surveyor's Record of
Government Corners Renewed**

T. 26 S. T. S. E. 1 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

46

Section Corner to Sections 4 - 5 - 8 - 9.
Found - Orig. 16", now 26" Fir Corner Tree, alive, shows good scars, Ren.#6.
Orig. 10", now 16" Fir, alive, N.31°E. 7.3 ft., prev. opened, scribe visible.

Orig. BT. to S.E., only decayed remains of stump.
28" D. Fir S.71°E. 31.0 ft., pitched blaze.
9" D. Fir S.52°W. 29.6 ft., scribe visible on pitched blaze.
24" D. Fir N.82°W. 61.0 ft., scribe visible on pitched blaze.

At a point 1.5 feet East of the center of Corner Tree;

Set - Brass Cap Mkd: County Surveyor's Office 1970

T 26 S	R 1 W
S 5	S 4
S 8	S 9

This corner lies on very steep, N.E. slope approx. 430 ft. East of top of ridge. We put line tag on Mace Mtn. Trail #1518.

3/5/70

47

Section Corner to Sections 5 - 6 - 7 - 8.
Found - Corner Stone, in place with "X" on top & 5 notches on S. & E.
Orig. 6", now 14" Fir, alive, N.33°E. 57.4 ft., open & find "5" scribe.
Orig. 18", now 40" Fir, alive, S.4½°W. 71.3 ft., shows good scar, we tag.
Orig. 40", now 60" Fir, alive, S.53°E. 83.2 ft., shows good scar, we tag.
Possible Remains of N.W. Orig. BT. down & badly decayed.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office 1970

T 26 S	R 1 W
S 6	S 5
S 7	S 8

New BT's: 18" D. Fir N.19°W. 14.2 ft. mkd: T26S R1W S6 CS BT.
12" D. Fir N.17°E. 13.7 ft. mkd: T26S R1W S5 CS BT.
14" D. Fir S.67°E. 6.6 ft. mkd: T26S R1W S8 CS BT.
6" D. Fir S.20°W. 18.7 ft. mkd: S 7 CS BT.

This corner lies on very gentle, almost flat, easterly slope, about 1400 ft. east of Burnt Creek Access Road #12644.

3/6/70

48

¼ Corner to Sections 7 and 8.
Found - Corner Stone, in place, and mkd: "+" on top & "¼" on west face.
Orig. 24", now 50" Fir, alive, N.6°W. 55.4 ft., prev. opened, scribe visible.
We find a hole & pieces of Chinquapin where S.E. Orig. BT. should be.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office 1970

T 26 S	R 1 W
¼ S 7	¼ S 8

New BT's: 12" D. Fir S.82°W. 5.9 ft. mkd: "¼ S7 CS BT".
14" D. Fir N.51°E. 10.7 ft. mkd: "¼ S8 CS BT".

This corner lies on bench at S.W. Corner of cutoff area.

3/6/70

49

¼ Corner to Sections 8 and 17.
Found - Old Corner Stone, in place, mkd: "+" on top & "¼" on S.W. Side.
Orig. 10", now 18" Fir, alive, N.50°E. 14.5 ft., shows scar.
We Rescribe: "¼ S 8 CS BT".
Orig. 10", now 15" Fir, alive, S.65°W. 19.1 ft., we open & find scrbd. revrd.
We Rescribe: "¼ S17 CS BT".

Set - Brass Cap at Cor. Mkd: County Surveyor's Office 1970

T 26 S	R 1 W
S 8	S 17

New BT: 12" Cedar S.64°W. 39.0 ft. mkd: "¼ S17 CS BT".
This corner lies in vinemaple thicket, down logs & old logging debris.
N. Umpqua Highway bears South approx. 450 ft., put tag at Hwy. on North Side, approx. 200 ft. west of 32 mile post.

3/6/70

50

Section Corner to Secs. 5 and 6 only, T27-1W.
From Iron Rod set as reference Pins, see notes in file & Ren. #38.
This corner lies in center of Road.
Reset Corner to Proper Location, See Sketch in file.
New BT's: 30" Cedar N.3°W. 34.3 ft. scribed "T26S R1W S31 CS BT".
12" Hemlock N.31°W. 49.6 ft. scribed T26S R1W S31 CS BT.

11/13/70

Vernon "Ray" Tracy
Jack Heritage & V. Perron
March, 1970 C.S. File No. 52/77

John M.
Powell
&
Crew
C.S. File
54/94