

Douglas County Surveyor's Record of  
Government Corners Renewed

T 26 T. S. R 1 R.W.W.M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21881

76

1/4 Corner for Secs. 9 and 10.

Set - 1" x 36" I.P. with a 2 1/2" Brass cap stamped T26S R1W 1/4 S9/  
S10 PE 5188 1977. From which bears:

A 22" Hemlock, S.84°W., 48.4 ft. blazed and scribed "1/4 S9 BT".  
A 19" Hemlock, S.46°15'E., 24.4 ft. blazed & scribed "1/4 S10 BT".

Maurice E. Farr  
For: Umpqua Nat'l  
Forest

Jan. 1977  
M 63 - 20  
C.S. 58/138

1/4 Corner for Secs. 9 and 16.

Set - 1" x 36" I.P. with a 2 1/2" brass cap stamped T26S R1W S9 S16 1/4  
PE 5188 1977. From which bears:

A 8" Hemlock, N.71°30'E., 19.8 ft. blazed & scribed "1/4 S9 BT".  
A 50" D. Fir, S.22°E., 18.4 ft. blazed & scribed "1/4 S16 BT".

1/77

3/77

78

W.C. for C.C. for Secs. 3 and 4 only. (NE of Sec. 4)

Found - Orig. 12" now 16" D. Fir corner tree has been previously opened  
on the south and west sides. Has a healed scar on the east  
side. Fragmentary scribing is visible on the opened face and  
on the removed pieces of wood (in reverse). There are 3 healed  
hacks on the east and west sides at chest height.

Orig. 14" now 31" D. Fir bears S.25°E., 30.2 ft. (Rec. 23.76 ft.)

Orig. distance to this BT could be 10 lks. in error. Has a  
healed scar.

Orig. 14" now 30" D. Fir bears S.71°W., 13.3 ft. (Rec. 11.88 ft.).  
Has faint sign of a healed scar.

Placed County BT signs on both trees, which are healthy and in  
good condition.

Set - I placed a Forest service location sign on the east & one on the  
west side of the corner tree, marked "corner tree".

1 ft. south of the corner tree, I set a 2 1/2" brass cap on a 1"  
iron pipe marked County Surveyors Office

1977

W.C.  
1.0 ↑ N  
C.C.  
S4 | S3

T26S R1W

No new accessories. Corner lies 350 ft. west of the Williams Creek trail.

9/13/77

79

1/4 Corner for Sec. 1 only. (North boundary)

Found - A 26" broken fir stob bears S.50°E., 25.74 ft. Has a healed  
scar. Open and find scribing & reverse "S1BT".

A 33" Cedar, orig. 20", bears S.11°W., 29.7 ft. Has a healed  
scar. Cedar is alive and well.

Placed County BT sign on both tree and stob.

No monument found. Apparently the corner stone has broken and  
and rolled down hill.

Set - 2 1/2" brass cap on a 1" iron pipe set by reference to orig.  
BT's. Set in a mound of stone 4 ft. wide at base by 4 ft. high  
on downhill side. Brass cap stamped County Surveyors Office  
T26S R1W 1/4 only 1977.

S 1

New BT - A 13" D. Fir bears S.42°E., 88.7 ft. scribed "1/4 S1 CS BT"  
on a double blaze. Place county BT sign on Fir.

Note: Found two fir trees 100 ft. + East which appeared to be bearing  
trees but when chopped out, no scribing was found. Face well  
chopped by an axe. 50 years growth over face.

9/14/77

80

1/4 Corner for Secs. 23 and 26.

Found - Stone 12"x8"x4" set solidly in the ground. marked "X" on top &  
"1/4" on the north face.

Orig. 30" now 36" D. Fir bears S.33°30'E., 9.9 ft. (Rec. S.30°E.,  
9.9 ft.) Has a healed scar.

Orig. 12" now 20" Red Cedar bears N.71°E., 13.86 ft. (Rec.  
N.67°E., 13.86 ft.) Has a healed scar.

Placed county BT signs on both trees, which are alive & well.

Set - Removing the stone, I set in it's place a 2 1/2" Brass cap on a  
1" Iron pipe. B.C. stamped County Surveyors Office T26S R1W  
1/4 S23 S26 1977. I buried the corner stone alongside the I.P.

No new accessories. Corner lies 100 ft. east of F.S. Rd. #2616D.

9/16/77

Dennis Gaylord, U.S. F.S.  
Doug. Co. Surveyors Office Deputy  
Witness: Travis Worthen  
Sept. 1977  
C.S. 59/40