

**Douglas County Surveyor's Record of  
Government Corners Renewed**

T 26      T. S.      R 1 W      R. W. W. M.

MOKE-CHAPMAN CO., EUGENE, ORE. 21881

**95**

CONT. FROM  
PREV. PAGE.

Dennis Gaylord  
US FS Deputy,  
Doug. Co. Surveyors Office  
Tony Flores, Wit.  
March 15, 1979  
C.S. 60/24

A 20" D. Fir bears N.29°30'E., 20.3 ft. has healed double blazes.  
A 12" D. Fir bears S.55°E., 78.4 ft. Has double healed blazes.  
A 17" D. Fir bears S.66°W., 52.5 ft. to base of tree at center  
(tree is leaning). Has double healed blazes.  
Set - A 2 1/2" Brass cap on a 1" x 36" I.P. as a witness corner. This  
W.C. monument bears North, 50.0 ft. from the true corner monumen  
and is marked County Surveyor's Office T26S R1W W.C.  
S7 S8 S18 S17 South 50.0 1979.  
New Accessories: (these BT's are referenced to the witness con. monument)  
A 20" White Fir bears N.73°30'E., 61.9 ft. scribed "T26S R1W  
S8 WC CS BT" on a double blazes.  
A 21" D. Fir bears N.35°W., 30.8 ft. scribed "T26S R1W S7 WC CS  
BT" on double blazes.  
Corner lies in left edge of F.S. Road #2604

\_ 3/15/79 \_

**96**

1/4 Corner for Secs. 19 and 20.  
Found - Original corner stone, marked "X" on top and "1/4" on the west  
face, is firmly set in the ground. Stone measures 12" x 8 x 6".  
13" Chinquapin bears N.24°E., 23.8 ft. (Rec. N.38°E., 24.42')  
Has a nearly healed and decayed blaze. Some scribing visible.  
A 37" D. Fir bears N.75°W., 8.9 ft. (Rec. S.81°W., 9.9 ft.) Has a  
single healed blaze and bark scribing "S19 BT CS TA —"  
Set - Moving the corner stone aside, I set in it's place a 1" I. Pipe  
with a 2 1/2" brass cap attached marked County Surveyors Office  
T26S R1W 1/4 S19 S20 1979. I bury corner stone alongside  
pipe.  
No new accessories marked.  
Corner is located approx. 300 ft. north of F.S. Rd. #2618.

\_ 8/14/79 \_

**97**

Section corner for Secs. 29, 28, 32 and 33.  
Found - Original corner stone set firmly in place, measures 14" x 10" x 8"  
No marks visible on stone.  
A 36" D. Fir snag bears N.37°E., 15.84 ft. and has a single healed  
laze.  
A 25" Fir stump (hi stump) bears S.59°E., 13.8 ft. (Rec. S.64°E.,  
13.2 ft.) Has a single healed blaze.  
A 36" D. Fir stump bears S.70°W., 19.8 ft. Has a single healed  
blaze. (Rec. S.68°W.)  
36" windfall is now a stump. Root hole bears N.34°W., 12.5 ft. No  
marks or scars visible.  
Set - Moving corner stone aside, I set in it's place a 2 1/2" brass cap  
on a 1" galv. I.P. Cap marked "County Surveyors Office  
T26S R1W S29 S28 S32 S33 1979". I bury corner stone along-  
side pipe.  
New Accessories:  
Set a 5/8" iron rod with a 1 1/2" alum. cap in orig. SW BT stump  
and marke cap "RM". Cap bears S.67°30'W., 18.85 ft.  
A 5/8" I.Rod with a 1 1/2" Alum. cap marked "RM" bears N.33°E.,  
13.02 ft.  
This corner i 100 ft. south of F.S. Rd. #2627 in a proposed clearcut. Any  
new BT's set will be cut.

\_ 8/14/79 \_

**98**

1/4 Corner for Sec. 30 only, T.26-1E.  
Found - Both bearing trees with good healed over scars and Forest Service  
BT tags. Both trees in excellant condition and both are now a  
approx. 32" in diameter. (BLM notes, C.S. Vol. 22 Pg. 9523)  
The area has been logged over in a selective-cut hi-lead logging show. The  
brass cap and pipe were pulled and lost during the logging.  
Found - the orig. hole wehere the corner pipe had been, and was able to  
identify by the calls from the two bearing trees.  
Set - a 5/8" x 30" iron rod, in the orig. hole, with an alum. cap mkd:  
T26S R1E 1/4 30 418.  
Did not mark any new trees.

\_ 3/28/80 \_

Dennis Gaylord, U.S. Forest Service  
Deputy, Doug. Co. Surveyors Office  
Witness: Darrel Myers  
August 14, 1979  
C.S. 60/34

Burton W. Holt  
For: Sun Studs  
March 28, 1980  
C.S. 58/176