

Douglas County Surveyor's Record of
Government Corners Renewed

T 26 T. S. 2 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

25

Corner to Sections 1 and 12 only.

Found - 36" Fir S.72°W. 29 ft., uprooted & down, no scribing.
Fir Tree, now 12", N.33°W. 20.5 ft., showing good scar. #137
Opened scar enough to see good scribing "B".

All trace of Corner Tree Gone.

Set - Iron Pipe with Brass Cap Mkd: County Surveyor's T26S S1
Office, 1961 R2W S12

New BT: 10" R.Cedar S.85°W. 8.4 ft., Mkd: T26S R2W S12 CS BT.
Orig. N. W. BT. Still in good condition.

Milo Godfrey
Clete Putnam
April 17,
1961
C.S. File
No. 52/77

RE-RENEWED, SEE CORNER NO. #137

26

Corner to Sections 13 and 24.

Found - Rock 5" x 6" x 12" had been moved out of position,
"1/4" chiseled on rock.
Cedar Tree, now 30", N.55°E. 9.9 ft., uprooted & down., has
been opened previously & good scribing "1/4" visible.
All trace of Orig. Fir to S.W. gone.

Fir Stump, 18", S.49°W. 17.2 ft. good scribing "S24" visible.

Set - Brass Cap Mkd: County Surveyor's T26S R2W S13 Set Rock
Office, 1961 S24 alongside B.C.

New BT's: 11" I. Cedar N.32 1/2°E. 38.3 ft. Mkd: 1/4 S13 CS BT.
13" D.Fir S.12°W. 50.7 ft. Mkd: 1/4 S24 CS BT.

FOUND O.K. 7-20-67 V.R.T.

Section Corner to Sections 14 - 13 - 23 - 24.

Found - Mound of Rocks & Rotten Fir Stump N.25°E. 44.9 ft., scribing Vis.
Fir Tree, now 36", S.20°E. 19.1 ft., shows 2 good axe scars.
Tree in good condition, did not open.

Remains of rotten Fir Stump S.75°W. 51.5 ft., no scribing found.
No trace found of N.W. BT., location for tree falls in road.

Set - Brass Cap Mkd: County Surveyor's T26S R2W S14 S13
Office, 1961 S23/S24

File Stones up around Brass Cap.
New BT's: 15" D.Fir S.83°W. 34.3 ft. Mkd: T26S R2W S23 CS BT.
6" W.Oak N.84 1/2°W. 24.1 ft. Mkd: T26S R2W S14 CSBT
7" W.Oak S.70°E. 22.0 ft. Mkd: T26S R2W S24 CS BT.
No trees available to N. E.

FOUND O.K. 7-20-67 V.R.T.

1/4 Corner to Sections 14 and 13. FD. OK K. HOFFINE 6/07
SEE M 153-43

Found - Fir Snag, 20", old bark scribing "1/4 SBT" visible, bears
N:20°E: 45.5 ft. from corner.

43" Fir N.40°W. 39.6 ft., scar visible, does not resemble axe scar.

Set - Brass Cap Mkd: County Surveyor's Office, 1961 T26S R2W
1/4 S14/S13 Build Rock Mound.

New BT's: 43" Fir to N.W. N.43°W (corrected bearing) 39.6 ft.
Mkd: 1/4 S14 CS BT.

6" W.Oak N.66°E. 36.2 ft. Mkd: 1/4 S13 CS BT.

28

Section Corner to Sections 10 - 11 - 14 - 15.

Found - G.L.O. Iron Pipe & Brass Cap in Mound of Rock.

36" D.Fir N.40 1/2°W. 10.6 ft., good bark scribing visible. REN #4

30" Fir N.62°E. 35.0 ft., tree recently uprooted & down. Good
bark scribing visible.

30" Fir Stump S.25 1/2°W. 35.0 ft., bark scribing visible.

30" Fir Stump S.22 1/2°E. 65.3 ft., bark gone from stump, no
scars or scribing visible.

New BT's: 8" Madrone N.73°E. 48.7 ft. Mkd: S11 CS BT.

5" Maple S.86°E. 29.4 ft. Mkd: S14 CS BT.

5" D.Fir S.81°W. 121.4 ft. Mkd: S15 CS BT.

Nov. 7, 1962

M. Godfrey
Vernon Tracy
Mike Stone

Milo E. Godfrey, Deputy
Vernon Tracy
Cletis Putnam
October 1961 - C.S. 52/77

FD. OK BY
R. QUIMBY 11/01
M 139-15