

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 26 S. T. S. R. 2 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORG. 21881

(continued)

New BT's: 10" Cedar N. 52° W. 10.9 ft. mkd.  $\frac{1}{4}$  S19 CS BT.  
10" D.Fir S. 38° W. 16.6 ft. mkd.  $\frac{1}{4}$  S30 CS BT.  
Note - This corner lies on top of small rounding spur sloping N.  
Reset Stone alongside Brass Cap.

49

$\frac{1}{4}$  Corner to Sections 31 and 32.  
Found - Orig. 10", now 15" Fir, Alive, N. 48° W. 13.9 ft. Open & find "BT",  
scribe & reverse, under 58 yrs. ring cnt.  
Orig. 8", now 14" Fir, down & rotting, N. 80° E. 28.4 ft., shows scar.  
5"x7"x13" Stone Mkd: " $\frac{1}{4}$ ", tipped out of position.  
Set - Brass Cap at Cor. Mkd: County Surveyor's T26S R2W  
Office, 1967  $\frac{1}{4}$  S 31 | S 32

Reset Stone alongside.  
New BT's: 6" W.Fir S. 69° W. 12.8 ft. mkd.  $\frac{1}{4}$  S31 CS BT.  
9" D.Fir N. 24° E. 19.4 ft. mkd.  $\frac{1}{4}$  S32 CS BT.  
Note - This corner on N-S cutting line cut off to East.

50

Section Corner to Sections 25 - 26 - 35 - 36.  
Found - 1916 G.L.O. Brass Cap, firmly set & properly marked.  
Orig. 18", now 22" Laurel N. 55° W. 25.1 ft., Alive, hollow,  
by looking inside, reverse scribing visible.  
New BT's: 15" D.Fir S. 30° E. 16.4 ft. mkd. T26S R2W S36 CS BT.  
12" D.Fir S. 66° W. 25.7 ft. mkd. T26S R2W S35 CS BT.  
11" Laurel N. 35° W. 55.1 ft. mkd. T26S R2W S26 CS BT.  
10" Maple N. 72° E. 28.6 ft. mkd. T26S R2W S25 CS BT.  
Note - This corner lies on precp. S. E. slope.

51

$\frac{1}{4}$  Corner to Section 26 only.  
Found - 1916 G.L.O. Brass Cap, firmly set & mkd. "8 $\frac{1}{4}$  S26" under S. side  
of 26" Fir log which we notch around Brass Cap.  
50"?, now 66" Cedar, Alive, N. 42° W. 15.2 ft., shows scar.  
Laurel Stool bears N. 56° E. 15.8 ft., locus of N.E. O.BT.  
New BT's: 16" Cedar N. 55° W. 38.2 ft. mkd.  $\frac{1}{4}$  S26 CS BT.  
26" Cedar N. 52° E. 43.3 ft. mkd.  $\frac{1}{4}$  S26 CS BT.  
Note - This corner lies on southerly slope at SW corner of timber in  
old logged-off unit.

52

W.  $\frac{1}{4}$  Corner to Section 22 only.  
Found - 1918 G.L.O. Brass Cap Mkd. properly set in mound of stone. # 148  
40", now 42" Fir Snag, N. 79° E. 70.0 ft., shows good scar.  
36", now 38" Fir, alive, S. 85° E. 31.0 ft., shows good scar.  
New BT's: 9" W.Fir N. 52° E. 24.3 ft. mkd.  $\frac{1}{4}$  S22 CS BT.  
14" Cedar S. 8° E. 13.8 ft. mkd.  $\frac{1}{4}$  S22 CS BT.  
Note - This corner lies approx. 400 ft. S. of old road from Smith's  
Ford Bridge on moderate N. slope.

53

Corner No. 1, of Tract 38.  
Found - 1918 G.L.O. Brass Cap, firmly set in mound of stone.  
Orig. 40", now " Fir, S. 60° W. 4.0 ft. Alive, shows good scar.  
Since Mensch only marked one BT., we mark new one:  
14" D. Fir S. 52° E. 44.0 ft. mkd. "1 Tr 38 CS BT."  
Note - This corner lies approx. 457 ft. E. of  $\frac{1}{4}$  cor. of Sec. 26, Ren. #51.

54

Corner No. 4, Tract 38. FOUND OR BY HOSTETTER, OCT. 2002 - M141-76  
Found - 1918 G.L.O. Brass Cap, firmly set.  
14", now 16" Cedar, alive, N. 8° W. 20.5 ft., prev. opened & scribe  
visible "4 Tr 38 BT" on decaying blaze.  
New BT's: 14" Cedar N. 26° W. 52.3 ft. mkd. "4 Tr 38 CS BT."  
10" W.Fir S. 16° E. 29.1 ft. mkd. "4 Tr38 CS BT."  
Note - This corner lies on very gentle, southeast slope.

Vernon "Ray" Tracy  
Jack Heritage and D. West  
July, 1967  
C. S. File No. 54/40