

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 26 S. T. S. R. 2 W R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21901

55

Closing Corner to Sections 34 and 35.  
(This is also the #2 corner of Tract 38.)  
Found - 1916 G.L.O. Brass Cap, firmly set & properly marked.  
S.W. BT. is completely destroyed.  
Find reverse scribe on the S.E. BT's. fragments.  
New BT's: 4" Cedar S. 23° E. 16.5 ft. mkd. CC S35 CS BT.  
14" Yew N. 51° E. 22.3 ft. mkd. CC CS BT.  
No trees avail. in section 34.  
Note - This corner lies on E. slope approx. 140 ft. W. of small creek.

56

S.W. Corner to Section 26 only.  
Found - 1916 G.L.O. Brass Cap, properly marked.  
20", now 28" Cedar N. 23° E. 24.4 ft., alive, previously  
opened & scribe visible. Only one BT. was mkd. for corner.  
New BT: 12" W. Fir N. 70° E. 21.8 ft. mkd. T26S R2W S26 CS BT.  
Note - This corner lies on steep, southerly slope.

$\frac{1}{4}$  Corner to Sec. 35, T26-2W. & Sec. 2, T27-2W.  
Found - No trace of Corner Stone nor S.E. BT. Call of 26 lks on  
bluff 15' high on line fits good.  
Orig. 40", now 40" Fir Snag 20' high, N. 4° W. 29.7 ft.,  
shows  $\frac{1}{4}$  S35 BT on burned unhealed blaze. (Mkd. by Collier, 1913)  
Set - Brass Cap at Cor. Mkd: County Surveyor's  $\frac{1}{4}$  S 35 T26S R2W  
Office, 1967 S 2 T27S  
Set in Mound of Stone.  
New BT's: 6" D. Fir N. 63° W. 9.2 ft. mkd.  $\frac{1}{4}$  S35 CS BT.  
9" D. Fir S. 11° W. 3.3 ft. mkd.  $\frac{1}{4}$  S2 CS BT.  
Note - This corner lies on very steep E. slope approx. 225 ft. W. of  
Creek.

RE-RENEWED, SET CORNER NO. #131

Vernon "Ray" Tracy  
Jack Heriatge & D. West  
July, 1967  
C. S. File No. 54/40

58

Section Corner to Secs. 34 & 35, T26-2W. & Sec. 3 & 2, T27-2W.  
Found - 1957 Cad. Brass Cap & Original Corner Stone.  
13", now 15" Fir, N. 25 $\frac{1}{2}$ ° E. 25.7 ft. Alive, healed blaze.  
13", now 13" Fir, Down, S. 43° E. 49.5 ft., scribe visible  
on unhealed blaze.  
13", now 16" Fir S. 29 $\frac{1}{4}$ ° W. 57.4 ft. Alive, healed blaze.  
10", now 14" D. Fir (not W. Fir) N. 76° W. 73.9 ft. Alive,  
healed blaze.  
29", now 15" Laurel S. 82° E. 55.4 ft. Alive, healed blaze.,  
Do not open healed blazes. Only Orig. SE. BT. standing.  
New BT: -15", D. Fir S. 75° E. 20.2 ft. mkd. T27S R2W S2 CS BT.  
Note - This corner lies on top of spur, ridge sloping south at old  
cutting corner. Sections 35 - 2 & 3 cut off.

59

$\frac{1}{4}$  Corner to Sec. 31, T26-2W. & Sec. 6, T27-2W.  
Found - Orig. 24", now 33" Fir, N. 78° E. 49.5 ft. Alive, shows good scar.  
Orig. 24", now 36" Fir sawed stump, S. 12° E. 26.4 ft. Open &  
find "S6 BT" reverse scribe under 41 years overgrowth.  
(These BT's were apparently rescribed about 1913 during the last  
retracement of the S. Line of T26-2W.)  
Set - Brass Cap at Cor. Mkd: County Surveyor's  $\frac{1}{4}$  S 31 T26S R2W  
Office, 1967 S 6 T27S  
New BT's: 17" Cedar S. 85° E. 83.8 ft. mkd.  $\frac{1}{4}$  S6 CS BT.  
10" Cedar N. 23° E. 29.3 ft. mkd.  $\frac{1}{4}$  S31 CS BT.  
Note - This corner lies on E-W cutting line, cut off to South approx.  
10 to 15 years ago.

60

Section Corner to Sections 31 & 32, T26-2W. & Sec. 5 & 6, T27-2W.  
Found - Old 3" sq. Cedar Post - Orig. 12", now 22" Cedar, alive,  
S. 80° W. 11.9 ft., shows good scar, Do not open, and  
Rescribe: "T27S R2W S6 CS BT".  
Orig. 16", now 30" Cedar, alive, N. 45° W. 21.1 ft., shows scar.  
Do not open - Rescribe "T26S R2W S31 CS BT".  
Orig. 12", now 24" Cedar, N. 80° E. 23.8 ft., alive, previously  
opened, face rotted, no scribe.  
Set - Brass Cap at Cor. Mkd: County Surveyor's S 31 S 32 T26S R2W  
Office, 1967 S 6 S 5 T27S

(continued next page)