

Douglas County Surveyor's Record of
Government Corners Renewed

T. 26 S. T. S. R. 2 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

(continued)

New BT's: 11" Cedar N. 69° E. 36.5 ft. mkd. T26S R2W S32 CS BT.
18" Cedar S. 20° E. 24.8 ft. mkd. T27S R2W S 5 CS BT.
Note - This corner lies at cutting corner, cut off in Section 6.

61

$\frac{1}{4}$ Corner to Sec. 32, T26-2W. and Sec. 5, T27-2W.
Found - Orig. 20", now 22" Laurel N. 35° W. 4.6 ft., Alive, scribe visible on unhealed blaze.
Orig. 20", now 32" Fir, S. 35° E. 19.8 ft., Alive, bark scribe, " $\frac{1}{4}$ B" in fair condition.

Set - Brass Cap at Cor. Mkd: County Surveyor's $\frac{1}{4}$ S 32 T26S R2W
Office, 1967 S 5 T27S

New BT: 12" D.Fir N. 8° W. 12.8 ft. mkd. $\frac{1}{4}$ S32 CS BT.
20" W.Fir S. 1° W. 9.0 ft. mkd. $\frac{1}{4}$ S 5 CS BT.

Note - This corner lies on top of ridge, sloping south & E-W cutting line, cut off to north.

62

Sec. Cor. to Sections 32 & 33, T26-2W. & Secs. 4 & 5, T27-2W.

Found - Orig. 12", now 30" Cedar, N. 57° E. 23.8 ft. Alive, shows good scar. We do not open.

Orig. 10", now 18" Fir, S. 67° E. 18.5 ft. Alive, scribe visible on opened blaze.

Orig. 40", now 50" Fir, N. 30° W. 8.6 ft. Alive, shows poor bark scribe " T S3 BT".

Orig. 8", now 12" Fir, now snag, S. 40° W. (record S.35°W.) 3.3 ft., Open & shows " T27S R2W S5" scribe.

Set - Brass Cap at Cor. Mkd: County Surveyor's S 32 | S 33 T26S
Office, 1967 S 5 | S 4 T27S R2W

New BT's: 26" Cedar N. 36° W. 37.1 ft. mkd. T26S R2W S32 CS BT.

14" Cedar N. 24° E. 31.2 ft. mkd. T26S R2W S33 CS BT.

5" D.Fir S. 59° E. 25.6 ft. mkd. S 4 CS BT.

9" Cedar S. 21° W. 21.4 ft. mkd. T27S R2W S5 CS BT.

Note - This corner lies 20 ft. S. of creek 2 ft. wide, course S.

63

$\frac{1}{4}$ Corner to Sec. 33, T26-2W. & Sec. 4, T27-2W.

Found - Orig. 20", now 38" Cedar Snag, S. 53° W. 18.5 ft. (not S.57°W.) scribe visible on opened blaze.

Orig. 36", now 48" Fir, N. 55° E. 18.5 ft. Alive, bark scribe, poor.

Set - Brass Cap at Cor. Mkd: County Surveyor's $\frac{1}{4}$ S 33 T26S R2W
Office, 1967 S 4 T27S

New BT's: 8" W.Fir N. 45° E. 4.8 ft. mkd. $\frac{1}{4}$ S33 CSBT.

9" W.Fir S. 56° W. 43.1 ft. mkd. $\frac{1}{4}$ S4 CS BT.

Note - This corner lies old E-W cutting line, selective logged to south.

64

$\frac{1}{4}$ Corner to Sections 25 and 26.

Found - 1916 G.L.O. Brass Cap, firmly set in mound of stone.

Orig. 10", now 12" Hemlock, N. 33° E. 9.2 ft., down & burned.

Hole for other Orig. BT. bears N. 27° W. 19 ft.

New BT: 12" Cedar S. 28° W. 41.0 ft. mkd. $\frac{1}{4}$ S26 CS BT.

Note - No other trees available due to old logging. This corner lies on steep, N. E. slope.

65

$\frac{1}{4}$ Corner to Sections 34 and 35.

Found - 1916 G.L.O. Brass Cap, firmly set, properly marked.

Uprooted Stump of 24" Cedar N. 80° W. 19.1 ft., now lying north of corner, scribing visible on open blaze.

No trace of other BT.

New sBT: 16" Hemlock S. 25° E. 110.9 ft. mkd. $\frac{1}{4}$ S35 CS BT.

No trees available in Section 34.

Note - This corner lies 12.5 ft. N. of the #3 corner of Tract 38, see Ren.66, on steep E. slope 100 ft. W. of temporary log road.

Vernon "Ray" Tracy
Jack Heritage & D. West
July, 1967
C. S. File No. 54/40

WILD-CORNER NO. #159