

Douglas County Surveyor's Record of
Government Corners Renewed

T. 26 S. T. S. R. 2 W. R. W. W. M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21881

78

$\frac{1}{4}$ Corner to Sec. 6, T26-2W. & Sec. 1, T26-3W.
Found - 1963 Cadastral Brass Cap, set in mound of Stone.
Orig. 40" Fir, now sawed stump, S. 88° E. 14.5 ft., shows "BT",
bark scribe.
50" Fir, alive, N. 2° W. 31.0 ft., shows $\frac{1}{4}$ S CS BT. (Ren. #22)
(bark scribe in poor condition)
18" Cedar S. 53 $\frac{1}{2}$ ° E. 27.1 ft.
New BT: 9" Hemlock N. 53° W. 29.3 ft. mkd. $\frac{1}{4}$ S1 CS BT.
Note - This corner lies on top of ridge, course N.E. & S.W. at N.E.
corner of cut-off unit.

79

North $\frac{1}{4}$ Corner to Section 1 only, T26-2W.
Found - Basalt Stone 18"x10"x8" mkd. " $\frac{1}{4}$ " on S. side, firmly set
by Collier in 1913.
Orig. 36", now 48" Fir, alive, S. 5° W. 44.2 ft., shows " $\frac{1}{4}$ S" bark scribe.
Orig. 36", now 50" Fir, alive, N. 60° E. 25.1 ft., (Record 23.1), shows
edge of old axe bark blaze & possible fragmentary scribe marks.
Set - Brass Cap at Cor. MKd: County Surveyors T25S
(Reset Stone alongside) Office, 1967 2 T26S R2W $\frac{1}{4}$ S1
New BT's: 14" D. Fir S. 36° E. 23.0 ft. mkd. $\frac{1}{4}$ S1 CS BT.
16" D. Fir S. 53° W. 4.3 ft. mkd. $\frac{1}{4}$ S1 CS BT.
Note - This corner lies on very steep, west slope approx. 220 ft.
east of small creek, course S.W.

80

North $\frac{1}{4}$ Corner to Section 4 only, T26-2W.
Found - Orig. 10", now 16" Cedar, alive, N. 30° E. 10.6 ft., scribe marks
visible on unhealed blaze.
Orig. 16", now 32" Cedar, alive, S. 20° W. 19.8 ft., shows good
scar. Do not open. (Rescribe: " $\frac{1}{4}$ S4 CS BT")
Set - Brass Cap at Cor. Mkd: County Surveyors T25S
Office, 1967 T26S R2W $\frac{1}{4}$ S4
New BT: 16" Cedar S. 72° E. 19.6 ft. mkd. $\frac{1}{4}$ S4 CS BT.
Find - Remains of Corner post while excavating to set Brass Cap.
Note - This corner lies on bench approx. 400 ft. N. of top of
ridge, course NE. & SW.

81

Closing Corner for Sections 28 and 27. *FD OK FEB. 2004
D. EDWARDS M143-66*
Found - G.L.O. Brass Cap, properly marked in 1917.
10" D. Fir, now 22", S. 12° W. 9.2 ft., shows good face.
New BT; 10" D. Fir S. 86 $\frac{1}{2}$ ° E. 25.8 ft. scribed T26S R2W S27 CCCS BT.

82

Closing Corner to Sections 21 and 28 only. *FD OK FEB. 2004
D. EDWARDS M143-66*
Found - G.L.O. Brass Cap, properly marked in 1918.
6", now 12" Hemlock, SNag, S. 32° W. 21.8 ft., opened & *FD OK BY
T Hostetter
12/2005 M149-17*
found scribing "8".
40", now 46" Fir, N. 11° W. 33.0 ft., shows good face.
New BT's: 10" Hemlock N. 79 $\frac{1}{2}$ ° W. 18.1 ft. mkd. T26S R2W S18 CC CS BT.
12" Hemlock S. 45° W. 13.0 ft. mkd. T26SR2W S28 CC CS BT.
Note - This corner lies 360 ft. south of logging road.

83

$\frac{1}{4}$ Corner to Sections 28 and 29. *FD OK BY
T. Hostetter
12/2005 M149-17*
Found - 8"x10"x12" Stone, set in mound of stone, no marks found.
Orig. 10", now 26" Hemlock, Alive, S. 33° E. 13.2 ft., prev. opnd. *T. Hostetter*
and shows " $\frac{1}{4}$ S29BT" scribe.
Also find pieces of overgrowth with reverse scribe.
Orig. 8", now 13" Cedar Snag, N. 40° W. 40.0 ft., (record N. 45° W. 33.7)
previously opened & shows " $\frac{1}{4}$ ". Open lower & find "BT".
Set - Brass cap at Cor. Mkd: County Surveyors T 26 S R 2 W
office, 1967 $\frac{1}{4}$ S 29 S 28
(Set under 36" log lying across corner point)
New BT's: 7" Hemlock N. 48° E. 22.0 ft. mkd. $\frac{1}{4}$ S28 CS BT.
9" Hemlock S. 70 $\frac{1}{2}$ ° W. 20.1 ft. mkd. $\frac{1}{4}$ S29 CS BT.
Note - This corner lies on flat bench area.

Vernon "Ray" Tracy
Jack Heritage & E. West
August, 1967
C. S. File No. 54/40