

**Douglas County Surveyor's Record of  
Government Corners Renewed**

T 26

T. S.

R 2

R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Lee Roberts  
For: Weyerhaeuser Co.  
Oct. 1977  
M 67 - 61

Closing Corner for Secs. 35 and 36 only of T.25-2  
Set - 5/8" x 42" Rebar  
BT's- 10" Fir, N.20°E., 8.2 ft. to R.R. spike  
18" Fir, N.42°W., 11.9 ft. to R.R. spike.

109

10/77

R. B. Kimberling  
F.C. Silagy  
Doug. Co. Surveyors  
Office  
Dec. 30, 1977  
C.S. 59/42

1/4 Corner for Sec. 7 and Sec. 12 of T26-3. 110  
Found - 1959 Cadastral brass cap, properly marked, set in a 1.0 ft. high  
3.0 ft. dia. mound of stone with pipe 13" above ground.  
a 20" Fir (down) bears S.63°W., 35.6 ft. with a well healed blaze.  
(no record of marking tree.)  
a 15" Cedar, dead, bears N.81 1/2°E., 46.5 ft. with visible  
scribing "1/4 S7 BT" in partially healed single blaze.  
a 12" now 14" Cedar bears N.62°W., 19.8 ft. with visible scribe  
marks in almost healed blaze.  
New BT - A 50" D. Fir bears N.45°E., 32.3 ft. single blazed and marked  
"1/4 S7 CS BT".  
Corner is 150 ft. south of south bank, North Umpqua River.

12/77

111

R. B. Kimberling  
P.L. Earle  
S.J. Flaue  
Doug. County Surveyors  
Office  
C.S. 59/46  
Jan. 10, 1978

Section Corner for Secs. 6 and 7; and Secs. 1 & 12 of T26-3.  
Found - A 2 1/2" I.P. with 1959 Cadastral brass cap 7" above ground  
properly marked.  
A 15" now 36" Cedar stump is pushed over, orig. position bears approx  
S. 60°W., 19.8 ft. but no visible blaze (OBT).  
Remains of a Fir stump bears N.46°W., 58.1 ft. (OBT).  
A 12" now 13" Cedar snag bears S.73°E., 27.1 ft. with scribing  
"T26S R2W S7 BT" in single blaze (1959 resurvey).  
A 50" Fir stump with a Weyerhaeuser tag and blaze bears S.60°W.,  
35.0 ft.  
A 28" Fir stump with a Weyerhaeuser tag and blaze bears N.59°W.,  
47.4 ft.  
New BT's- A 13" Cedar with "MR" carved in west face bears N.83°E., 20.0 ft.  
double blazed and scribed "T26S R2W S6 CS BT".  
A 10" Fir, bears S.20 1/2°E., 124.1 ft. double blazed and scribed  
T26S R2W S7 CS BT".  
A 3" "X" chisled 3.0 ft. above ground in a 20 ft. x 20 ft. boulder  
bears S.88 1/2°W., 32.0 ft.  
A 6" Chinkapin bears N.50°W., 71.8 ft. double blazed and scribed  
T26S R3W S1 CS BT"  
Corner is 30 ft. North of Road.

1/10/78

112

Gary Langlitz  
S. Flaue  
Doug. Co.  
Surveyors Off.  
March 4, 1978  
C.S. 59/46

South 1/4 Corner for Sec. 18 only.  
Found - A 1" I.P. extending 14" above ground on a steep easterly slope,  
with a 1918 GLO brass cap.  
An orig. 35" D.Fir now 32" alive, but in poor condition, no  
scribing visible on rotten face, bears N.47°E., 11.2 ft.  
An orig. 18" D.Fir now a 25" stump with well healed blaze bears  
N.20°W., 38.3 ft. "W-Nail" in base of this BT bears N.20°W., 37.0 ft.  
A "W-Nail" in the base of a 44" D. Fir bears S.33°W., 25.7 ft.  
Set - At the present position of the 1918 GLO monument, we lower said  
monument to extend approx 3 inches above ground.  
New BT - An 18" D. Fir scribed "RP S 1/4 S18 CS BT" on a double blaze, bears  
S.77°E., 40.3 ft.  
Corner located along southerly edge of recently logged area.

4/4/78

113

Gary Langlitz  
Frank Silagy  
Doug. Co. Surveyors  
Office  
Witness: Glen McChesney  
Weyerhaeuser Timber  
Co.  
July 20, 1978  
C.S. 60/11

1/4 Corner for SEc. 19 and Sec. 24 of T26-3.  
Found - No trace of orig. 1855 or 1901 corner posts.  
No trace of original 1855 BT's Ren. #21  
From 1910 retracemetn, we find: A 10" now 13" Laurel (Madrone)  
alive with fragmentary reverse scribing found on unhealed  
blaze, bears N.69°E., 8.6 ft.  
A 10" now 15" Laurel (madrone) alive with well healed blaze  
which we open and find good face but no scribing, bears  
S.24°W., 6.6 ft. (Rec. S.21°W., 6.6 ft.)  
Set - At a location which agrees with measurements shown to the  
previously described resurvey bearing trees, WE SET: a 1" x 30"  
Iron pipe, 27" in theground with brass cap attached marked: