

**Douglas County Surveyor's Record of
Government Corners Renewed**

T 26

T. S.

R 2

R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Ronald Geisler
For: Champion
International
Crew: Lynn Sibley
Dean Turner
June 30, 1987
C.S. 63/60

140

East 1/4 Corner for Section 27 only.
Found - 2 1/2" alum. cap on a 1" iron pipe extends 11" above ground. Ren. 124
6" hemlock, leaning badly bears N.62°W., 11.5 ft. (Rec. 10.4 ft.)
Scribing visible. (1981)
12" Hemlock now down and uprooted bears N.30°30'W., 20.0 ft.
to root hole. Scribing visible. (1981)
New BTs - 11" Hemlock bears N.87°W., 40.7 ft. Scribed "S27 1/4 BT"
9" Hemlock bears S.70°30'W., 42.8 ft. Scribed "S27 1/4 BT".
6/30/87

Ronald Geisler
For: Champion
International
Crew: Lynn Sibley
Dean Turner
C.S. 63/60 Juen 30, 1987

141

Closing Corner for Sections 3 and 4 only.
Found - 1959 BLM 3 1/2" brass cap on a 2 1/2" iron pipe extends 4" above
ground. Also found basalt stone alongside monument.
24" D. fir stump bears S.14 1/4°W., 35.3 ft. Face cut off. (1959)
New BT - 15" D. fir bears S.55°E., 13.2 ft. scribed "T26S R2W S3 CC BT"
6/30/87

142

East 1/4 Corner for Section 13 only
Found - 3" dia. brass cap 4" below ground. Ren. No. 99
8" now 16" dia. D. Fir down and out of position (to be cut up)
with a fully healed double blaze, root hole bears S.2°W., 128.5'
(agrees with record) Ren. No. 99
Steel fence post with U.S. Forest Service sign, bears N.0 1/2°E.,
5.0 ft. (Rec. N.3°W., 5.0 ft.) Ren. No. 99
6" now 9" dia. D. Fir with a fully healed single blaze, bears
N.81°E., 116.5 ft. (Rec. N.77°E., 116.5 ft.) Ren. No. 130
NE corner of two story log cabin bears S.22 1/2°W., 180.2 ft. (Rec.
S.18 1/2°W., 180.2 ft.) Ren. No. 130

New Accessories:

3" dia. Holly tree, we did not blaze or scribe, in yard, bears
S.14 1/4°W., 106.6 ft. No tags put on tree.
12" dia. Willow tree, we did not blaze or scribe, in yard bears
N.5 1/4°E., 33.2 ft. No tags put on tree.
SE corner of an old 20' x 20' log cabin bears N.25 3/4°W., 183.3 f
Cabin not set on permanent foundation.

Corner is 1 ft East of a 3'x6'x6' high boulder and 18 ft. East of a small
pond. Corner is at edge of yard. Owner did not want trees scribed. New
BTs are only ones of their kind near corner.

2/3/92

143

Center East 1/16 Corner for Section 17.
Found - 3" BLM brass cap on a 2 1/2" O.D. iron pipe protruding 2"
above a 2 ft. dia. mound of stone. Cap is marked:
"U.S. Cadastral Survey C E1/16 C 1959 Bureau of Land Management"
S17

Accessories Found -

11" now 16" dia. D. Fir with a fully healed single blaze, bears
N.80 1/2°W., 22.9 ft. (rec. N.80 1/2°W., 23.8 ft. to center of trunk
1959 survey)
11" now 17" dia. 3 ft. high D. Fir stump with a fully healed singl
blaze, bears S.2 1/4°E., 13.2 ft. (agrees with rec. 1959 survey)

New Accessories -

7" dia D. Fir double blazed and scribed "CE1/16 S17 CS BT"
bears S.46°W., 7.4 ft.
13" dia. Maple, double blazed and scribed "CE1/16 S17 CS BT"
bears N.44 1/2°W., 18.5 ft. to center of trunk.
11" dia. I. Cedar, double blazed and scribed "CE1/16 S17 CS BT"
bears S.18 1/2°E., 67.0 ft.

Note - Corner lies 5 ft. south of creek bank.

6/11/92

Douglas County
Surveyors Office
Randall Smith and
Stephen Flause
Feb .3, 1992
C.S. File 64/23

Douglas County
Surveyors Office
Randall Smith
Stephen Flause
June 8, 1992
C.S. 64/26