

**Douglas County Surveyor's Record of  
Government Corners Renewed**

T. 26 S. T. S. R. 2 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Don Bentz  
For: U.S. Forest Service  
July 19, 1993  
C.S. File 63/153

Douglas County Surveyor's Office  
Randall Smith, Stephen Flause  
Oct. 24, 1994 C.S. File 64/52

144

East  $\frac{1}{4}$  Corner for Section 36 only.  
Found - 1" Iron Pipe, firmly set 10" above ground in a 2 ft. dia. mound of stone with a  $2\frac{1}{2}$ " Brass Cap properly marked.  
50" D.Fir stump with healed blaze bears N.7°W., 15.3 ft.  
41" D.Fir stump with healed blaze bears S.87°W., 32.3 ft.  
New Accessories -  
5" Fir with double blaze, upper scribed  $\frac{1}{4}$  Sec 36, lower blaze scribed BT with nail and washer stamped LS 839 and bears S.41°W., 21.3 ft.  
Set spike in center of 50" D.Fir stump which bears N.7°W., 15.3 ft.  
Note - All bearing trees have a 6" red band painted around the trees and the blaze face painted red. USFS sign 54-3, Bearing Tree, and 54-9, Land Surveying Monument, are nailed to all bearing trees.

145

Corner for Sections 25 & 36 only.  
Found - 3" Iron Pipe, 12" above ground in a 24" mound of stone with a 3" Brass Cap properly marked.  
40" Cedar bears S.84°W., 23.4 ft. with a partly visible scribing.  
28" D.Fir with healed blazes was blown over. See Ren. # 68  
New Accessories -  
30" D.Fir with double blaze, upper scribed T26S R2W S25, lower blaze scribed BT with nail and washer stamped LS839 bears N.78°W 42.8 ft.  
Note - All bearing trees have a 6" red band painted around the tree and the blaze face painted red. USFS sign 54-3 'Bearing Tree' and 54-9, 'Land Surveying Monument' are nailed to all bearing trees.

146

Corner for Sections 24 & 25 only.  
Found - 3" Iron Pipe firmly set 8" above ground with a  $3\frac{1}{2}$ " Brass Cap properly marked.  
31" Cedar bears S.74°W., 19.1 ft with a partly healed lower blaze and an open upper blaze with no scribing.  
40" D.Fir stump bears N.7°W., 70.0 ft. with healed blaze.  
New Accessories -  
8" W.Fir with upper blaze scribed T26S R1W S30, lower blaze scribed BT with brass washer stamped LS 839 bears S.21°E., 13.1 ft.  
Note - All bearing trees have a 6" red band painted around the tree and the blaze face painted red. USFS sign 54-3 'Bearing Tree' and 54-9 'Land Surveying Monument' are nailed to all bearing trees.

147

Center  $\frac{1}{4}$  Section 17  
Found -  $3\frac{1}{4}$ " dia. brass cap on a  $2\frac{1}{2}$ " O.D. iron pipe, protrudes 2" above ground. (1959 BLM)  
Accessories Found -  
18" now 21" dia. Hemlock with a fully healed single blaze, bears N.75 $\frac{1}{4}$ °E., 47.8 ft. (1959 BLM)  
8" now 14" dia. Hemlock with a fully healed single blaze bears S.24 $\frac{1}{2}$ °W., 27.2 ft. (rec. S.24 $\frac{1}{2}$ °W., 27.7 ft. is a slope measurement) (1959 BLM)  
New Accessories -  
10" Maple, double blazed and scribed "C $\frac{1}{4}$  S17 CS BT" bears N.1°W., 27.2 ft.  
7" Maple, double blazed and scribed "C $\frac{1}{4}$  S17 CS BT" bears N.89°W., 5.2 ft.  
Note - Corner lies in old growth timber on a bench.