

Douglas County Surveyor's Record of
Government Corners Renewed

26 T. S. 3 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE., 21881

James W. Byron, Dep. Co. Surveyor
R. Irving
J. Fee
May 31, 1955
C.S. File No. 46/154

Renewed section corner to section 7, 12, 13, and 18 T26S.R3W.&R4W. 64
Found:

3 BTs as renewed. REN.#13
The N.E. BT now 16 inch stump only. Scribed BT bears N 27°E 25.1 Feet
The S.W. BT alive & in good condition bears 17° W. 22.4 feet..
Now 14 inch B.O. 22.4 feet shows blaze I do not cut out.
The S. W. now 20 inch stump only, rotted but shows blaze it bears
562°E. 54.1 feet. The N.W. BT burned.
I blaze & scribe 8 inch W.O S74°E. 84.2 feet S 18 CS BT.
Blaze & scribe 12 inch W.O. N.48°E 15.9 feet 23 W. S 7 CS BT.
Blaze & scribe 13 inch W.O. N.73½° W. 15.7 feet R 4W. S 12 CS BT.

Set Brass cap marked $\frac{12}{13} \frac{7}{18}$ T 26 S. R 3 W. County Surveyors Office., 1955

James W. Byron, Dep. Co. Surveyor
R. Irving
J. Fee
May, 1955
C.S. File No. 46/154

Renewed section corner to section 8, 9, 17, and 16. 65
Found:

Brass cap at corner. $\frac{8}{17} \frac{9}{16}$
The N.W. BT which checks for bearing & Dist. is the only BT left. The
other BTs have been cut 7 stumps rotted. SEE ALSO REN.#28
The N.W. BT now 24 inch shows good blazes, I do not cut out.
Blaze & Scribe 8 inch W.O. S.62°E 85.0 feet S 16 CS BT.
Blaze & Scribe 10 inch W.O. N.72°E. 53.8 feet S.9 CS BT.
Blaze & Scribe 10 inch Cedar S.7½°W. 31.9 feet S 17 CS BT.

J. Byron, Dep. Co. Surveyor
R. Irving
J. Fee
June 8, 1955
C.S. File No. 46/154

Renewed ¼ corner to sections 17 & 16. 66
Found:

N.W. BT as previously renewed now 14 inch R.F. Shows good blaze I
do not cut out. Also found N.E. BT stump only scribed "BT" at base.
Both BTs check for bearing & Dist. I do not find ¼ inch iron bolt
at corner. REN.#29 169

Set: ¾ inch iron rod at corner (Corner is under N. S. fence and in small brook)
Blaze & Scribe 8 inch R. Fir S.8°W. 17.0 feet ¼ S CS BT.

James W. Byron, Deputy Co. Surveyor
R. Irving
J. Fee
June, 1955
C.S. File No. 46/154

Renewed ¼ corner to sections 17 & 20. 67
Found:

Auto springs and BT 24 inch R.Fir N.69°W. 44 feet as renewed by Boyer, 1949
Also found 30 inch B.O. S. 3°E. 10.0 feet. Original BT A section cut from
this tree. Shows scribing. REN.#44 173

Blaze & Scribe 10 inch R.Fir N.68°E. 23.5 feet ¼ S 17 CS BT.

Renewed ¼ corner to sections 7 & 8. 68

Location of ¼ corner determined by proportional measurements.
Set 1 inch iron pipe with brass cap marked ¼ S 7/8 T 26 S. R3W. County
Surveyors office, 1955 at surface of ground.

Renewed ¼ corner to sections 7 & 18. 69

Original BTs not found. Position of corner located by proportional
measurements.

Set: 1 inch iron pipe with brass cap marked County Surveyors Office, 1955
¼ corner $\frac{7}{18}$ T 26S. R 3W. 159

Blaze & Scribed 12 inch W. O. N.69W. 65.8 feet ¼ S 7 CS BT.
Blaze & Scrib 12 inch W. O. S. 11½W. 77.0 feet ¼ S 18 CS BT.

Renewed ¼ corner to Sections 18 & 17. 70

BTs not found. Location of ¼ corner determined by Sub Division of 140
section. Corner falls on steep bank of San Umpqua River.

Set: Brass cap at top of bank for witness corner. Brass cap marked CS, 1955
Witness corner 21.3 feet N. $\frac{5}{18}$ S. 18/17
Blazed & Scribed 12 inch W.O. S.59°W. 61.8 feet Witness Corner S 18 CS BT.
Mt. Scott Lookout bears N 16¼°E.

Renewed Section Corner to Sections 7, 8, 18, & 17. 71

Location of corner determined by double porportion.
Set: Brass cap 2 inches under surface marked CS, 1955 $\frac{7}{18} \frac{8}{17}$ T26 S. R3W.

Blaze Bark & Scribe 40 inch R.F. N.35°W. 173.6 feet, S 7 T26S. R3W CS BT.
Blaze & Scribe 50 inch triple Cedar S22½°W. 173.3 feet, S 18 CS BT.
No suitable trees in N.E. or S.E. Quads.