

Douglas County Surveyor's Record of
Government Corners Renewed

T. 26 S. T. S. R. 3 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

127

Center $\frac{1}{4}$ Corner Section 9.
Found - 1924 GLO Brass Cap Mkd: "C $\frac{1}{4}$ S9".
7", now 11", W. Oak S. 16° E. 4.6 ft., shows faint scar, dying.
We do not open.
8", now 16", B.Oak N. 47°W. 5.3 ft., shows scar, alive and in
good condition. We do not open.
New BT's: 11" D.Fir N. 70° E. 26.4 ft. Mkd: "C $\frac{1}{4}$ S9 CS BT".
Rescribe 16" B.Oak N.47°W. 5.3 ft. Mkd: "C $\frac{1}{4}$ S9 CS BT".
Note - Corner lies in N. - S. Fence Line.

1924 GLO CALL THIS
NOTES SPECIAL
"S.M.C."

128

South M. C. of Section 9. (Left Bank of N. Umpqua River)
Found - 1924 GLO Brass Cap, firmly set & Mkd: "S MC S9".
11", now 13", Ash South 15.8 ft., shows scribe on partially
No trace of other BT. healed scar.
New BT: 11" W.Oak S. 65° E. 22.2 ft. Mkd: "S MC S9 CS BT".
This corner lies approx. 50 ft. North of road, course N.E. & S.W.

SEE REN.
#229 FOR
"W.C." S.M.C.

129

$\frac{1}{4}$ Corner to Sections 9 and 16.
Found - GLO Brass Cap at 4-way Fence Cor. Mkd: " $\frac{1}{4}$ S 9 1924".
Also found old Oak Post, Ren. #79. S 16
20" Fir S. 85 $\frac{1}{4}$ ° E. 118.1 ft., cut flush with ground, no scribe.
10", now 16", W.Oak N. 15° W. 23.1 ft., shows good scar,
we do not open. See Ren. #79.
New BT: 12" W. Oak S. 9° W. 58.7 ft. Mkd: $\frac{1}{4}$ S16 BS BT.
Rescribed 16" W. Oak N. 15° W. 23.1 ft. Mkd: $\frac{1}{4}$ S9 CS BT.

Vernon "Ray" Tracy
Mike Stone & Jerry Layne
January 1966
C. S. File No. 54/7

130

West 1/16 Sections 9 and 16.
Found - Badly rotted remains of 8", now 15" Fir S. 41° E. 10.6 ft.,
found "W 1/16 S" scribe & reverse.
No trace of 1924 Brass Cap nor B.Oak BT. to N.E.
Set - Brass Cap at Cor. Mkd: County Surveyor's T26S W 1/16 S 9
Office, 1966 R3W S 16
New BT's: 18" D.Fir S. 51° E. 17.2 ft. Mkd: W 1/16 S16 CS BT.
16" Pine N. 24° E. 41.3 ft. Mkd: W 1/16 S9 CS BT.
This corner lies approx. 40 ft. S. of N. Umpqua Highway.

131

Wit. Corner to $\frac{1}{4}$ Corner of Sections 9 and 10. (Right Bank of River)
Found - 14", now 20", Fir N. 63° W. 12.5 ft. Open & find "9" scribe.
No trace of other BT's. nor marks on Bedrock. See Ren. #30.
Set - "PK" Nail & run North 35.0 ft. & Set Wit. Corner & Brass Cap, #236
14" in ground and build mound of stones around Pipe Mkd:
County Surveyor's Office, 1966 T26S R3W
35 ft. to Corner. W.C. $\frac{1}{4}$ S 9 / S 10
New BT's: 8" D.Fir S. 34° W. 8.4 ft. Mkd: W.C. S9 CSBT.
14" D.Fir S. 80° E. 23.3 ft. Mkd: W.C. S10 CS BT.
Note - this witness corner lies on top of high bank.

RE-
WITNESS CORNER NO. 236

132

$\frac{1}{4}$ Corner to Sections 4 and 9.
Found - 1924 GLO Brass cap pushed out of place & buried.
14", now 24", Fir Stump N. 47° E. 4.0 ft., shows good scar.
14", now 24", Fir S. 69° W. 19.1 ft. Alive, prev. opened &
shows good "S" & parts of other scribe.
Reset - GLO Brass Cap at Corner Point.
New BT's: 10" D.Fir S. 58 $\frac{1}{2}$ ° W., 40.2 ft. Mkd: $\frac{1}{4}$ S9 CS BT.
7" D.Fir N. 38° E. 66.0 ft. Mkd: $\frac{1}{4}$ S4 CS BT.
Note - Fence corner bears N. 47° E. 5.0 ft., fences E - W & S.

133

Section Corner to Sections 3 - 4 - 9 - 10.
Found - 1924 GLO Brass Cap Mkd: "T26S R3W" 1924.
5", now 7", W.Oak N.24°W. 1.3 ft., alive, shows good scar
20", now 24", B.Oak N.22°W. 13.2 ft., shows good scars, Alive.
12", now 19", B.Oak S.45°W. 3.3 ft., shows faint scar, Alive.
10", now 18" B.Oak S.13°W. 42.2 ft., Top broken out, shows scar. Alive.
New BT's: 14" D.Fir N.38°E. 18.4 ft. Mkd: S9 T26S R3W CS BT.
12" D.Fir S.20°E. 6.4 ft. Mkd: S10 T26S R3W CS BT.
This corner lies on top of ridge, course NE and SW.