

Douglas County Surveyor's Record of
Government Corners Renewed

T. 26 S. T. S. R. 3 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

134

$\frac{1}{4}$ Corner to Sections 4 and 3.

Found - Orig. 18", now 21" B.Oak Stump S. 14° W. 310.9 ft. Chop out "BT" scribe & reverse from back side.

No BT. East of Line.

Set - Brass Cap at Corner Mkd: County Surveyor's Office, 1966

T26S $\frac{1}{4}$ S 4/ S 3 R3W

New BT's: 27" Red Cedar S. 22° W. 38.0 ft. Mkd: $\frac{1}{4}$ S4 CS BT.

20" Red Cedar S. 42° E. 21.9 ft. Mkd: $\frac{1}{4}$ S3 CS BT.

Note - This corner lies on steep South slope.

135

$\frac{1}{4}$ Corner to Sections 8 and 9.

Found - 1924 GLO Brass Cap, bent over & Stump Holes at proper bearing & distance for BT's. recorded in 1924 resurvey.

No evidence of Ren. # 3.

Reset - Brass Cap.

Since the closest trees are approx. 600 to 800 ft. off,

We use most southerly Pole of 3 wire transmission line as Bearing Object.

Pole bears N. 32° W. 199.5 ft. Put yellow Line Tag on Pole facing corner.

136

South $1/16$ Corner of Sections 8 and 9.

Found - GLO Brass Cap, 1924, Mkd: "S $1/16$ S8/S9".

10", now 29", B.Oak N. $83\frac{1}{2}^{\circ}$ W. 120.8 ft., shows faint scar, We do not open.

N. E. BT., down & badly burned.

New BT: 17" B.Oak in clump of three, N. 88° E. 32.9 ft. Mkd:

"S $1/16$ S9 CS BT".

Note - This corner lies near bottom of S. W. slope 136 ft. North of fence, course S. 70° W. & N. 70° E.

137

Section Corner to Sections 4 - 5 - 8 - 9.

Found - 1924 GLO Brass Cap Mkd: and Stumps of the BT's. recorded in 1924 resurvey notes.

New BT's: 15" Red Cedar S. 17° W. 118.2 ft. Mkd: T26S R3W S8 CS BT.

14" Red Cedar N. 22° W. 109.5 ft. Mkd: T26S R3W S5 CS BT.

No trees available to S.E.

This corner lies at fence corner, fences N. - S. & E.

138

S. W. Corner D. L. C. No. 41.

Found - 15", now 24", Fir S. $14\frac{1}{2}^{\circ}$ W. 49.0 ft., Alive & shows good scar. We do not open. Eppstein's Ren. #34.

No trace of $\frac{3}{4}$ " I. Pipe set by B.B.Irving, 1941, recorded in C. S. File No. 47/63.

1" I. Pipe bears North 66.0 ft., also set by B.B.I.C.S 47/63.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1966

S. W. DLC 41 / T26S R3W

Brass Cap set flush with ground on south edge of driveway.

Fence Corner bears North 12.0 ft., running E. & N. Also

the 1" I. Pipe N. 66.0 ft. is the S. E. Corner DLC 40.

139

S. E. Corner D. L. C. No. 40.

Found - 1" Iron Pipe, as recorded in C.S. File No. 47/63, Set by B. B. Irving, 1941 from Eppstein's BT, recorded in Ren. #32. No trace of Eppsteins's BT.

From the S. W. Corner DLC #41 which is a Brass Cap, we measure 66.0 ft. North to I. Pipe.

New BT: 9" B.Oak S. 65° W. 4.4 ft. Mkd: S.E. DLC 40 CS BT.

Note - This corner lies in a fence corner with fences W. & S.

Vernon "Ray" Tracy
Mike Stone & Jerry Layne
January 1966
C. S. File No. 54/7