

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 26 S. T. S. R. 3 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

146

Mst. Easterly S.E. Corner D. L. C. No. 45.  
Found - Orig. 6", now 11" W.Oak N. 40° W. 15.2 ft. Open & find  
"5 BT", scribe reversed.  
Orig. 8", now 8", B. Oak S. 80° W. 13.2 ft., down, dead  
& rotten. No scribe found.  
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1966  
T26S R3W E.SE. Cor. DLC 45  
New BT's: 12" W.Oak S. 8° W. 5.9 ft. Mkd: E.SE DLC 45 CS BT.  
12" D. Fir S. 67° E. 23.1 ft. Mkd: E.SE. DLC 45 CS BT.  
Note - This corner lies approx. 250 ft. East of Int. "L" Corner.

147

Interior "L" DLC No. 45.  
Found - Orig. 6", now 20" W.Oak N. 40° W. 76.6 ft. Open & find  
"C I" scribe & reverse.  
No trace of S. W. BT.  
Set - Brass Cap at Cor.Mkd: County Surveyor's Office, 1966  
T26S R3W Int."L" DLC 45  
New BT's: 7" W.Oak S. 55° W. 28.2 ft. Mkd: Int.L DLC 45 CS BT.  
13" W.Oak N. 41° E. 13.5 ft. Mkd: Int.L DLC 45 CS BT.  
Note - Chisel 3" x 3" "X" on top of N. E. Wing Wall of Bridge  
over Buckhorn Creek. "X" bears S. 85° W. 101.6 feet.

FD OK PER BEUTZ  
1-89 M 107-46

148

1/4 Corner to Sections 32 and 33.  
Found - Basalt Stone 8x9x24", firmly set in mound of stone,  
as recorded in Ren. #18, from which Cole's BT's:  
Orig. 36", now 60" Pine S. 78° E. 149.2 ft., burned Snag,  
Open, badly rotted, no scribe found, possibly bark scribed.  
No trace of B.Oak to N. W.  
Set - Brass Cap in place of Stone 12" in ground & build mound  
of stone around Pipe & Mkd: County Surveyor's Office, 1966  
T26S R3W 1/4 S 32/S 33.  
New BT's: 10" Cedar S. 47° W. 29.1 ft. Mkd: 1/4 S32 CS BT.  
12" Pine S. 34° E. 6.8 ft. Mkd: 1/4 S33 CS BT.

149

S. E. Corner DLC #38.  
Found - 10x12x18" Stone 14" underground at corner location ,  
no marks found. See Ren. #33.  
18", now 20", W.Oak S. 33 3/4° E. 289.1 ft.(center) shows  
scars of being chopped out.  
48" W.Oak N. 14 1/2° E. 326.6 ft.(not 322.9 ft.), Now Stump,  
broken off, scribe visible on unhealed face. Ren. #52.  
Set - Brass Cap flush with ground, mkd: County Surveyor's  
T26S R3W S.E. Cor. DLC 38 Office, 1966  
New BT: 6" Ash N. 82° E. 189.4 ft. Mkd: S.E DLC 38 CS BT.  
Note - This corner lies 20 ft. S. of road & 46.9 ft. S. of the  
S. W. Corner DLC #40. No trace of 3/8" Ir. Rod set  
by Frear, See Ren. #52.

150

S. W. Corner D. L. C. No. 40.  
Found - 1" I. P. 16" underground & 8x14x18" Stone Mkd: "40",  
recorded in C.S. File No. 47/63. - Ren. #51  
18", now 20", W. Oak S. 32° E. 333.2 ft.(center) partial  
scribe visible on rotting face.  
48" W.Oak, now stump, broken off, N. 17 1/4° E. 282.5 ft.,  
(not 277.5 ft) scribe visible on unhealed face. Ren.#51.  
Set - Brass Cap, flush with ground, Mkd: County Surveyor's  
T26S R3W S.W. Corner DLC 40 Office, 1966  
New BT: 21" W.Oak N. 10 1/2° E. 311.9 ft. Mkd: SW DLC 40 CS BT.  
Note - This corner lies on N. edge of Road, 46.9 ft. N. of the  
S. E. Corner DLC #38.  
No trace of 3/8" I. R. set by Frear.

Vernon "Ray" Tracy  
Mike Stone - J. Layne - Jack Heritage  
February 1966  
C. S. File No. 54/7