

Douglas County Surveyor's Record of
Government Corners Renewed

T. 26 S. T. S. R. 3 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97401

151

$\frac{1}{4}$ Corner to Sections 33 and 34.
Found - Orig. 28", now 48", Cedar N. 78° E. 103.0 ft. Open &
shows " $\frac{1}{4}$ " S" scribe.
No trace of Orig. Laurel to N. W.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1966
T26S R3W S33/S 34
New BT's: 14" Cedar N. 16° W. 22.2 ft. Mkd: $\frac{1}{4}$ S33 CS BT.
12" W. Fir N. 23° E. 50.7 ft. Mkd: $\frac{1}{4}$ S34 CS BT.
Note - This corner lies on N. E. Slope 12 ft. S. of fence remnants,
course E - W.

RE-RENEWED. SEE CORNER NO. #227

152

$\frac{1}{4}$ Corner to Sec. 7, R3W. & Sec. 12, R4W.
Found - Very old, squared Post showing partial scribe, "12" & " $\frac{1}{4}$ ". Ren. #14
1" I. Pipe at approximate corner location, unrecorded.
No trace of Original BT's.
Eppstein's BT's., See Ren. #14, are now stumps, as follows:
30" W. Oak Stump S. 82 $\frac{1}{2}$ ° W. 101 ft., badly burned, no scribe found.
14" W. Oak Stump N. 34 $\frac{1}{2}$ ° E. 97.7 ft., sawed stump & log show traces
of old faces, badly rotted, no scribing.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1966
T26S $\frac{1}{4}$ R4W S 12/S 7 R3W
New BT's: 8" D. Fir N. 42 $\frac{1}{2}$ ° E. 170.0 ft. Mkd: $\frac{1}{4}$ S 7 CS BT.
14" W. Oak N. 56° W. 145.8 ft. Mkd: $\frac{1}{4}$ S12 CS BT.
Note - This corner lies in N. - S. Fence.

153

$\frac{1}{4}$ Corner to Sec. 31, T26-3W. & Sec. 6, T27-3W.
Found - 1 $\frac{1}{2}$ " O.D. Iron Pipe at Fence Corner, See Ren. 12A, T27-3W.
18", now 26", D. Fir N. 31 $\frac{1}{2}$ ° E. 66.0 ft. (face), shows very good,
upper & lower scars. Do not open.
Stump hole to S. E., probably other BT.
New BT: 6" D. Fir S. 58° W. 16.5 ft. Mkd: $\frac{1}{4}$ S6 CS BT.
Note - This corner lies at fence corner with fences S - E & W. and
40 feet west of creek, course N.

154

Sec. Cor. to Secs. 32 & 33, T26-3W. & Secs. 5 & 4, T27-3W.
Found - 1958 Cadastral Brass Cap mkd. for corner & " $\frac{3}{4}$ " I. Road alongside
and set in a mound of stone.
All Co. Surv. BT's., recorded Ren. #46, are stumps or snags:
6" Cedar N. 85 $\frac{1}{2}$ ° E. 47.5 ft., now snag, shows scribe.
16" Cedar S. 14° E. 62.0 ft. Alive & Healthy, scribe visible.
17" Cedar S. 13 $\frac{1}{2}$ ° W. 58.1 ft. Alive & scribe vis. on partially healed
face.
22" Cedar N. 84° W. 220.4 ft., turned out, scribe visible.
Orig. Laurel to S. E. & Oak to S. W. Still Alive.
New BT's: 10" W. Oak N. 53° E. 53.9 ft. Mkd: T26S R3W S33 CS BT.
7" Cedar N. 83° W. 159.8 ft. Mkd: T26S R3W S32 CS BT.

155

$\frac{1}{4}$ Corner to Section 33, T26-3W. & Sec. 4, T27-3W.
Found - 1958 Cad. Brass Cap mkd. for corner.
60" D. Fir N. 75 $\frac{3}{4}$ ° W. 101.0 ft. Alive, scribe visible-pitched face.
67" Cedar S. 48 $\frac{3}{4}$ ° W. 369.6 ft., now broken snag 12 ft. high,
shows " $\frac{1}{4}$ " S3 BT", should be "S4".
New BT: 5" Laurel S. 87° E. 119.2 ft. Mkd: $\frac{1}{4}$ S 4 CS BT.
Note - This corner lies approximately 100 ft. East of bottom of
small draw, course N.

156

West 1/16 for Sec. 34, T26-3W. & Sec. 3, T27-3W.
Found - 1958 Cad. Brass Cap Mkd: "W 1/16 S34 - S 3, 1958.
6" Cedar S. 32° W. 25.1 ft. Slash piled on backside of tree,
scribe visible, BT. appears to be dying.
8" D. Fir S. 25 $\frac{1}{2}$ ° E. 9.9 ft., Blaze nearly healed over. Alive, good con
New BT: " Cedar N. 24° W. 35.0 ft. Mkd: W 1/16 S34 CS BT. /condition.
Note - This corner lies on steep, east slope, Brass Cap just below
large root of Fir Tree.

Vernon "Ray" Tracy
Mike Stone & Jack Heritage
February 1966
C. S. File No. 54/7