

Douglas County Surveyor's Record of
Government Corners Renewed

T. 26 S. T. S. R. 3 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

157

Sec. Cor. to Secs. 33 & 34, T26-3W. & Secs. 4 & 3, T27-3W.
Found - 1958 Cadastral Brass Cap mkd. for section corner.
13" Cedar N. $32\frac{3}{4}^{\circ}$ E. 31.0 ft. scribed T26S R3W S34 BT.-Alive.
9" D.Fir S. $47\frac{1}{4}^{\circ}$ E. 9.9 ft., scribe visible on pitched face.
10" D.Fir S. 68° W. 11.2 ft., pitched & almost healed blaze.
11" D.Fir N. 45° W. 11.2 ft., down & dead, scribing visible.
New BT: 9" D. Fir N. $18\frac{1}{2}^{\circ}$ W. 35.5 ft. Mkd: T26S R3W S33 CS BT.
Note - This corner lies approximately 120 ft. east of logging road,
course N.E. & S.W. in young Fir, Cedar & Laurel.

158

Sec. Cor. to Secs. 35 & 36, T26-3 and Secs. 2 & 1, T27-3.
Found - 1958 Cadastral Brass Cap Mkd: & BT's. as follows:
20" Fir N. $51\frac{1}{2}^{\circ}$ E. 43.6 ft. Alive & in good condition,
nearly healed blaze.
12" Cedar S. $73\frac{1}{2}^{\circ}$ E. 58.6 ft., Alive & in good condition.
(Recorded as S. $73\frac{1}{2}^{\circ}$ W.)
20" D.Fir S. $30\frac{1}{4}^{\circ}$ W. 40.3 ft. Alive & in good condition.
13" D. Fir, uprooted & dead, N. 34° W. 38.9 ft.
See Ren. # 16, T27-3W. for BT's. mkd. in 1936, now stumps
and snags.
New BT: 18" Cedar N. 45° W. 25.3 ft. Mkd: T26S R3W S35 CS BT.
Note - Corner lies in swampy area.

159

$\frac{1}{4}$ Corner to Sections 7 and 18.
Found - Brass Cap at Cor. Mkd: County Surveyor's Office, Ren. #69,
and Stumps of BT's., as recorded, as follows:
12" W.Oak N. 69° W. 65.8 ft., burned, no scribe.
12" W.Oak S. $11\frac{1}{2}^{\circ}$ W. 77.0 ft., shows "18 CS" Reverse.
New BT: 6" D. Fir S. 62° W. 40.0 ft. Mkd: $\frac{1}{4}$ S18 CS BT.
No trees to North.
Note - Corner lies 30 ft. North of small creek, flowing S.E.

160

$\frac{1}{4}$ Corner to Sec. 4, T26 and Sec. 33, T25S.
Found - 1943 GLO Brass Cap for corner & following BT's:
Orig. 42" D. Fir S. 85° E. 114.2 ft. (face) Prev. opened,
face pitched over.
12", now 18" D. Fir N. $52\frac{3}{4}^{\circ}$ W. 17.8 ft., shows very good scar,
we do not open.
12", now 14" D. Fir S. $10\frac{3}{4}^{\circ}$ W. 10.6 ft., shows good scar,
fence wire wrapped around BT & grown over.
New BT: 9" D. Fir S. 51° W. 22.3 ft. Mkd: " $\frac{1}{4}$ S 4 CS BT".

161

Sec. Cor. to Secs. 4 & 5, T26 and Secs. 32 & 33, T25.
Found - 1943 GLO Brass Cap Mkd. & BT's., as follows:
Orig. 50" Fir N. 25° E. 15.8 ft., bark scribed, Alive.
Only rotted remnants left of other Orig. BT's.
Find BT's. as recorded in Ren. #13, T25-3, as recorded.
7", now 10" Yew N. 20° W. 17.8 ft. Alive, scribe visible on
partially healed face.
8", now 13" Yew N. $37\frac{1}{2}^{\circ}$ E. 35.6 ft. Alive, scribe visible on
partially healed face.
50" Fir Stump S. 76° E. 48.2 ft., scribe visible on face.
8", now 11" Yew S. 62° W. 9.9 ft. Alive, scribe visible on
partially healed face.
New BT: 18" W. Fir S. 22° E. 44.6 ft. Mkd: T26S R3W S 4 CS BT.
Note - Brass Cap lies in E. - W. Fence 76 feet West of fence corner.

162

$\frac{1}{4}$ Corner to Sec. 3, T26S. and Sec. 34, T25S.
Found - 1943 GLO Brass Cap mkd. & BT's. as follows:
Orig. 16" R. Cedar S. 17° W. 2.6 ft., shows old scar.
54", now 56" D. Fir N. 15° W. 15.2 ft., shows good scar. #206
5", now 6" Yew Stump S. 88° E. 10.5 ft., shows "18 CS BT"
on unhealed face.
New BT's: 6" Yew N. 10° E. 25.1 ft. Mkd: " $\frac{1}{4}$ S34 CS BT".
16" R. Cedar S. 6° E. 31.4 ft. Mkd: $\frac{1}{4}$ S 3 CS BT.
Note - This corner lies 24 ft. East of small creek, course S. E.

Vernon "Ray" Tracy
Mike Stone & Jack Heritage
February 1966
C. S. File No. 54/7