

**Douglas County Surveyor's Record of
Government Corners Renewed**

T. 26 S. T. S. R. 3 W. R. W. W. M.

KOIKE-CHAPMAN CO., EUGENE, ORE. 21681

163

Sec. Cor. to Secs. 6 & 5, T26-3 and Secs. 31 & 32, T25-3W.
 Found - 1943 GLO Brass Cap & Stumps of following BT's:
 Orig. 40" Fir Stump S. 60° W. 4.6 ft., fragmentary bark scribe visible
 60" Fir Stump N. 12 $\frac{3}{4}$ ° E. 42.9 ft., scribe & reverse visible.
 20" Fir Stump S. 58 $\frac{1}{2}$ ° E. 43.6 ft., burned "S" scribe visible on face.
 22" Fir Stump N. 66 $\frac{1}{2}$ ° W. 42.2 ft., badly burned, fragmentary scribe visible.
 New BT's: 7" D. Fir N. 23 $\frac{1}{2}$ ° E. 50.2 ft. Mkd: T25S R3W S32 CS BT.
 15" D. Fir N. 49° W. 130.4 ft. Mkd: T25S R3W S31 CS BT.
 No trees available to S.E. or S. W.
 Note - Brass Cap lies at fence corner, course E. - W. & S.

164

$\frac{1}{4}$ Corner to Sections 2 and 11. *SEE ALSO REN. #200*
 Found - Iron Rod & BT's, as recorded in Ren. #54 & #113, as follows:
 12", now 20" R. Fir S. 26° W. 55.4 ft. Both blazes healed. Do not open.
 18", now 24" R. Fir N. 78 $\frac{1}{2}$ ° E. 26.5 ft., Both blazes healed. Do not open.
 Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1966
 T26S $\frac{1}{4}$ $\frac{S}{S}$ $\frac{2}{11}$ R3W
 (We build mound of Stone around Pipe)
 Note - Corner lies in old fence line running N. 10° W. - S. 10° E.
 All BT's. in good condition.

165

N. W. Corner D. L. C. No. 42.
 Found - 1 $\frac{1}{4}$ " Steel Shaft by Roberts in 1911, *See Ren. #1.*
 No trace of Original BT's.
 Measure from the $\frac{1}{4}$ corner of Sections 18 & 19, 443.5 ft. as recorded in Orig. DLC field notes & find that it checks within less than a foot.
 Set - Brass Cap flush with ground & Mkd: County Surveyor's Office, 1966
 N.W. Corner D.L.C. $\sqrt{42}$ T26S R3W
 Brass Cap lies on N. edge of asphalt Street course E. & W.
 No BT's. available, we use the following bearing objects:
 Power Pole bears S. 14° W. 38.8 ft., Pole # Copco B9673.
 S.W. Corner of imitation brick house bears N. 10° W. 8.1 ft.
 N.W. corner of concrete sidewalk 4.0 ft. wide bears S. 47° E. 72.5 ft.
W. U.R.T.

166

N. W. Corner D. L. C. No. 43.
 Found - Stumps of BT's., as recorded in Ren. # 8, as follows:
 12", now 16" Fir N. 53° E. 3.5 ft., shattered stump, No scribing.
 12", now 24" Fir S. 24° E. 17.0 ft., chop out "B" scribe & reverse.
 No trace of Original Bearing Trees.
 Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1966
 T26S R3W N. W. Cor. DLC $\sqrt{43}$
 New BT's: 10" W. Oak N. 32° E. 51.1 ft. Mkd: N.W. DLC 43 CS BT.
 8" W. Oak S. 27 $\frac{1}{2}$ ° W. 49.7 ft. Mkd: N.W. DLC 43 CS BT.
 Note - Corner lies at fence corner, course S. and E.

167

Wit. Cor. S. W. Corner DLC No. 46.
 After diligent search, we fail to find any trace of original S. W. Corner DLC #46. The actual corner would fall in cemetery. From the tie to N.W. corner DLC 43 in the original field notes, being 3 $\frac{1}{2}$ chs. or 231.0 ft. west of the N. W. Corner DLC 43, we measure 185 ft & Set - Wit. Cor. in the East fence of the cemetery, 46.0 ft. East of actual corner which falls 46.0 ft. inside cemetery for Wit. Cor.
 Brass Cap at Cor. Mkd: County Surveyor's Office, 1966
 T26S R3W Wit. Cor. SW DLC 46 $\sqrt{46}$ 46 ft. to Cor.
 New BT's: 19" D. Fir S. 10 $\frac{1}{2}$ ° E. 81.5 ft. Mkd: W.C. SW DLC 46 CS BT.
 26" D. Fir N. 17° E. 18.0 ft. Mkd: W.C. DLE 46 CS BT.

168

N. E. Corner D. L. C. No. 46.
 From the $\frac{1}{4}$ Cor. of Secs. 19 & 20, *See Ren. #75*, we measure South 4.86 chains, 320.8 ft., which is the record bearing & distance in Orig. DLC Notes for the beginning corner of DLC #46.
 Found - 14"x10" Stone & faint "4" mkd. on top. Orig. Notes call for Stone to be 12" x 15". Corner falls at fence corner, fences N-S-W.
 (continued over)

Vernon "Ray" Tracy
 Mike Stone & Jack Heritage
 February and March 1966
 C. S. File No. 54/7

RE-RENEWED SEE CORNER #232