

Douglas County Surveyor's Record of
Government Corners Renewed

T. 26 S. T. S. R. 3 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

(continued)

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1966
T26S R3W N.E. Cor. DLC 46/7

New BT's: 10" W. Oak S. 89° W. 92.2 ft. Mkd: N.E. DLC 46 CS BT.
11" W. Oak N. 34° W. 109.6 ft. Mkd: N.E. DLC 46 CS BT.

169

Found Wit. Cor. to $\frac{1}{4}$ Corner Sections 17 and 16.

Found - $\frac{3}{4}$ " I. Rod for Corner in N. - S. Fence in small creek under
a pile of logging debris. Corner recorded Ren. #66.

10", now 16" Fir N. 64 $\frac{1}{2}$ ° W. 12.0 ft., now stump, open
& find "S2 scribe & reverse. See Ren. #29.

8", now 8" Fir S. 8° W. 17.0 ft., now stump, See Ren. #66.

21" I. Cedar N. 30 $\frac{1}{2}$ ° W. 59.6 ft., shows " $\frac{1}{4}$ S17CS" on
partially healed blaze. No record this BT, apparently
marked in 1958 from information on tag.

Set - Wit. Cor. 55.0 ft. N. of True Corner, Brass Cap Mkd:
County Surveyor's Office, 1966

T26S R3W $\frac{1}{4}$ S 17/S 16 55 ft. S. to Corner.

New BT's: 21" I. Cedar S. 83° W. 32.5 ft. Mkd: W.C. $\frac{1}{4}$ S17 CS BT.

9" D. Fir N. 27 $\frac{1}{2}$ ° E. 39.2 ft. Mkd: W.C. $\frac{1}{4}$ S16 CS BT.

Witness Corner lies in N. - S. Fence.

170

Sec. Cor. to Secs. 19 & 30, T26-3W. & Secs. 24 & 25, T26-4W.

Found - Co. Brass Cap as recorded in Ren. #77, set in 1959.

16" Laurel N. 4° W. 223.0 ft. alive & almost healed blaze.

3" Laurel N. 42° E. 37.0 ft., blaze healed, alive.

12" R. Fir S. 68° E. 125.8 ft. alive, scribe visible on
partially healed blaze.

New BT: 5" D. Fir S. 8° W. 21.4 ft. Mkd: S25 CS BT.

Note - Corner lies at fence corner, fences N. & E.

No trace of Orig. BT. called for in Ren. #77 as area
has been cleared & burned.

171

$\frac{1}{4}$ Corner to Sections 28 and 33.

Found - Orig. 6", now 15" W. Oak S. 15° W. 152.5 ft. Chopped
out reverse scribe "4" & partial "S.", face apparently
rotted before blaze healed. Ring count reveals 100+.

No trace other Orig. BT.

Set - Brass Cap at Cor. Mkd: County Surveyor's T26S R3W $\frac{1}{4}$ S 28
Office, 1966 S 33

New BT's: 10" D. Fir S. 49° W. 80.0 ft. Mkd: $\frac{1}{4}$ S33 CS BT.

8" R. Cedar N. 33° W. 15.0 ft. Mkd: $\frac{1}{4}$ S28 CS BT.

Note - This corner lies on S.E. slope approximately 400 ft.
North of Little River Road.

172

$\frac{1}{4}$ Corner to Sections 34 and 35.

Found - 1" Steel Shaft at Corner, Fences N. - S. & W.

No trace of Orig. BT's. nor BT's. recorded in Ren. #96.

Obtained affidavit from J. C. Livingston, stating he was present
when shaft was set by Ben. B. Irving in 1932 on Cooper Survey,
See C.S. File No. 37/78. See signed affidavit in C.S. File 54/7.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1966
T26S R3W $\frac{1}{4}$ S 34/S 35

(Set B.C. alongside shaft in Mound of Stone.)

New BT's: 16" Pine N. 12° E. 70.3 ft. Mkd: $\frac{1}{4}$ S35 CS BT.

7" Cedar N. 2° W. 18.1 ft. Mkd: $\frac{1}{4}$ S34 CS BT.

Note - Corner lies at fence corner above described, on barren,
rocky hillside, sloping S. W.

Vernon "Ray" Tracy
Mike Stone & Jack Heritage
March 1966
C. S. File No. 54/7

FD OK 4/86
BY DOLAN
PER M100-67