

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 26 S. T. S. R. 3 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

173

FD. BC.  
BENTZ 12-91  
M 114-31

FD. OK 2/85  
G. BAUGHMAN  
M 90-65

$\frac{1}{4}$  Corner to Sections 17 and 20  
Found - Old, Auto Spring for corner & BT's. as recorded in Ren. #44 & #67.  
Orig. 20", now 28" B. Oak S. 3° E. 10.0 ft., scribe marks  
nearly rotted away.  
24" Fir N. 69° W. 44.0 ft., scribe visible on unhealed blaze,  
now stump.  
10", now 15", D. Fir N. 68° E. 23.5 ft., alive & in good condition,  
Blazes healed, Do not open.  
 $\frac{1}{2}$ " Iron Bolt bent over.  
Set - Brass Cap at Cor. Mkd: County Surveyor's T26S R3W  $\frac{1}{4}$  S 17  
Office, 1966  $\frac{1}{4}$  S 20  
(Set alongside of auto spring. Corner lies 34 ft. West  
of N. - S. Fence.)

Vernon "Ray" Tracy  
Mike Stone & Jack Heritage  
March 1966  
C. S. File No. 54/7

174

Sec. Cor. to Secs. 18 & 19, T26-3W. &  
Secs. 13 & 24, T26-4W.  
Found - 1" Iron Pipe, 3 ft. high, set in Mound of Stone. See C.S. 7/54  
No trace of BT's., but do find stools of Myrtle at  
approximate locations of Original BT's. In searching through field  
books & map made by R. W. Fenn, C.S. in 1903, we find reference to mound  
of stone & I. Pipe at the location of this corner. Map in possession  
of W. H. L. Osborne & field books are to be turned over to Co. Surveyor.  
Since this corner has been used for 60 to 70 years we set:  
Set - Brass Cap alongside existing Pipe in Mound of Stone & Mkd:  
County Surveyor's T26S R4W S 13 | S 18  
Office, 1966 S 24 | S 19 R3W  
New BT's: 13" Myrtle N. 82° E. 45.5 ft. Mkd: T26S R3W S18 CS BT  
(This tree in clump of two)  
8" Myrtle S. 60° E. 34.9 ft. Mkd: T26S R3W S19 CS BT.  
7" Myrtle S. 70° W. 29.0 ft. Mkd: T26S R4W S24 CS BT.  
(This tree in clump of seven)  
7" Myrtle N. 73° W. 12.0 ft. Mkd: T26S R4W S13 CS BT.  
March 8, 1966

RE-NEWED, SEE CORNER NO. #226

Vernon "Ray"  
Tracy &  
Crew  
C. S.  
File  
No. 54/27

175

$\frac{1}{4}$  Corner to Sec. 2, T26-3W. & Sec. 35, T25-3W.  
Found - 1943 GLO Brass Cap mkd.  
50", now 50" D. Fir Stump S. 51° W. 35.6 ft., partial face  
visible. "W" nail added.  
22", now 26" W. Fir, down, N. 2 $\frac{1}{2}$ ° E. 15.2 ft., face burned, no scribe.  
Weyerhaeuser BT's. as recorded Ren. #121, as follows:  
18" W. Fir N. 20° E. 12.9 ft. (center) "W" nail at base, we scribe  
 $\frac{1}{4}$  S35 CS BT.  
38" Cedar N. 52° W. 42.0 ft. (to "W" nail)  
New BT: 6" Hemlock S. 25° W. 68.7 ft. mkd.  $\frac{1}{4}$  S 2 CS BT."  
Note - This corner lies on E. - W. cutting line, cut off to south.  
June 29, 1966

Vernon "Ray"  
Tracy &  
Crew  
C.S. File  
No.  
54/7

176

$\frac{1}{4}$  Corner to Sections 12 and 13.  
Found - Mound of Basalt Stone & remnants of old squared post.  
Orig. 60", now 68" Sugar Pine, S. 20° E. 21.1 ft. Alive. Does  
not show scar, probably bark scribed & bark badly flaked off.  
Orig. 40", now 46" Fir Stump N. 52° E. 31.0 ft. Old bark blze &  
frag. bark scribe, Weyerhaeuser reported found in 1957, C.S. 53/115.  
Set - Brass Cap at Cor. Mkd: County Surveyor's T26S  $\frac{1}{4}$  S 12 R3W  
Office, 1966  $\frac{1}{4}$  S 13  
New BT's: 8" W. Fir S. 30° W. 9.0 ft. mkd.  $\frac{1}{4}$  S13 CS BT.  
8" W. Fir N. 30° W. 16.4 ft. mkd.  $\frac{1}{4}$  S12 CS BT.  
Ed. OK 12/30/77 - R. KIMBERLING - SURVEYOR'S OFF. C.S. 59/42  
MICROFILM TO HERE 10/67 June 20, 1966

James W.  
Byron, Dep.  
For Doug. Co.  
10/24/60  
M 19 - 76

Wit. Cor. for S 1/16 Corner Sections 2 and 1.  
Set - 3/4" Iron Rod With. Cor. S1/16 Secs. 2 & 1, N. shoulder of N. Umpqua Hwy.  
Chisled Line on concrete curb in front of Mac's Place.  
New BT: 26" R. Fir bears N. 37° W. 83.0 ft. mkd. S1/16 S2 CS BT W.C.  
October 24, 1960

RE-NEWED, SEE CORNER NO. #249