

Douglas County Surveyor's Record of  
Government Corners Renewed

T 26

T. S.

R 3

R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

C O N T. - - -

Douglas County  
Surveyors Office  
Randall Smith  
S. J. Flause  
May 18, 1988  
C.S. 62/52

(1/4 Cor. 11 and 12)

12" now 36" dia. S. Pine with an axe bark blaze "M" and a small healed lower blaze, bears N. 59°W., 54.8 ft. (Record N.59°W., 53.5 ft. is a possible face measurement. Source unknown.

5" now 8" dia. Yew with a partially healed double blaze, upper blaze opened no scribing found, lower blaze has a Weyerhaeuser W nail set in it. Bears S. 16°E., 29.7 ft. (agrees with record) Source unknown.

Last two trees noted as source unknown are possible BTs by Marion D. Hale, date 1946, see C.S file No. 53/115.

New BTs - 9" Doug.fir double blazed and scribed "1/4 S11 CS BT" bears S.36°W., 17.5 ft.

8" D. fir double blazed and scribed "1/4 S12 CS BT" bears N.59½°E., 19.5 ft.

248

Douglas County  
Surveyors Office  
Randall Smith  
Stephen Flause  
August 10, 1989  
C.S. 64/1

Witness Corner for South 1/16 Section 1 and 2

Found - Nail in asphalt with red paint (source unknown) A strong metal reading is taken at point of nail. Asphalt is not dug up to see 3/4" iron rod set in Ren. #177

True 1/16 Cor. perpetuated with a brass cap/iron pipe monument in BLM's 1963 dependent resurvey not found; corner falls in rip rap between Hwy 138 and the North Umpqua River.

From Ren. #177: (B.O. and BT go to Wit. Cor.) (Nail set south of witness Corner not found.)

Chisled line on concrete curb, now part of foundation of restaurant, faint red paint visible, can feel line in concrete under bottom edge of building, bears N.1¼°E., 55 ft. (agrees with record)

26" now 33" dia. D. fir with a fully healed double blaze bears N.37°W., 83.0 ft. (agrees with record)

New Accessories:

2 ft. x 3 ft. concrete storm drain box, we chisle a 3" "+" on easterly concrete corner, "+" bears N.87 3/4°W., 62.6 ft.

20 ft. x 2½ ft. rounded ends concrete pad with an existing 3/4" iron rod, 1.2 ft. from west end, in middle, 3/4" iron rod bears N.25°E., 41.6 ft.

Witness Corner lies under AC at south edge of Dave and Ellen's (formerly Mac's Place) Restaurant parking lot.

8/10/89

1/4 Corner for Sections 25 and 36

Found - 1981 3¼" BLM brass cap on a 2½" O.D. iron pipe, protruding 3" above ground.

37" now 37" dia. down and out of psition D. fir with an unhealed single blaze scribing visible "1/4 S26 BT", root hole bears N.51°W., 11.6 ft. (agrees with record)

14" now 14" dia. D. fir with a fully healed single blaze bears S.20°E., 26.7 ft. (Rec. S.22½°E., 26.7 ft.)

New BTs - 13" dia. D. fir double blazed and scribed "1/4 S36 CS BT" bears S.84°W., 9.8 ft.

6" dia. I. cedar double blazed and scribed "1/4 S25 CS bT" bears N.45°W., 37.8 ft.

6" dia. I. Cedar double blazed and scribed "1/4 S25 CS BT" bears N.48½°E., 37.1 ft.

Corner lies in a east-west cut line approx. 300 ft. northeast of end of road.

1/19/90

Douglas County  
Surveyors office  
Randall Smith  
Stephen Flause  
C.S. 64/5  
Jan. 19, 1990

249

250

251