

County Surveyor's Record, Douglas County, Oregon

T 26 S, R 4 W.

WEST COAST PRINTING & BINDING CO., PORTLAND 13735

CHAINS

Section corner to secs. 29, 30, 31 and 32. Found - Hub & Tack at cor. under E-W fence, and all trees alive & in good condition as renewed previously. (No date). All check for bearings and distances. Blazes have grown over. I did not cut out. Set 1" Iron Pipe with Brass Cap mkd. 30/29 31/32 T 26 S, R 4 W., County Surveyors Office, 1955. Va. 21 1/4°.

46

REN #13

Section corner to secs. 28, 29, 32 & 33. Found - Sandstone rock 8" x 12" x 15" at cor. Also both trees as renewed previously. The Cedar checks for bearing and distance. The Fir checks for bearing only measures 267.2 ft., recorded 262.2 feet. Set 1" Iron Pipe with brass cap mkd. 29/28 32/33 T 26 S, R 4 W., Sec. cor. 1955; County Surveyors Office. Placed sandstone rock alongside of Brass Cap. Blazed and Scribed 12" W. O., N. 2 1/2° W., 115.8 feet, S 29, T 26 R 4 CS BT.

47

REN #14

Section corner to secs. 21, 22, 27 and 28. Found - Original B.T. - 18" B. O., N. 42° W., (now 35") which I open and find scribe S 21. Also I find orig. 16" W. O. (Now 24"), shows old blaze center rotted, no scribing visible. Make record distance intersection to locate corner. The Orig. 18" B. O. now bears N. 45° W. The Orig. 16" W. O. now bears N. 46° E. Set 1" Iron Pipe Brass Cap Mkd. 21/22 28/27 T 26 S R 4 W County Surveyors Office 1955. Blaze & scribe: 18" R. Fir, N. 87° E., 14.0 ft. S 22 T 26 S, R 4 W., CS BT. 14" R. Fir, S. 33° W., 6.3 feet, S 28 T 26 S R 4 W., CS BT. 10" W. O., S. 62° E., 32.7 feet, S 27 CS BT. 12" R. Fir, N. 25° W., S 21 T 26 S, R 4 W., 31.6 feet, CS BT.

48

Section corner to secs. 13, 14, 23 & 24. Found 3/4 inch Iron Rod at corner. The S. E. & N. E. BTs as renewed previously, alive and in good condition. Blazed and scribed: 14" B. O. at wire fence corner scribed S 23 CS BT above top wire. BT at base of tree, bears S. 78° W., 70.7 feet. 7" W. O., N. 17 1/2° W., 186.0 feet, S 14 CS BT.

49

RE-RENEWED, SEE CORNER NO. #118

Section corner to secs. 27, 28, 33 & 34. This sec. corner was renewed by cole in 1923 from stone set by Germond and calls that had been mistakenly copied from orig. notes. I find stool of ash on right bank of stream which Cliff Agee states is the location of the original B. T., a 15" Ash, S. 51° E., 85.8 feet. The 18" now 30" W. O. Cole scribed is standing and in good condition and shows good blaze. We do not open. Using coles distance and bearing to his corner checks his dist. and bearing to stool of Ash on which cole states he found scribing. I use stool of Ash, S. 51° E., 85.8 feet to locate corner. Set 1" Iron Pipe with Brass Cap mkd. County Surveyors Office, 1955, 28/27 33/34 T 26 S, R 4 W. Blazed and Scribed: 30" W. O., S. 22 1/2° E., 106.8 feet, mkd. T 26 S, R 4 W., S 34 CS BT. This is the same BT Cole scribed in 1923. 24" W. O., T 26 S, R 4 W., S 28 CS BT. No other trees available. Va. 21 1/4°.

50

REN #10

1/4 sec. corner to sec. 31 (T 26 S, R 4 W) and sec. 6 (T 27 S, R 4 W). Found - Both BTs Est. 40 years ago, more or less. Check for bearings and distances. Also found bottom of squared stake at corner. We cut out W. O. tree and scribing good - scribed 1/4 S. Ash alive and in good condition. Set 3/4 inch Iron Rod at corner 12 inches below surface. Blazed and Scribed: 15" W. O., S. 36° E., 48.0 feet, 1/4 S 31, T26S, R4W., CS BT. 12" W. O., N. 30° E., 103.6 feet, 1/4 S 6, T27S, R4W., CS BT.

51

Vol. 2 R 278

SEE REN #33

RE-RENEWED, SEE CORNER NO. #115

James W. Byron - Deputy County Surveyor
Ray Irving
John Fee
April, 1955.
C. S. File No. 46/122.