

Douglas County Surveyor's Record of
Government Corners Renewed

26 T. S. 4 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97196

James W. Byron, Dep. Co. Surveyor
John Fee
April 21, 1955.
C. S. File No. 46/122.

52
Sec. corner to secs. 14, 15, 22 and 23.
Found 14" W. O., S. $56\frac{1}{2}^\circ$ E., 276.3 feet, cut out with chip lying on ground at base of tree. Scribe marks are visible. *REN. No. 6*
Found 24" Ash shows old blazes, N. $62\frac{1}{2}^\circ$ W., 228.4 feet.
Set point at record bearings and distance.
Set brass cap mkd. County Surveyors Office, T 26 S, R 4 W, ~~21/23~~ ^{22/23} 1955.
From which
Ash, 12", bears N. 70° W., 256.3 feet dist. mkd. T 26 S, R 4 W, CS BT.
18" W. O., bears S. $12\frac{1}{2}^\circ$ W., 403.0 feet dist. mkd. T 26 S, R 4 W., S 22 CS BT.
18" W. O., bears S. $32\frac{1}{4}^\circ$ E., 237.0 feet dist., mkd. T 26 S, R 4 W., S 23 CS BT.
9" W. O., bears East 377.5 feet dist. mkd. T 26 S, R 4 W., S 14 CS. BT.
61.0 feet W. to F. line.

James W. Byron, Dep. Co. Surveyor
R. Irving
J. Fee
May 31, 1955
C.S. File No. 46/154

53
Renewed section corner to section 7, 12, 13, and 18. T26 S. R4W. & R3W.
Found:
3 BTs as renewed. (*SEE #13 IN T. 26-3*) *FOOK 6/86 BY DONALD BENTZ m 101-8*
The N.E. BT now 16 inch stump only. Scribed BT bears N 27° E. 25.1 feet.
The S.W. BT alive & in good condition bears 17° W. 22.4 feet.
Now 14 inch B.O. 22.4 feet shows blaze I do not cut out.
The S.W. now 20 inch stump only, rotted but shows blaze it bears 562° E. 54.1 feet. The N.W. BT burned.
Blaze & scribe 8 inch W.O. S 74° E. 84.2 feet S 18 CS BT.
Blaze & scribe 12 inch W.O. N. 48° E 15.9 feet 23 W. S 7 CS BT.
Blaze & scribe 13 inch W.O. N. $73\frac{1}{2}^\circ$ W. 15.7 feet R 4W. S 12 CS BT.
Set Brass cap marked County Surveyors Office, 1955
 $\frac{12}{13} \frac{7}{18}$ T 26 S. R 3W.

James W. Byron
M. Godfrey
S. Bilow
For Harry Young
June 2, 1958
C.S. File No. 49/98

54
 $\frac{1}{4}$ Section Corner to Sections 13 & 24.
Found - Both BT's. as recorded by Eppstein., good scribing visible.
Find Auto Spring 12" under surface. *SEE COR #9*
BT's check for bearing & distance.
Set Brass Cap alongside Auto Spring Mkd: $\frac{1}{4}$ S13 T26S R4W County
S24 Surveyor's Office, 1958
I Chisel B. O. in Concrete on N. E. Corner of Shed & Barn, bears
N. 78° W. 131.0 ft.
Note: See Sketch in file.

James W. Byron, Deputy
Milo Godfrey
S. A. Bilow
December 9, 1958
C. S. File No. 49/125

55
Section Corner to Sections 7, 8, 17, & 18.
Found - Orig. 15", now 24" B. Oak N. 2° E. 52.1 ft., I open & find good scribing "S8".
Old Stump Holes that check bearing & distance for Orig.
N.E. & N.W. BT's.
No trace of Orig. S.W. BT.
Set Brass Cap at Corner Mkd: T26S R4W $\frac{S 7}{S 18} \frac{S 8}{S 17}$ County Surveyor's Office, 1958.
New BT's: 8" W. Oak bears N. 27° E. 57.0 ft. scribed S 8 T26S R4W CS BT.
15" B. Oak bears N. 59° W. 90.8 ft. scribed S 7 T26S R4W CS BT.
12" B. Oak bears S. $19\frac{1}{2}^\circ$ W. 83.0 ft. scribed S18 T26S R4W CS BT.
12" B. Oak bears S. 26° E. 11.3 ft. scribed S17 T26S R4W CS BT.
----- *REN. #55 #56* } FOUND O.K. JAN. '71 J.M.P.

56
Meander Corner to Sections 7 & 18.
Found - Orig. 7", now 15" W. Oak N. 52° W. 25.7 ft., I open & find good reverse scribing "BT".
No trace of Orig. S.E. BT.
Note: Corner at Edge of Bluff, I set Wit. Cor. 14 Ft. East.
Set Brass Cap at Wit. Corner Mkd. County Surveyor's Office, 1958
Wit. Cor. 14' West to MC $\frac{S 7}{S 18} \frac{7}{8}$ T26S R4W
Note: This M.C. 17.63 chains West of Sec. Cor. $\frac{18}{17}$.
New BT's: 15" W. Oak bears S. $25\frac{1}{2}^\circ$ E. 32.5 ft. scribed WC MC S18 CS BT.
15" W. Oak bears N. 30° W. 42.4 ft. scribed WC MC S 7 CS BT.