

Douglas County Surveyor's Record of
Government Corners Renewed

T. 26 S. T. S. R. 4 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

98

1/4 Corner to Sections 14 and 23.
Set - Brass Cap stamped: 1/4 Cor. 23/14 T26S, R4W
L. S. 544
Scribed BT's: 29" W.Oak bears N.29°W. 409.0 ft. scribed "1/4 Sec. 14 BT."
14" W.Oak bears S.31°45'W. 160.2 ft. scribed "1/4 Sec. 23 BT."

99

Exterior "L" D.L.C. No. 43
Set - Brass Cap stamped: Ext. "L" DLC 43 T26S, R4W
LS 544
BT's: 12" W.Oak bears N.14°30'E. 55.2 ft. scribed Ext. "L" DLC 43 BT.

100

S. E. Corner D. L. C. No. 40.
Set - Brass Cap stamped: SE Cor. DLC 40 T26S, R4W
LS 544
BT's: 9" Madrone bears South 1.7 feet, scribed SE DLC 40 BT.
10" B.Oak Clump bears N.66°15'W. 40.8 ft. scribed SE DLC 40 BT.

101

1/4 Corner to Sections 34 and 35. Witness Corner.
Witness Corner
Found - No trace of 1" Binder & Mound of Rocks, as corner falls in middle of cultivated pasture, See Ren. #12.
16", now 24" W. Oak, S.34°E. 72.6 ft., shows good scars.
7", now 13" W.Oak, S.34 3/4°W. 163.3 ft., opened for scribing "S".
Set - Brass Cap in Fence Line Mkd: County Surveyor's T 26 S R 4 W
Office W.C. 47' N. to 1/4
1971 S 34 / S 35
New BT's: 8" W.Oak S. 5° W. 40.4 ft. scribed "W.C. 1/4 S 34 CS BT".
8" W.Oak S.41°E. 25.5 ft. scribed W.C. 1/4 S 5 CS BT.
This Witness Corner lies in E - W Pasture Fence.

1/11/71

102

1/4 Corner to Sections 8 and 9.
Found - 18", now 32" W.Oak, N.54°E. 188.1 ft., opened for scribe "S".
15", now 27" W.Oak, N.60°W. 238.9 ft., shows faint scar. } Orig. BT's
Set - Brass Cap at Cor. Mkd: County Surveyor's T 26 S R 4 W
Office, 1971 1/4 S 8 / S 9
New BT's: 12" W.Oak S.4 1/2°W. 79.5 ft. scribed "1/4 S8 CS BT".
Rebld.& resbd: 32" W.Oak, Orig., N.54°E. 188.1 ft. scribed "1/4 S9 CS BT".

1/11/71

103

1/4 Corner to Sections 10 and 11.
Found - 3/4" Iron Pipe set by Boyer, All things check with M 4 - 71, CS 33/38.
7", now 36" W.Oak, N.54°W. 404.0 ft., tree shows old axe face,
I do not open, probably rotted out.
Set - Brass Cap at Cor. Mkd: County Surveyor's T 26 S R 4 W #726
(Alongside I.P.) Office, 1971 1/4 S 10 / S 11
New BT's: 13" W.Oak N.8 1/2°E. 117.0 ft. scribed "1/4 S11 CS BT".
8" W.Oak N.11 1/2°W. 135.5 ft. scribed "1/4 S10 CS BT".
This corner falls at fence corner, fence running S - E - W.

1/14/71

104

Interior "L" Corner D. L. C. No. 43.
Found - 14" D.Fir, now stump, N.48 1/2°E. 48.0 ft., opened for scribe "Int".
This corner lies about 20 ft. west of N - S fence line on west edge of roadway.
Ren. No. 8 calls for this corner to fall 511.5 ft. East of Section Corner to Secs. 13-14-23-24. I find 5/8" Iron Rod to be 541.0 ft. west of DLC. Cor.
Set - Brass Cap at Cor. Mkd: County Surveyor's T 26 S R 4 W
(Steel Fence Post Algd) County, 1971 Int. L D L C
New BT's: 36" B.Oak N. 1° E. 185.1 ft. scribed "Int. L DLC 43 CS BT".
13" Ash N.35°W. 141.7 ft. scribed "Int. L DLC 43 CS BT".

1/15/71

Don E. Garrett
For: Sterchi & Connine
December 1970 Map M 40 - 71

John M. Powell
W. Penley & J. Heritage
January, 1971
C. S. File No. 56/1

RE-RENEWED SEE CORNER NO. #121

FD OK 6/18/80 SURVEYOR OFFICE C.S. 6/1/11

FD OK PER BAUGHMAN RB, 6/3/110 2/90

SEE CONDITION REPORT IN C.S. 6/1/6 4/16/80