

Douglas County Surveyor's Record of
Government Corners Renewed

T 26 T. S. R 4 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Gary Langlitz, Surveyors Office
Peter Earle
Jan. 20, 1975
C.S. 57/17

109

N NW Corner DLC #52
Found - 5/8" I. R. set at the NNW cor. of DLC 52 by McLind from a survey dated July, 1973 and filed in the Douglas Co. Surveyors Office in map file M 50 - 32.
At the corner point we set a 1" x 30" I. Pipe with brass cap attached mkd.

COUNTY SURVERORS T 26 S
OFFICE
1975

NNW
DLC
52
R 4 W

We place the found iron rod alongside and set a steel fencepost with survey marke sign attached 1 ft. north of the corner.
There are no suitable trees near.

1/20/75

R. B. Kimberling
P. L. Earle
Aug. 2, 1977
C.S. 59/38

110

1/4 Corner for Secs. 15 and 22.
Found - A 1" Iron pipe with brass cap 8" above ground marked:
"County Surveyors Office" Ren. #81

T 26 S R 4 W

(See also M 13 - 40)

S 15
S 22

No trace of bearing trees but passed several 150 yr. old Oak trees in SW quadrant closer than 500 ft.

A 1/2" square iron rod bears N.27 1/2°W., 74.0 ft.

A 3/4" x 30" iron rod laying down and buried 0.5 ft. approx.

bears south 7.0 ft., 1.0 ft. south of fence line of County Rd.

New accessories:

Reset 3/4" x 30" iron rod 26" in ground, bears due west 14.0 ft. 1.5 ft. east of County R/W corner post, 0.8 ft. north of fence li

8/2/77

R. B. Kimberling
M. W. Cline
Doug. Co. Surveyors Office
Sept. 27, 1977
C. S. 59/40

111

Section corner for Secs. 16, 15 21 and 22.

Found - A 1" Iron pipe with top bent over and leaning south, 6" above ground. Top of iron pipe is 0.3 ft. NE of brass cap set from bearing trees on this renewal. See Ren. #83

A 10" now 13" Madrone bears N.66°W., 33.9 ft. with a well healed blaze.

A 7" now 8" Madrone is down, scribed "T26S R4W S21 CS BT". Stump hole bears S.70°W., 30.4 ft.

A 8" Fir stump bears N.52°E., 74.9 ft.

Set - 1" x 36" Iron pipe with brass cap 0.8 ft. above ground (from bearing trees) marked "Douglas County Surveyor" T 26 S R 4 W

1977

S 16 S 15
S 21 S 22

New BT's- A 8" White Oak bears N.88°E., 73.9 ft. double blazed and scribed "T26S R4W S15 CS BT".

A 8" Black Oak bears S.81°W., 50.1 ft. double blazed and scribed "T26S R4W S21 CS BT".

A 9" D. Fir bears S.2°E., 54.4 ft. double blazed and scribed "T26S R4W S22 CS BT".

Note: Corner is at fence corner E-W and South.

9/27/77

112

William Ruppert
PLS #866
For: Gamegan, Wilcox
and Weathers
-May 1978 RM 3 -15

1/4 Corner for Secs. 29 and 32.

Set - 1" x 30" Galv. steel pipe with 2 1/2" brass cap marked T26S R4W 1/4 S29 S32 PLS 866 1978.

5/78

113

Robert Wade
For: Dave Philipi
May 1, 1980
M 83 - 72

1/4 Corner west side of Section 31.

Set - By proportionate measurement - 5/8" iron rod. (See Ren. #73)

5/1/80

RE-RENEWED, SEE CORNER NO. #116

- OVER -