

Douglas County Surveyor's Record of
Government Corners Renewed

T 26

T. S. R 4

R. W. W. M.

FOKE-CHAPMAN CO., EUGENE, ORE. 97331

124

FD 11/90 M112-18

Douglas County
Surveyors Office
Randall Smith
Stephen J. Flause
Sept. 7, 1989
C.S. 64/1

Interior L, DLC #43

Found - A 1983 Douglas County 2½" dia. brass cap on a 1¼" x 36" long I.P. bent, laying on top of ground. Ren. #121
14" now 30" dia. 2 ft. high broken and rotted D. fir stump, no blazes or scribing seen, bears N.48½°E., 48.0 ft. (agrees with record.) Ren. #8
36" now 36" dia. B. Oak with a fully healed double blaze bears N.1°W., 185.1 ft. (Rec. N.1°E., 185.1 ft.) Ren. #104
24" now 32" dia. W. oak with a fully healed double blaze bears N.19°W., 179.8 ft. (Trv. N.18°W., 179.8 ft.) Ren. #121
13" Ash now depression with roots, bears N.35°W., 141.7 ft. (agrees with rec.) Ren. #104
DCSO BC/IP stamped T26S S14 S13 S23 S24 R4W 1981" protrudes 6" above ground in an east-west fence line., bears S.89°W., 537.8 ft. (Rec. 5/8" iron rod, west 541.0 ft. in Ren. #104; Section corner bears West, 511.5 ft. in Ren. #8; west 511 ft. M 6 - 3)
Set - Brass cap monument reset at the intersection of distances to bearing trees and a record bearing to Ren. #8 fir stump. 1983 DCSO BC/IP is straightened and set 10" below ground. The marks "RESET 1989" are added to brass cap.
No new accessories. Corner lies along west edge of gravel road.

9/7/89

Section Corner for Secs. 7 and 6; and Secs. 1 & 12 of T.26-5

125

Douglas County
Surveyors Office
Randall Smith
Terrie Franssen
June 26, 1990
C.S. 64/9

Found - A 2½" dia. 1964 DCSO brass cap on a 1¼" O.D. iron pipe protruding 14" above ground. BC/IP leans 6" north of plumb. Ren. #88
24" now 36" dia. B. Oak is down shows a previously opened blaze, no scribing visible. Root hole bears S.65°E., 372.9 ft. (rec. S.63°E., 372.9 ft.) Orig. BT.
18" now 20" dia. W. Oak with a fully healed double blaze, bears S.50°E., 322.8 ft. (agrees with record) Ren. No. 88
20" now a double trunked 2 ft. high D. fir stump with a 20" east and a 13" west trunk, no blazes or scribing visible, bears N. 81½°E., 320.0 ft. (agrees with rec.) Ren. No. 88
New BTs -A triple trunked W. Oak double blazed and scribed "T26S R4W S7 CS BT" on 14" northwest trunk, root crown bears S.64°E., 278.6 ft.
14" W. Oak double blazed and scribed "T26S R4W S6 CS BT" bears N.88½°E., 335.5 ft.
7" W. Oak double blazed and scribed "T26S R4W S7 CS BT" bears S.78½°E., 396.6 ft.
Corner lies 4 ft. south of an east-west running fence lines, and approx. 100 ft. east of a N'easterly - S'westerly bald grassy ridge.

6/26/90

1/4 Corner for Sections 10 and 11

126

Douglas County
Surveyors Office
Randall Smith
Stephen Flause
Aug. 28, 1990
C.S. 64/10

Found - A 1971 DCSO 2½" dia. brass cap on a 1¼" O.D. iron pipe protruding 12" above ground. Ren. No. 103
7" now 38" dia. W. Oak with a previously opened blaze, no scribing visible bears N.52°W., 404.6 ft. (Rec. N.54°W., 404.6 ft.) Original BT.
13" now 15" dia. W. Oak with a fully healed double blaze, bears N.8½°E., 117.0 ft. (agrees w/rec.) Ren. No. 103
8" now 11" dia. W. Oak with a fully healed single blaze, bears N.14 3/4°W., 135.5 ft. (Rec. N.11½°W, 135.5 ft.) Ren. No. 103
New BT - A multi trunk W. Oak double blazed and scribed "1/4 S11 CS BT" on 11" dia. west trunk bears N.42°E., 114.3 ft. to center of west trunk at base.
(See condition report (CS 61/6) for additional information.)

8/28/90

Fd B.C. 9/91
1991-0060
K. DeGeort