

Douglas County Surveyor's Record of
Government Corners Renewed

26

T. S.

5

R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

33

Section corner to secs. 11, 12, 13 and 14.

Corner renewed from original W. O. BT, N.33°E., 15.8 feet. (now 18 inches). We cut out - center rotted but old face in fair condition. Some scribe marks visible - letter S visible. We also cut out 2 foot W. O., N.48°W., 27.7 feet and find original blaze scribed 26S in good condition. Both trees alive and check for bearing and distance. We also found stump holes that check bearings and distances for orig. BTs, SW and SE. Set an 1 inch x 36 inch iron pipe with brass cap at corner point, mkd. County Surveyor's Office, T26S, R5W, $\frac{11}{14}$ | $\frac{12}{13}$ 1954.

Blazed and scribed:

14 inch R. Fir, N.35°W., 75.0 feet, mkd. T26S, R5W, S11 CS BT.

8 inch W. Oak, N.37°E., 38.8 feet, mkd. T26S, R5W, S12 CS BT.

8 inch W. Oak, S.85°E., 9.8 feet, mkd. T26S, R5W., S13 CS BT.

10 inch W. Oak, S.86°W., 15.3 feet, mkd. T26S, R5W, S14 CS BT.

34

Witness corner for Meander corner on west bank of North Umpqua River, between secs. 11 and 14.

We found both original BTs and used record distances to fix position of Meander corner.

The Northwest BT is down and rotten - we cut out old blaze and found old scribing in fair condition. The Southwest BT is a standing snag. We cut out old blaze and found scribing in good condition.

Set a 1 inch iron pipe with brass cap for Witness corner 100 feet west of Meander corner and mkd. W.C. 100' W. M.C. $\frac{11}{14}$ T26S, R5W, County Surveyor's Office, 1954.

Blazed and scribed:

14 inch W. O., N.0°56'30"E., 30.0 feet mkd. W. C. S14 CS BT.

14 inch W. O., S.65°46'30"W., 14.3 feet mkd. W. C. S14 CS BT.

35

$\frac{1}{4}$ corner and Meander corner to secs. 11 and 14 on East bank of North Umpqua River.

BTs of original survey not found. Point for corner located by proportional distance between Meander corner and the Northeast corner of Section 14.

Set an iron pipe with brass cap at corner mkd. County Surveyor's Office, $\frac{1}{4}$ corner M. C. 1954, Sec. 11

Blazed and scribed: Sec. 14.

30 inch B. O., N.7°43'W., 201.0 feet mkd. $\frac{1}{4}$ S11 MC CS BT.

14 inch B. O., S.43°10'W., 67.5 feet mkd. $\frac{1}{4}$ S14 MC CS BT.

11 inch W. O., S.79°15'E., 332.3 feet mkd. $\frac{1}{4}$ S14 MC CS BT.

36

Northeast corner of the Ardin A. Tyrell DLC No. 39.

We can find no evidence of original corner. Neither original BT. Found.

Point for corner located by proportional measurement on a true line between Meander corner and Northeast corner of section 14.

Set a 1 inch x 30 inch iron pipe with brass cap at corner point mkd.

County Surveyor's Office, N. E. corner DLC 39 | T26S
R5W | 1954 .

Blazed and scribed:

13 inch W. O., S.23°33'W., 83.5 feet mkd. N. E. corner Cl 39 CS BT.

7 inch B. O., S.89°40'W., 14.4 feet mkd. N. E. corner Cl 39 CS BT.

*Fd OK BY: DE Groot
10/85 KRIS M99-55*

37

Northeast Exterior L corner of the Ardin A. Tyrell DLC No. 39.

We find no evidence of old corner. Point for corner located by

proportional measurement. Set I.P. with brass cap mkd. Cl 39 N.E. Ext. L

Blazed and scribed: cor T26S R5W, County Surveyor's Office, 1954.

14 inch W. O., S.1°35'W., 31.7 feet mkd. N. E. Ex L Cl 39 CS BT.

18 inch Pear, S.32°15'W., 339.9 feet mkd. N. E. Ex L Cl 39 CS BT.

38

Northeast interior L corner of the Ardin A. Tyrell DLC No. 39.

Found no evidence of old corner. Corner set by proportional measurement.

Set and iron pipe with brass cap mkd. Cl 39 N.E. Int. L cor.
T26S R5W

Blazed and scribed: County Surveyor's Office 1954

14 inch W. O., S.26°18'E., 747.7 feet mkd. N.E. Int. L Cl 39 CS BT.

6 inch W. O., S.87°48'E., 713.3 feet mkd. Int. L Cl 39 CS BT.

James W. Byron, Deputy County Surveyor
September, 1954.
C. S. File No. 46/74.