

Douglas County Surveyor's Record of
Government Corners Renewed

26 T. S. 5 R. W. W. M.

KORE-CHAPMAN CO., EUGENE, ORE., 21881

James W. Byron, Deputy County Surveyor
Milo Godfrey
S. A. Billow
December 1958
C. S. File No. 49/128

45
Meander Corner to Sections 14 & 23, Left Bank.
Found - Orig. 10", now 18" Oak, down S.41°W. 60.1 ft. I open
& find good scribing "BT".
No Trace of Orig. N.E. BT.
Set Brass Cap in Concrete at MC Mkd: $\frac{S14}{S23}$ MC T26S R5W County
Surveyor's Office, 1958
New BT's; 12" W. Oak bears N.34°W. 69.2 ft. scribed MC S14 CS BT.
9" W. Oak bears S.79°W.103.5 ft. scribed MC S23 CS BT.
See Sketch in file for exact location of MC. in relation to the
Section Corners.

46
Section Corner to Sections 14, 15, 22, & 23.
Found - 3 Orig. BT's.:
Orig. 14", now 24" W. Oak N.78½°E. 442.2 ft., I open & find
good scribing "S".
Orig. 15", now 40" B. Oak N.83½°W. 280.5 ft., I do not open.
Orig. 11", now 20" W. Oak S.48¼°E 311.5 ft., I open & find
good scribing "S23".
Orig. S.W. BT. not found.
I locate position of Sec. Cor. by distance intersected bearings are
about 2° in error.
Set Brass Cap at Corner Mkd: $\frac{S15}{S22} | \frac{S14}{S23}$ T26S R5W County Surveyor's
Office, 1958
New BT's: 13" W. Oak bears S.27°E. 167.0 ft. scribed S23 T26S R5W CS BT.
12" W. Oak bears N.77°E. 373.4 ft. scribed S14 T26S R5W CS BT.
20" W. Oak bears N.80°W. 158.3 ft. scribed S15 T26S R5W CS BT.
No trees near to S.W.

47
Meander Corner Right Bank Sections 10 & 11.
Found - Orig. 10", now 24" W. Oak N.25½°W. 136.6 ft., I open & find
good scribing "BT S10".
Orig. 13", now 29" W. Oak N.16°E. 192.1 ft. Shows good scar,
I do not open.
Note - Corner in River, Set Witness Corner.
Set Brass Cap at Wit. Cor. Mkd: Wit. Cor. 185 ft. South to M.C. S10/S11,
T.26S. R.5W. County Surveyor's Office, 1958.
New BT's: 29" W.Oak (Orig. N.E. BT. for M.C.) East 53.5 ft. scribed
WC MC S11 CS BT.
7" W. Oak bears S.62°W. 3.8 ft. scribed WC MC S10 CS BT.

48
¼ Section Corner to Sections 10 & 11.
Found - Orig. 20", now 48" B. Oak N. 1°W. 456.1 ft., I open & find good
scribing "BT".
No trace of Orig. N.E. BT.
Set Brass Cap at Corner Mkd: ¼ S10/S11 T26S R5W County Surveyor's
Office, 1958
New BT's: 6" W.Oak bears N.74°W. 24.4 ft. scribed ¼ S10 CS BT.
13" B.Oak bears S. 8°E. 33.2 ft. scribed ¼ S11 CS BT.

49
Section Corner to Sections 13, 14, 23, & 24.
Found - 3 Orig. BT's: Orig. 8", now 20" B.O. N.4½°W. 423.7 ft., I
open & find good scribing "S".
Orig. 12", now 20" B.Oak, down & partly rotted, N.15½°E. 349.1 ft.
I believe this BT. slid down hill about 20 ft., I find good
scribing in rotted section.
Orig. 14", now 40" B.O. S.47°W. 227.0 ft., shows scar, I do not
open. I find base of burned Oak Stump that checks record for
Orig. S.E. BT.
Set Brass Cap at Corner Mkd: $\frac{S14}{S23} | \frac{S13}{S24}$ T26S R5W County Surveyor's
Office, 1958
New BT's: 11" B.Oak bears S.67°W. 73.3 ft. scribed S23 T26S R5W CS BT.
15" B.Oak bears N. 9°W.148.0 ft. scribed S14 T26S R5W CS BT.
8" B.Oak bears N.23°E. 91.8 ft. scribed S13 T26S R5W CS BT.
7" B.Oak bears S.13°E.151.0 ft. scribed S24 CS BT.