

Douglas County Surveyor's Record of
Government Corners Renewed

26 T. S. 5 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

50

$\frac{1}{4}$ Section Corner to Sec. 13, T26S R5W, & Sec. 18, T26S R4W.
Found - Orig. 12", now 42" B.Oak N. 7° 48'W. 211.2 ft. I open &
find good scribing " $\frac{1}{4}$ S".
Set Brass Cap at Corner Mkd: $\frac{1}{4}$ S13/S18 T26S County Surveyor's
R5W R4W Office, 1958
New BT's: 12" W.Oak bears S.81°40'W.(True) 91.5 ft. scribed $\frac{1}{4}$ S13CSBT.
9" W.Oak bears N.23°E.(True) 104.5 ft. scribed $\frac{1}{4}$ S18CS BT.

Section Corner to Sec. 13 & 24, T26S R5W, & Sec. 18 & 19, T26S R4W.
Set by single proportion between $\frac{1}{4}$ Corner 13/18 & Meander
Corner on South Bank of River.

Set Brass Cap at Corner Mkd: $\frac{1}{4}$ S13 | S18 T26S County Surveyor's
R5W S24 | S19 R4W Office, 1958
from which:
10" W.Oak bears S.42°53'W. 296.0 ft. scribed S24 T26S R5W CS BT.
13" E.Oak bears N.11°52'E. 373.3 ft. scribed S18 T26S R4W CS BT.

52

$\frac{1}{4}$ Section Corner to Sections 23 & 24.
Found - Both Orig. BT's.
Orig. 12", now 18" W. Oak S.40°E. 6.6 ft., I open & find
good scribing " $\frac{1}{4}$ S".
Orig. 14", now 24" W. Oak S.65°W. 12.5 ft., shows scar.
I do not open.
Note - Corner is in Ravine. I set Witness Corner 10 ft. North of
True $\frac{1}{4}$ Section Corner.
Set Brass Cap at Witness Corner Mkd: Wit. Corn. 10 ft. South to
 $\frac{1}{4}$ S23/S24 T26S R5W County Surveyor's Office, 1958.
New BT's: 7" W.Oak bears N.60°E. 38.8 ft. scribed $\frac{1}{4}$ S24 W.C. CS BT.
24" W.Oak which is also Orig. S.W. BT. for $\frac{1}{4}$ Cor, S.36°W.,
19.8 ft. scribed WC $\frac{1}{4}$ S23 CS BT.

53

Section Corner to Sections 8, 9, 16, & 17.
Found - All Original BT's:
Orig. 30", now 48", Laurel, center burned out, N.32 $\frac{1}{2}$ °W. 48.8 ft.
Orig. 10", now 18" W.O. S.27°W. 45.5 ft., I open & find
good scribing "T26S16".
Orig. 10", now 18" W.Oak record N.49 $\frac{1}{2}$ °E., should be
78.5 ft. I open & find good scribing.
Orig. 6", now 16" B. Oak S.36 $\frac{1}{4}$ °E. 42.2 ft., shows good old
scar. I do not open.
Set Brass Cap at Corner Mkd: $\frac{1}{4}$ S 8 | S 9 T26S R5W County Surveyor's
S17 | S16 Office, 1958.
New BT's: 22" Cedar bears S.67°E. 23.0 ft. scribed S16 T26S R5W CS BT.
12" R.Fir bears N.29°E. 45.0 ft. scribed S 9 T26S R5W CS BT.
24" Forked Laurel bears S.56°W. 11.7 ft. scribed S17
T26S R5W CS BT.
12" Cedar bears N. 9°W. 54.5 ft. scribed S 8 T26S R5W CS BT.

54

$\frac{1}{4}$ Section Corner to Sections 16 & 17.
Find Orig. 10", now 20" W. Oak N.10 $\frac{1}{2}$ °W. 194.0 ft., I open & find
good scribing " $\frac{1}{4}$ S".
Shell of 30" Oak Stump that checks bearing & distance for
N.E. BT., no scribing found.
Set Brass Cap at Corner Mkd: $\frac{1}{4}$ S17/S16 T26S R5W County Surveyor's
Office, 1958
New BT's: 12" W.Oak bears S. 7°E. 59.9 ft. scribed $\frac{1}{4}$ S16 CS BT.
12" W.Oak bears N.74°W. 67.6 ft. scribed $\frac{1}{4}$ S17 CS BT.
Note - North South Fence 9 ft. West.

55

$\frac{1}{4}$ Section Corner to Sections 8 & 17.
Found - Both Orig. BT's.: Orig. 18", now 28" B.Oak S.55°W. 207.2 ft.,
I open & find good scribing. Orig. 10", now 30" B.Oak,
N.39°E., I find to be N.48°E. 59.4 ft., shows good scar. I
do not open.
Set Brass Cap at Corner Mkd: County Surveyor's Office, 1958, $\frac{1}{4}$ S 8
T26S R5W. S17

James W. Byron, Deputy
Milo Godfrey
S. A. Bilow
December 1958
C.S. File No. 49/128