

Douglas County Surveyor's Record of
Government Corners Renewed

26 T. S. 5 R. W. W. M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21881

continued -

Set Brass Cap at Corner Mkd: County Surveyor's Office, 1960

R5W	S24	S19	T26S
	S25	S30	

New BT's: 10" B.Oak bears S.32°W. scribed S25 T26S R4W CS BT. 119.2 FT. (A.G.)
 11" B.Oak bears N.72°E. 61.1 ft. scribed S19 T26S R4W CS BT
 11" B.Oak bears N. 8°W. 18.1 ft. Scribed S24 T26S R5W CS BT.
 6" Oak bears S. 7°E. 80.5 ft. scribed S30 CS BT.

Approximately 1901
Recorded in Vol. 2, Page 266.

Section Township Corner T26S 62

R5W	S36	S31	R4W
	S1	S6	

RENEWED, SEE CORNER NO. 84

Marked R. Fir Tree 15" diam. for Corner, from which:
 R. Fir 16" bears N.87°30'W. 33½ lks. dist.
 R. Fir 10" bears S.30°00'E. 47 lks. (old BT. in evidence)
 B.Oak 12" bears N.77°30'E. 82 lks.
 R. Fir 14" bears S.63°00'W. 33 lks.

¼ Cor. W. Side of Section 31, T. 26S. R. 4W. Set Pitch Post 6" sq. for ¼ Corner. Note - both Old Bearing Trees standing. **RE-RENEWED, SEE CORNER NO. 63 #148**

Sec. Cor. to Secs. 7 & 18, T26-5W and Secs. 12 & 13, T26-6W. Note - This corner is on new 99 highway pavement. It was originally a three way fence corner but has been used for many years as section corner. Was used & referenced out by State Hwy Dept. before grade was built. See C. S. File No. 49/152 to see sketch as to how referenced & Points found.

Set Brass Cap at Wit. Cor. for Sec. Corner Mkd: Wit. Corner 120 ft. West to

S12	S7	T26S
S13	S18	County Surveyor's Office, 1959

No Trees Near.

64
FDX-2/86
CARL SCHAFER
M 100-70
James W. Byron, Deputy County Surveyor
Done for McKay
Hilo Godfrey
S. Bilow
May 5, 1959
C. S. File No. 49/152

¼ Section Corner to Sec. 7, T26-5W and Sec. 12, T26-6W. Found - 2" I. Pipe at Corner and both BT's. as renewed by B. B. I.: REN #9
 14", now 16" R. Fir S.42°W. 55.4 ft., shows good scar. I do not open.
 10", now 12" Stump Fir, shows good scribing N.31½°E., record 23.8 ft. I find to be 47.0 ft.
 New BT's: 5" R.Fir bears N.32°E. 29.0 ft. scribed ¼ S 7 CS BT.

N. W. Cor. DLC #48 & N. E. Cor. DLC #46. Found - 5/8" I. Bolt at corner & both BT's. as recorded by Frear 1919. REN #2
 24", now down Oak S.54°W. 45.0 ft., shows good scribing "46 CS".
 12", now 18" B.O. Snag S.17½°E. 72.7 ft., center rotted, no scribing found.
 Also find, now 12" Laurel, shows good scribing RP 24 bears S.32°W. 25.0 ft. (not of record)
 I Set ¾" I. Rod alongside I. Bolt and Scribe New BT's:
 12" B. Oak bears N.77°W. 11.8 ft. scribed NE CL 46 CS BT.
 8" W. Oak bears S.63°W. 22.6 ft. scribed NE CL 46 CS BT.

Township Corner -

R6W	S36	S31	R5W
	S1	S6	

Set from stump, scribe visible, in S.E. & Stump Hole in S.W. Set - 1" x 48" pipe 42" in ground with pile of Rock 20" square base, 12" high, from which:
 10" White Oak bears S.55°W. 27.8 ft. Mkd: T27S R6W S1 CS BT.
 6" W.Oak bears S.14°E. 15 ft. mkd: T27S R5W S6 CS BT.
 6" W.Oak bears N.73°E. 48 ft. Mkd: T26S R5W S31 CS BT.
 10" W.Oak bears N.50°W. 74.1 ft. Mkd: T26S R6W S36 CS BT.

66-A
FDX-05 HD 6-2
1951
Ben B. Irving
1934
Wit: N.E. Richardson
E. Brown.