

Douglas County Surveyor's Record of
Government Corners Renewed

26 T. S. 5 R. W. W. M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21881

Milo E. Godfrey, Dep. Co. Surv.
Wm. Stoffel & Mike Stone
November & December, 1963
C. S. File: 49/125

79

$\frac{1}{4}$ Section corner to Sections 20 & 29

Found: $1\frac{1}{4}$ " iron pipe set at corner by Richardson, 1946. See renewal No. 73.
The Fir tree N. 83° E. 18.3 feet. Is now a stump-old face burned.
The 10" fir S. $42\frac{1}{2}^\circ$ W. 23.4 feet. Is now a dead snag-very plain
axe scars.
The 8" laurel N. $60\frac{1}{2}^\circ$ W. 19.2 feet. Is still alive & standing. Good
scar visible where it was opened in 1946-face probably rotted.
(Fleser's tree) ~~RENEWED, SEE CORNER NO. #161~~
New BTS: $1\frac{1}{4}$ " Douglas fir N. $64\frac{1}{2}^\circ$ W. 17.4 feet, scribed $\frac{1}{4}$ S 20 CSEB.
" Douglas fir S. $41\frac{1}{2}^\circ$ E. 21.8 feet, scribed $\frac{1}{4}$ S 29 CS BT.
Note: Corner is approximately 6 inches West of N & S fence line.

80

Section Corner to Sections 29, 30, 31 & 32

Found: White Oak (now 16" in diameter) S. 19° W. 28.4 feet.-chopped open
and found good scribing "S 31"-this tree had been opened approximately
50 years ago and rehealed over old face.
White oak (now 13" in diameter) N. 9° E. 28.4 feet-this tree had
also been opened approximately 50 years ago-did not reopen.
White oak (now 18" in diameter) N. 25° W. 37.0 feet. (instead of
38.3 feet) faint old scars visible-did not open.
White oak (not black oak) (now 16" in diameter) S. 29° E. 37.6 feet-
shows good scars-possibly opened previously-did not re-open.
Set: Brass cap at corner mkd: County Surveyors - S. $\frac{30}{29}$
Office, 1963 S. $\frac{31}{32}$
New BT's: Although all original BT's are still alive & standing.
12" incense cedar N. 20° W. 8.4 feet, scribed S. 30 CS BT.
8" Douglas fir S. $58\frac{1}{2}^\circ$ W. 53.1 feet, scribed S. 31 CS BT.
9" white oak S. 65° E. 17.7 feet, scribed S. 32 CS BT.
9" white oak N. 55° E 17.0 feet, scribed S. 29 CS BT.

81

$\frac{1}{4}$ Section corner to Sections 29 & 32

Found: Madrone tree (now 9" in diameter) N. 47° W. 6.8 feet-cut open scar
and found fragments of scribe marks at edges of old rotted face.
Fir stump (now 24" in diameter) S. 55° E. 22.2 feet-opened scar &
found bottom edge of face, but no scribing.
Fir stump (now 24" in diameter) N. $66\frac{1}{2}^\circ$ E. 25.9 feet-shows good
scar. Did not open. See Renewal No. 13. (These three are Fleser's
trees)
Rotten remnant of oak stump S. 53° E. 19.8 feet-original BT.
No trace found of original N.E. tree.
Set: Brass cap at corner mkd: County Surveyors - $\frac{1}{4}$ S29
Office, 1963 S32
New BT's: 10" madrone N. 59° E. 12.5 feet, scribed $\frac{1}{4}$ S. 29 CS BT.
11" douglas fir S. 75° W. 16.3 feet, scribed $\frac{1}{4}$ S. 32 CS BT.

82

Section Corner to Secs. 20 - 21 - 28 - 29.

Found - 30" Bl.Oak N. 55° E. 100.3 ft., dnd opn., & fd. good scribing "S21".
34" Bl.Oak S. $38\frac{1}{2}^\circ$ E. 43.6 ft., shows good scar, did not open.
39" Bl.Oak S. 82° W. 19.1 ft., shows scar, did not open.
Down & badly rotted Oak N. $80\frac{1}{2}^\circ$ W. 88.4 ft., no scribing found.
Set - Brass Cap at Cor. Mkd: County Surveyor's T26S R5W $\frac{S20}{S29}$ | $\frac{S21}{S28}$
Office, 1963 ~~RENEWED, SEE CORNER NO. 136~~
New BT's: 15" D.Fir S. 46° E. 20.0 ft. Mkd: T26S R5W S28 CS BT.
12" D.Fir N. $76\frac{1}{2}^\circ$ E. 36.7 ft. Mkd: T26S R5W S21 CS BT.
22" D.Fir N. 16° W. 10.4 ft. Mkd: T26S R5W S20 CS BT.
17" D.Fir S. 30° W. 57.4 ft. Mkd: T26S R5W S29 CS BT.

83

Section Corner to Secs. 28 - 29 - 32 - 33.

Fd. - 22" W.Oak S. $20\frac{1}{2}^\circ$ E. 38.3 ft., cut open & fd. gd. scrng. Tree alive & standing.
17" Down & Dead Bl.Oak S. $32\frac{1}{2}^\circ$ W. 76.6 ft., shows scar. Did not open.
No trace of N. E. or N. W. Trees.
Set - Brass Cap at Cor. Mkd: County Surveyor's T26S R5W $\frac{S29}{S32}$ | $\frac{S28}{S33}$
Office, 1963
New BT's: 8" W.Oak N. 47° W. 16.3 ft. Mkd: T26S R5W S29 CS BT.
9" W.Oak N. 39° E. 4.8 ft. Mkd: T26S R5W S28 CS BT.
8" W.Oak S. 38° E. 10.9 ft. " T26S R5W S33 CS BT.
10" W.Oak S. 40° W. 32.7 ft. " T26S R5W S32 CS BT.