

Douglas County Surveyor's Record of
Government Corners Renewed

T. 26 S. T. S. R. 5 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Township Corner T26S R5W

S 36	S 31
S 1	S 6

 R4W (See Ren. No. 62) 84

Found - Corner Tree, 24" D. Fir in fence corner. Fences E.-W. & N.W.
1 1/8" Steel Axle N. 55° E. 3 ft. from Corner Tree.
30" Fir Stump N. 87 1/2° W. 22.1 ft., opened & fd. good scribing.
28" Fir Stump S. 62° W. 21.8 ft., shows good scar.
26" Fir Stump S. 30° E. 21.0 ft., shows good scar.
No trace found of N. E. Bearing Tree.
New BT's: 11" D. Fir N. 83° E. 28.8 ft. Mkd: T26S R4W S31 CS BT.
9" D. Fir N. 16° W. 41.3 ft. Mkd: T26S R5W S36 CS BT.
4" Madrone S. 36° E. 51.4 ft. Mkd: S6 CS BT.
No trees available S. W. of Corner.

Milo E. Godfrey & Crew
Jan. 3, 1964
C. S. File
No. 53/33

1/2 Corner to Sections 11 and 14. (Also M. C. (Rt. Bank)) 85
Found - Brass Cap set in 1954, in place, but bent over. Ren. #35.
11" W. Oak S. 79 1/2° E. 332.3 ft., alive & in good cond., scars plain.
30" Bl. Oak N. 7 3/4° W. 201.0 ft., still standing, but most of S. face & blazes burned away, some scribing still visible on edge of scars.
Burned remains of Oak Stump S. 43° W. 67.5 ft.
Drove Steel Fence Post alongside Brass Cap.
New BT's: 17" Bl. Oak S. 27 1/2° W. 106.2 ft. Mkd: 1/4 S14 CS BT.
34" Bl. Oak N. 10° W. 219.0 ft. Mkd: 1/4 S11 CS BT.
Note - Corner is in cultivated field approx. 50 ft. E. of River Bank.

FD. 2/85
G. BAUGHMAN
M 98-28

1/2 Corner to Secs. 16 and 15. 86
Found - Rotten Oak Stump S. 55° W. 193.4 ft., burl wood showing reverse of old axe marks faces corner. Scar is right size, right shape, & right position for old BT. blaze. I believe it to be overgrowth of old BT. blaze. No scribing visible.
Stump hole & rotten limbs of Oak on ground fit approx. location of S. E. BT.
Corner location also fits gov't. field notes for call at foot of hill.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1964
T26S R5W 1/4 S16/S15 Build Rock Mound
New BT's: 18" Bl. Oak S. 6° E. 51.8 ft. Mkd: 1/4 S15 CS BT.
14" W. Oak S. 65° E. 111.4 ft. Mkd: 1/4 S15 CS BT.
No trees convenient west of line.

Milo E. Godfrey, Deputy
Mm. Stoffel and Mike Stone
January 1964
C. S. File No. 49/125

Section Corner to Secs. 9 - 10 - 15 - 16. 87
Found - 8" W. Oak, now 12", N. 46° W. 39.5 ft., opened & fd. scribing. #152
12" W. Oak, now 14", S. 48° E. 89.0 ft., scribing visible "T" in not completely healed scar.
Orig. BT., White Oak, now 24", N. 88° E. 31.0 ft. is still standing.
24" white Oak S. 63 1/2° W. 14.8 ft., uprooted & dead, no other BT's. found.
Did not find Axle, set in 1951. See Ren. No. 20.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1964
T26S R5W

S 9	S 10
S 16	S 15

New BT's: 4" White Oak North 32.3 ft. Mkd: S10 CS BT.
8" White Oak S. 33° W. 35.0 ft. Mkd: T26S R5W S16 CS BT.
Note - Corner lies approx. 90 ft. S. E. of centerline Wilbur-Glide Road.

RE-RENEWED

Section Corner to Sections 15 - 16 - 21 - 22. 88
Found - White Oak, 24", N. 59° E. 128.0 ft., cut open & fd. good rev. scrbing, "T".
32" Bl. Oak S. 49 1/2° E. 134.6 ft., shows scars. Did not open.
Rotted Remnants of Oak S. 1 1/2° W. 410 ft. All reverse scribing visible on overgrowth of old scar.
No trace found of N. W. BT.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1964
T26S R5W

S16	S15
S21	S22

New BT's: 12" W. Oak N. 11 1/2° W. 77.5 ft. Mkd: T26S R5W S16 CS BT.
9" W. Oak N. 5° E. 55.5 ft. Mkd: T26S R5W S15 CS BT.
9" W. Oak S. 44° E. 98.7 ft. Mkd: T26S R5W S22 CS BT.
No trees near to S. W.