

Douglas County Surveyor's Record of  
Government Corners Renewed

26 T. S. 5 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

143

This Corner set from resurvey of township line for T26-5 & T25-5.  
Section corner for Secs. 6 & 5 T26-5 and Secs. 31 & 32 T25-5.

Set - Brass Cap at Sec. cor. mkd: County Surveyors T 25 S R 5 W  
(Steel fence post alongside) Office S 31 | S 32  
1972 S 6 | S 5  
T 26 S

New BT's: 30" W. Oak, N.36°E., 78.6 ft. scribed T25S R5W S32 CS BT.  
13" W. Oak, N.33½°W., 97.0 ft. scribed T25S R5W S31 CS B.  
13" W. Oak, S.30°E., 117.7 ft. scribed T26S R5W S5 CS BT.  
12" Ash, S.83°W., 133.7 ft. scribed T26S R5W S6 CS BT.

This corner lies between 2 creeks, east 300.0 ft. west 130.0 ft.  
- - - - - 1/21/72

This corner set from resurvey of township line for T26-5 and T25-5/  
¼ Corner for Sec. 31 T25-5 and Sec. 6 T26-5.

Set - Brass cap at ¼ Cor. mkd: County Surveyor's T 25 S R 5 W  
(Steel fence post alongside) Office ¼ S 31  
1972 S 6  
T 26 S

Bearing Objects - 5/8" I. Rod, S.43°W., 17.0 ft.  
5/8" I. Rod, S.31°E., 14.4 ft.  
SE I. Rod set at fence cor. Fences running E-W-S.

This corner lies 12.0 ft. north of east-west fence line.  
- - - - - 1/21/72

Southeast Corner D.L.C. #41

Found: 10" W. Oak, N.25°W., 69.9 ft. Alive shows good  
scar. Tagged. Ren. No. 116  
New road const. has removed other BT and I. Pipe  
at corner.

Set: 5/8" I. Rod in Center line of Road and set 5/8"  
I. Rod S.10°W., 29.1 ft. in fence line on  
R/W for reference monument.

3/16/72

144

Francis L. Ingram, Deputy Surveyor  
John M. Powell  
January, 1972  
C. S. File 56/10 1144 - 48

V. R. Tracy  
L. Monrean  
March, 1972  
C.S. File  
49/125

Fd.B.C.  
1188  
D. BENTZ  
1106-4

3/77

JAN 1973

Sec. Corner for Secs. 35 and 36; and 1 and 2 of T27-5.

Found - A 1" I.P. with a 1964 Doug. Co. Surveyors brass cap attached  
mkd. as described in Ren. #114 extending 12" above ground with  
¾" I. Rod alongside.

An orig. 20" now 52" B. Oak, alive and prev opened, no markings  
visible, bears S.82°W., 70.0 ft. (Rec. S.83 1/2°W., 71.9 ft.)

An orig. 12" now 34" B. Oak, alive with faint scar visible,  
bears N.65°W., 50.4 ft. (Rec. N.62°W., 48.8 ft.).

An orig. 10" now 31" B. Oak, alive with good scar visible,  
bears N.7 1/2°W., 102.9 ft. (Rec. N.7 1/2°W., 103.6 ft.) and  
(Rec. per Ren. #114, N.8°W., 102.1 ft.)

A 12" now 12" B. Oak, alive with healed single blaze bears  
N. 14 1/2°E., 10.3 ft. (Rec. N.11°E. 10.3 ft.)

A 10" now 13" B. Oak bears S.81 1/2°E., 21.1 ft. alive with  
healed double blaze. (Rec. S.84°E., 21.6 ft.)

The SW BT is gone.

Condition report only, no monument set, no new accessories.

A corner of fences running N & E bears South 19.5 ft.

6/9/77

145

Gary L. Langlitz  
Karen Cheney  
Doug. Co. Surveyor  
Office  
June 9, 1977  
C.S. 59/34

Section Corner, Sec. 31; and Sec. 6 of T27-5; Sec. 36, T26-6; Sec. 1, T27-6.

Found - A 1" O.D. Iron pipe firmly set in a mound of stone. Ren. #66-A

We find depressions in the ground and fragments of Oak roots at the  
approx. record positions of the orig. NE, SE, and NW bearing trees.  
There is no identifiable evidence at these positions.

A 10" now 13" Fork of a W. Oak, alive with well-healed double blazes  
bears S.63°W., 27.8 ft. (Measured to center of root crown at  
ground level) Ren. #66-A (Rec. S.55°W., 27.8 ft.)

A 6" now 10" W. Oak, alive with well-healed double blaze bears  
S.14°E., 15.4 ft. (Rec. S.14°E., 15 ft.)

A 6" now 9" W. Oak, alive with well healed double blaze bears  
N.70°E., 48.0 ft. (Rec. N.73°E., 48 ft.) Ren. #66-A

A 10" now 17" W. Oak, alive with well healed double blaze  
bears N.48°W., 73.3 ft. (Rec. N.50°W., 74.1 ft.)

Gary L. Langlitz  
S.J. Flaese; F.C. Silagy  
Doug. Co. Surveyors Office  
April 24, 1978  
C.S. 59/46