

Douglas County Surveyor's Record of
Government Corners Renewed

T 26

T. S.

R 5

R. W. W. M.

MOKE-CHAPMAN CO., EUGENE, ORE. 21881

162

C O N T - - - -

Narrative:

Field ties were made to monuments (shown as accessories) from the iron rod marked "A" backsighting the iron rod marked #1. When comparing measured bearings to inversed map bearings a consistent difference was noted (except to Accessory #4). The bearing difference was averaged to be 0° 19'03" and was applied to the right to all measured bearings. The corner location was determined at record bearing and distance (M57-73) from the iron rod marked "A". Except for the accessory monuments marked #1 & #2 (which apparently are out of position) and the monuments to the building corner (#4) the bearings & distances to the accessory monuments compare well to inverses computed from map information.

Douglas County
Surveyors Office
Larry E. Monrean
Deputy
April 26, 1991
C.S. 64/13

4/26/91

163